Chapter 11 Quality Control for Protective Coating Projects

Thomas A. Jones

Scope

The purpose of this chapter is to provide an overview for individuals involved in quality control inspection for protective coating projects. Many times inspection is considered the primary quality control activity, when in fact inspection is only one part of the quality control process. Equally important are the activities of document control, calibration verification, and identifying nonconformances and recommending corrective actions. This chapter concentrates on quality control performed by individual inspectors on the project level and not an overall quality program.

Terminology

- Quality control (QC) is gathering and documenting information that verifies that the work performed meets or exceeds some minimum standard as required by project specifications.¹
- Quality assurance (QA) is defined as the process to verify that the quality of the work performed is actually what is claimed on the basis of the quality control performed. Quality control is not synonymous with quality assurance. Quality assurance is meant to protect against failures of quality control.¹
- The quality program or quality system establishes and controls the level of QA and QC that may be required to show conformance to a specification or industry accepted standard.
- The Quality Control Manual is the governing document of written procedures used to implement the quality program.
- The QC manager or supervisor is the qualified person designated by upper management with the full support and authority to oversee the quality program. The overall quality program is maintained and evaluated on an annual basis by the QC manager who is responsible for issuing corrective actions and implementing revisions to the quality program.²
- The QA or QC inspector is the qualified person designated by the QC manager to perform individual inspections and verify that work is being performed

according to the predetermined criteria. The QC inspector should have the authority and support of upper management to identify nonconformance, recommend corrective actions, and stop work if required.²

Standards and Guidelines

In addition to this volume, the following SSPC publications provide standards, procedures, and guidelines to better understand the quality control process:

- SSPC-QP 1. Standard Procedure for Evaluating Painting Contractors (Field Application to Complex Industrial Structures)
- SSPC-QP 3. Standard Procedure for Evaluating Qualifications of Shop Painting Applicators
- SSPC-QP 5. Standard Procedure for Evaluating Qualifications of Coating and Lining Inspection Companies
- The Inspection of Coatings and Linings

Pre-Job Review

Contract and Specification Review

Prior to beginning any job the specification and all supporting documents should be reviewed by the designated individuals responsible for overseeing the job. Written acknowledgement of the specification, revisions, supporting documents, and correspondence should be provided. Ambiguous specifications and uncertainties and differences of opinion should be documented in writing and maintained in the job file. The quality control section of the specification may require verification of conformance of certain requirements prior to starting the job.

Quality Control and Inspector Requirements

All persons designated as inspectors may be required to have sufficient documentation or records available for:

- Formalized training or certification of the inspector
- Experience in the type of structure to be inspected

- Inspection equipment required by the job specification available to the inspector
- Records of calibration for all inspection equipment used by the inspector
- Standards and procedures required to show conformance to job specifications are available to the inspector
- Approved copies of material supplier technical data sheets, application instructions, and Material Safety Data Sheets (MSDSs)

Inspection Plan

A written inspection plan to show conformance to the specification may be required. The inspection plan should list inspection hold or work-stoppage points that conform to the individual specification requirements or industry standards and procedures. The following listed inspection hold points are considered basic for most work.³ Additional inspection hold points may be added if necessary:

- · Prior to the start of work
- Immediately following surface preparation
- Immediately prior to the coating or lining application
- · Following the application of each coat
- Following the curing of the coating or lining
- Final inspection and sign off, in accordance with job specifications

Document Control

The inspector should have sufficient inspection forms and records to show verification to the specification. Specific items required for documentation may vary depending on the job specification. Some specifications require the use of specified forms or approved standard forms. The frequency of recording and reporting all documented information should be determined and understood by the inspector prior to beginning the inspection assignment. Forms should have their own unique numbering system along with a filling system for efficient control. Several examples of different types of reporting forms may be found at the end of this chapter.

Pre-Job Conference

The inspector, owner representatives, applicator, and supplier should attend a pre-job conference. At this time, the inspector should identify any missing, incomplete, unclear, or ambiguous statements and communicate this information to the owner's represen-

tative. All uncertainties and differences of interpretation should be resolved and documented in writing. Prior to starting the job, the inspector, applicator, and owner's representative should have a clear understanding of the work requirements. In addition the degree of the inspector's authority to stop work or make any other managerial decisions should be established in writing by the owner and communicated to the applicator. An inspector must be careful to never overstep this degree of authority.⁴

Daily Inspection Activities

Daily inspection activities vary according specification requirements and the level of inspection performed by the inspector. In order to show conformance to specifications the inspector should prepare detailed documentation of work performed by the applicator. Inspection records provide a means of ensuring that deviations from the specification are corrected prior to final acceptance. In the event that more than one inspector inspects the work, the records provide a history of what has transpired and of the current status of the project.

Revision Log

The revision log should document the receipt of all revisions and changes to the specifications and inspection procedures. Issuance of all revised specifications should be documented along with verification that all persons involved in the inspection process and the applicator are properly informed of any changes. The removal of obsolete specifications and procedures should be verified.

Technical Resources Availability

The inspector should have available at the job site all necessary standards, quality control inspection procedures, and technical references required to verify conformance to the job specification. The inspector may be required to have some the following available:

- SSPC Painting Manual Volume 2: Systems and Specifications
- SSPC-PA 2. *Measurement of Dry Coat Thickness with Magnetic Gages*
- SSPC Visual Standards applicable to the specified work
- ASTM Protective Coating Inspection Standards for Field and Shop Applications
- · Updated material supplier technical data sheets and

written recommendations.

 Applicable required copies of SSPC, NACE, ASTM, NAVSEA, AWWA, API, and ISO standards, procedures, and guidelines.

Calibration Verification

Calibration of inspection equipment is usually performed by a qualified individual using industry accepted standards and issuing a certification that the equipment is properly calibrated. The inspector in the field can only verify that the equipment used to perform inspections is calibrated according to industry accepted standards and procedures. The inspector should document the verification of all calibrations according to specifications and procedures. Normally the following information is required to show verification:

- Equipment type and serial number
- Required frequency and calibration method
- · Record of calibration data
- Signature and date of person performing calibration verification

Daily Work Log

A description of the inspector's daily duties should be recorded in the daily work log. Supplemental data that cannot be recorded on standard forms should also be recorded in the daily work log. These should be objective observations, not "intuition" or "guesswork." They should be independent, not reflecting bias for or against the applicator or owner.4

Daily Inspection Report

The inspection daily report is probably the single most important document. The inspector should record observations and measurements on the coating job conditions as required, and note any hold points. This may include the following:

- · Weather and site conditions
- Pre-surface condition and cleanliness
- Surface preparation monitoring
- Post-surface preparation and monitoring of cleanliness and profile
- Pre-application surface cleanliness
- Coating material preparation and application
- Physical film properties or appearance properties
- Dry film thickness measurements according to specifications or industry standard such as SSPC-PA 2, *Measurement of Dry Coat Thickness*

with Magnetic Gages

- Verification of corrective actions prior to final approval
- Drawings, sketches, or photographs indicating where work occurred and to document the cumulative work progress
- Record of instruments used to obtain measurements and calibration verification
- Record of applicator's equipment and workforce

Nonconformance and Corrective Actions

Deviations or nonconformances from specifications and stop-work orders should be documented and corrective actions issued. Corrective actions taken to resolve deviations from specifications and procedures should be approved prior to restarting work. Follow up on the corrective actions should be verified prior to final approval. Any specification issues that were not resolved should be further documented to show nonconformance to the specification.

Photographic Record

Photographs of the coating inspection work taken by the inspector should be documented in such a manner that pictures can be properly identified. When possible the inspector should try to use the time/date stamp available on many cameras. A record showing location, area, and conditions along with corresponding number of the photograph should be noted. Undeveloped film should be properly stored and labeled until the film is developed.

Management Review

In process review should be scheduled and performed by management on an ongoing basis. Inspection documentation and records should be checked for accuracy, identifying problems that may need to be resolved. The review should be recorded and brought to the attention of the person responsible for the problem.

Post Job Activities

Recordkeeping

After completion of the inspection activities, verify that all required entries and supporting notes have been made and are legible. Signatures and dates required in documentation should be verified. Furnish any photographs (with date taken and other

identification on back of photo) and other supplemental documentation. Deliver or retain all documentation as required by contract or specification.

Traceability

Many times inspection records and documentation are required to be properly stored for a set period of time. Completed inspection records and documentation should be filed and organized in a manner that makes them easily accessible.

Summary

Quality control for protective coating projects begins prior to project start-up and continues after project completion. Many times inspection is considered the primary quality control activity. Specification review, documentation issuance, calibration verification, and corrective action follow-up are equally important. Standards and procedures needed to perform proper inspection need to be available and understood by all inspection personnel. A written inspection plan should be developed and followed by the inspector.

Records and support documents required to verify conformance with specifications should be filled out in a consistent and timely matter. Inspection equipment should be properly maintained and calibration verified as required. Deviations or nonconformance from specifications must also be properly documented and all corrective actions verified prior to final approval. All records and documents should be reviewed and organized in a consistent filing system. Proper storage of all records and documents allows for easy access should they be required at a latter date for review.

References

- 1. Glossary. In *The Inspection of Coatings and Linings;* Bernard R. Appleman, ed; SSPC: Pittsburgh,1997; p 429.
- 2. Windler, Frank J. Quality Control: A Necessary Factor in SSPC Contractor Certification. *Journal of Protective Coatings and Linings*, April 1988, pp 32-37.
- 3. Bechtel Power Corp. *Coating and Lining Inspection Manual;* SSPC: Pittsburgh, 1991; Chapter 2.
- 4. Drisko, Richard W. Reviewing and Preparing Inspection Documents. In *The Inspection of Coatings and Linings;* Bernard R. Appleman, ed; SSPC: Pittsburgh, 1997; pp 13-32.

Acknowledgements

The author and SSPC gratefully acknowledge Austin Paint Inspection for providing samples of their quality control and inspection forms and Bruce Rutherford for his peer review of this chapter.

About the Author

Thomas A. Jones

Thomas A. Jones is the senior technical auditor at SSPC, performing audits for the painting contractor certification program (PCCP). He has over 25 years experience in the protective coatings industry working in quality control inspection, project management, and technical service. He is the co-founder of the SSPC South Texas Chapter and is certified as a SSPC protective coatings specialist (PCS), NACE coatings inspector, and a NAVSEA paint inspector. Mr. Jones received his BA degree from Texas A&M-Corpus Christi.

DOCUMENTATION ACKNOWLEDGEMENT

PROJECT:				PROJECT:			OPY			
LOCATION:						OFFICE	ESTIMATING			
				START DATE:		QC MGR Proj Mgr	Inspector			
CONTACT:				FINSH DATE:						
THIS IS	THIS IS TO ACKNOWLEDGE RECEIPT OF ONE OR MORE OF THE FOLLOWING DOCUMENTS									
	SPECIFICATIONS REVISIONS CORRESPONDENCE REPORTS TEST RESULTS DRAWINGS OTHER									
RE	RECEIPT OF ALL DOCUMENTATION IS TO BE RECORDED IN THE PROJECT DOCUMENTATION LOG									
DATE		ENTATION, SPECIF PRINTS & REVISIO			DESCRIPTIO	N & TITLE				
UPDATE A	ALL SPECIF	ICATIONS & PR	OCEDURES A	AND RECOR	D IN APPROPE	RIATE REVI	SION LOGS			
ISSUED	TO:									
	Y:									
COMPA	NY:									
RECEIPT ACKNOWLEDGED BY:										
SIGNATURE REQUIRED DATE										
RETURN THIS FORM WITH SIGNATURE TO:										
		RETORN	THIS FORIVI V	VIIII SIGNA	TORE TO.					

INSPECTION EQUIPMENT CALIBRATION RECORD

PROJECT:			PROJECT:	CO					
LOCATION:				Office	QC Mgr Client				
ISSUED TO:			START DATE:	Proj Mgr	Cilent				
CONTACT:	RETURN	I DATE:	FINSH DATE:	NSH DATE:					
DOC	JMENT AS REQ	UIRED FOR EQU	JIPMENT REQUIRING C	ALIBRATION					
TYPE/MODEL	SERIAL#	DATE OF CALIBRATION	CALIBRATION REQUIREMENTS	VERIFIED	VERIFIED BY				
				+	 				

INSPECTION EG	COPY Office Employee File QC Mgr Proj Mgr Inspector							
PROJECT:		PROJEC	PROJECT #:					
LOCATION:						TACHMENTS		
ISSUED TO: ISS	UED DATE:	START [DATE:		Calibr	ation Record		
ISSUED BY: RET	URN DATE:	FINISH I	FINISH DATE:					
	INSPECTION	EQUIPMEN	NT					
ITEM	MODEL#	SERIAL#	DATE OF CALIBRATION	VE	RIFIED BY	CALIBRATION REQUIREMENTS		
	TEMPERATU	RE/HUMIDITY						
	SURFACE P	REPARATION						
	WET/DRY FIL	M THICKNESS						
	OTHER	TOOLS						
	SPECIFICATION	& STANDA	ARDS					
The following designated inspector has bee to perform the intended inspection as required order. The inspector will document required a inspector will return all equipment to the QC Nor stolen equipment.	l by contract. The inspect alibrations and maintain al	inspection equi or is required to Il records per jol	pment, certification a keep all equipment in b specifications. Upor	n a sat n com	fe place a pletion of	nd in good working the project, the		
ISSUED BY:			ISSUE	D TO	:			
QUALITY CONTROL MANAGER'S SIGNATURE	DATE	IN:	SPECTOR'S SIGNATURE			DATE		

	DATE: M T W R F S SU # Pg of						
DAILY COATING INSPECTION REPORT	PROJECT#:			COPY			
	INSPECTOR:		Office		ent		
PROJECT/CLIENT:	Proj Mgr						
LOCATION:				ACHMEN			
DESCRIPTION:	DFT SHEET NCR/CAR						
REQUIREMENTS:							
CONTRACTOR:	SPEC#:		REVISIO				
DESCRIPTION OF AREAS & WORK PERFORMED	HOLD POIN	IT INSPECT	TIONS PERFO	RMED			
	2. PRE SURFACE PR 3. SURFACE PREPAR 4. POST SURFACE P 5. APPLICATION MOI 6. POST APPLICATIO 7. POST CURE/DRY 8. CORRECTIVE ACT	1. WEATHER AND SITE CONDITIONS 2. PRE SURFACE PREPARATION/CONDITION & CLEANLINESS 3. SURFACE PREPARATION MONITORING 4. POST SURFACE PREPARATION/CLEANLINESS & PROFILE 5. APPLICATION MONITORING/WET FILM THICKNESS (WFT) 6. POST APPLICATION/APPLICATION DEFECTS 7. POST CURE/DRY FILM THICKNESS (DFT) 8. CORRECTIVE ACTIONS FOLLOW UP & FINAL INSPECTION APPROVED BY:					
SURFACE CONDITIONS	A	MBIENT CO	ONDITIONS				
NEW MAINT PRIMER/PAINT AGE/DRY/CURE	AREAS:						
STEEL GALVANIZE CONCRETE	TIME						
HAZARD SAMPLE REPORT # DEGREE OF CONTAMINATION:	DRY BULB TEMP° C/F		0 0	0	0		
TEST: CIµg/cm²/ppm Feppm pHppm	WET BULB TEMP° C/F		0 0	0	0		
DEGREE OF CORROSION:	% RELATIVE HUMIDITY		% %	%	%		
SCALE PITTING/HOLES CREVICES SHARP EDGES	SURF TEMP° C/F MIN/N	MAX /	0 / 0	/ 0	/ °		
WELD MOISTURE OILS PAINTED SURFACE CONDITION:	DEW POINT TEMP° C/F	:	0 0	0	0		
DRY TO/TOUCH HANDLE RECOAT	WIND DIRECTION/SPE	WIND DIRECTION/SPEED					
DRY/OVERSPRAY RUNS/SAGS PINHOLES HOLIDAYS	WEATHER CONDITION	S:					
ABRASION FALL OUT		APPLIC					
SURFACE PREPARATION							
START TIME FINISH TIME AREA ft²/m²							
SOLVENT CLEAN HAND TOOL POWER TOOL	GENERIC TYPE						
HP WASH PSI ABRASIVE BLAST ABRASIVE TYPE SAMPLE	PROD NAME MIX METHOD						
BLAST HOSE SIZE NOZZLE SIZE/PSI							
AIR SUPPLY CFM AIR SUPPLY CLEANLINESS	20125	STRAIN/SCREEN					
WATER/OIL TRAP CHECK EQUIPMENT CONDITION CHECK			IATERIAL TEMP				
CUREAGE OF EASH INFOCA BROCK E MEACUREMENT	KIT SIZE/COND SHELF LIFE	INDUCTION TIME					
SURFACE CLEANLINESS & PROFILE MEASUREMENT	BATCH NUMBER		POT LIFE				
JOB SPEC NACE/SSPC-SP NACE/SSPC SPEC/ VISUAL STDS	(A)		QTY ADDED				
PROFILE CHECK: DISC TAPE GAUGE	- (A) - (B)		% BY VOLUM				
SPECIFIEDmils/µm ACHIEVEDmils/µm	(C)		Specified WFT				
SURFACE EFFECT ON D.F.T. GAUGE/BMR/mils/μm	REDUCER		Acheived WFT		milsµ/m		
MEASUREMENTS	AIRLESS/CONV	BRUSH			PRIMER		
MEAGOTEMENTO	PUMP/POT						
	RATIO/SIZE		TRAP				
	GPM/CFM	HOSE Lng SPRAY G		FILTER			
D.F.T. GAUGE CALIBRATION	PSI	TIP SIZE		AGITATO	DR		
GAUGE GAUGE GAUGE SPECIFIED AVERAGE AVERAGE TOTAL							
TYPE SERIAL CALIB. AVERAGE D.F.T.THIS D.F.T.LAST AVERAGE MODEL # VERIFIED D.F.T. COAT COAT D.F.T.	E						
	INSPECTOR'S S	IGNATURE		DATE			
	· · · · · · · · · · · · · · · · · · ·						

					DATE: MTWRFSSU # Pg of												
D)FT	M	EASU	JREM	ENT V	VORK	SHEE	Т	PROJECT#:					COPY			
									INSPECTOR: QC Mgr Clien					ent			
PROJEC	CT/CI	LIE	NT:											Р	roj Mgr		
LOCATION	:NC													SPE	EC#:		
DESCRI	PTIC	N:												RE\	VISION#	!	
ITEM:									ITEM:								
LOCATIO		SPOT READINGS			LOCATION	A R		S	POT	REA	ADINGS	3					
LOCATIC	"	E	1	2	3	Total	%Min	Avg	LOCATION	E A	1	2	3		Total	%Min	Avg
	-	Â								A				\top			
	\rightarrow	В								В				+			
	-+	-												+			
	\rightarrow	С								С				+			
	-+	D								D				+			
	4	E								Ε				_			
Approx. ft ² /m ²									Approx. ft ² /m ²								
10 /111		Spe	cified DF	Т	mils/ μ m	Total Av	g.	mils/ μ m	10 7111	Spe	cified DF	Т	mils/ μ	μ m Total Avg. r			mils/µm
Reference	ce In	spe	ction Rep	ort#		for a	applicatio	n record	Reference Ir	nspe	ction Rep	oort#			for a	applicatio	n record
ITEM:									ITEM:								
LOCATIO	INC	A R		S	POT RE	ADING	S		LOCATION	A SPOT READINGS							
20071110		E A	1	2	3	Total	%Min	Avg	2007	E A	1	2	3		Total	%Min	Avg
		Α								Α							
		В								В							
		С								С							
		D								D							
		Е								Е							
Approx.			·						Approx.								
ft ² /m ²	5	Spe	cified DF	Т	mils/µm	Total Av		mils/µm	ft ² /m ²	Specified DFT mils/			mils/μ	m T	Total Avg	J.	mils/µm
Reference	e Ins	spec	tion Rep	ort #		for a	applicatio	n record	Reference Ir	nspe	ction Rep	ort #		_	for a	pplication	n record
ITEM:									ITEM:								
LOCATIO		A R		S	POT RE	EADING	S		LOCATION	A SPOT			POT	READINGS			
LOCATIO	N	E	1	2	3	Total	%Min	Avg	LOCATION	E	1	2	3		Total	%Min	Avg
		Α								Α							
		В								В							
		С								С							
		D								D							
		Е								Е							
Approx.					1				Approx.								
ft ² /m ²	- [:	Spe	cified DF	Т	mils/μm	Total Av	g.	mils/μm	ft ² /m ²	Spe	ecified DF	T	mils/μ	m -	Total Avo	g.	mils/µm
Reference Inspection Report # for application record					Reference II	nspe	ction Rep	oort #			for a	applicatio	n record				
		<u> </u>			IBRATIO		• •			,	-,						
GAUGE	GAU		PLATE/	DIAD	ADJUST	SPEC. AVERAGE	D.F.T	D.F.T									
TYPE MODEL	SER #		SHIM mils/µm	BMR	+/-	COAT	THIS COAT	LAST COAT									
										INSPE	ECTOR'S SI	IGNATURE				DATE	

			DATE: M T W R F S SU	# Pg of				
CORRECTIVE	ACTIONS REPO	RT	PROJECT#:	COPY				
			INSPECTOR:	QC Mgr Client				
PROJECT/CLIENT:	Proj Mgr							
LOCATION:				ATTACHMENTS				
DESCRIPTION:				STOP WORK ORDER				
REQUIREMENTS:				† <u> </u>				
CONTRACTOR:			SPEC#:	REVISION#:				
	& LOCATION		NAME/COMPAN					
DESCRIPTION OF	NONCONFORMING ITEM	VI	DESCRIPTION OF NONC	CONFORMANCE				
REFERENCED: SPECIFIC	ATION/PROCEDURE/STA	NDARD	ACTION LEVEL					
	DISCL	JSSION & RE	COMMENDATIONS					
	APPR	ROVAL & COF	RRECTIVE ACTIONS					
CORRECTIVE ACTIONS FOLLOW UP								
EWAL ADDROVAL								
FINAL APPROVAL:								
SIGNATURE	TITLE	DATE	INSPECTOR'S SIGNATURE	DATE				

PHOTOGRAPH RECORD			DATE:	MTWRFSSU	# Pg of	
			PROJECT#:	COPY		
				INSPECTOR:	QC Mgr Client	
PROJEC	CT/CLIENT:					Proj Mgr
LOCATION	ON:					CAMERA:
CAMER.	A TIME/DATE VERIFIED:	YES NO	N/A	PERMISSION REQ:	YES NO	EXPOSURES:
FILM DE	EVELOPER:			#	DATE	ROLL#:
#	LOCATION			AREA	C	OMMENT
1						
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15 16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						
32						
33						
34						
35 36						
	MDED ON FORM MICE	4ATOL: \\	LDIOTUSE			
NU	MBER ON FORM MUST I FILL OUT ONE FOR			INSPECTOR	S SIGNATURE	DATE