DATED 2026

(1) FERNHOLLOW PROPERTIES LIMITED

(2) BRIGHTQUAY STUDIOS LIMITED

(3) GARROW HOLDINGS PLC

AGREEMENT FOR LEASE

relating to Units 4 and 5, Kestrel Wharf, 18 Ferry Lane, Northbridge NB1 2XY

This document is a fictitious sample generated for a software demonstration. It is not legal advice and must not be used as a precedent.

CONTENTS

1. Definitions And Interpretation
2. Conditions
3. The Landlord'S Works
4. Variations
5. Access Before The Handover Date
6. Practical Completion
7. Handover Date And Delay
8. The Tenant'S Works
9. Grant Of The Lease
10. Defects
11. Collateral Warranties
12. Insurance
13. Termination
14. Notices
15. Assignment
16. Vat
17. Disputes
18. Data Protection
19. Confidentiality
20. Anti-Bribery
21. Non-Merger
22. Entire Agreement
23. Joint And Several Liability
24. Third Party Rights
25. Guarantee
26. Counterparts
27. Governing Law And Jurisdiction

Schedule 1 The Landlord's Works

Schedule 2 The Tenant's Works

Schedule 3 Principal terms of the Lease

Schedule 4 Rent and rent-free periods

Schedule 5 Programme

Schedule 6 Schedule of condition

Schedule 7 Form of collateral warranty

THIS AGREEMENT is dated 2026

PARTIES

(1) FERNHOLLOW PROPERTIES LIMITED, incorporated and registered in England and Wales with company number 00000001, whose registered office is at 2 Mill Yard, Northbridge NB1 4AA (the "Landlord").

(2) BRIGHTQUAY STUDIOS LIMITED, incorporated and registered in England and Wales with company number 00000002, whose registered office is at 9 Lantern Row, Eastwick EW2 3BB (the "Tenant").

(3) GARROW HOLDINGS PLC, incorporated and registered in England and Wales with company number 00000003, whose registered office is at 9 Lantern Row, Eastwick EW2 3BB (the "Guarantor").

BACKGROUND

(A) The Landlord is the owner of the freehold interest in the Building.

(B) The Landlord has agreed to carry out the Landlord's Works and to grant, and the Tenant has agreed to accept, the Lease on the terms of this Agreement.

AGREED TERMS

1. DEFINITIONS AND INTERPRETATION

1.1 The definitions in this clause apply in this Agreement.

"Access Date": the date eight weeks before the Target Handover Date, or such other date as the Landlord and the Tenant agree in writing.

"Agreed Form": in the form of the draft annexed to this Agreement and initialled by or on behalf of the parties, with such amendments as the parties agree in writing.

"Building": the building known as Kestrel Wharf, 18 Ferry Lane, Northbridge NB1 2XY.

"Building Contract": the contract to be entered into between the Landlord and the Contractor for the carrying out of the Landlord's Works.

"Certificate of Practical Completion": the certificate issued by the Landlord's Surveyor under clause 6.3.

"Contractor": the building contractor appointed by the Landlord to carry out the Landlord's Works.

"Defects Liability Period": the period of twelve months starting on the Handover Date.

"Handover Date": the date on which the Certificate of Practical Completion is issued or, if later, the date on which the Landlord gives vacant possession of the Property to the Tenant.

"Initial Rent": four hundred and eighty-six thousand five hundred pounds (£486,500) a year, exclusive of VAT.

"Landlord's Surveyor": Ashdown Pike LLP or such other chartered surveyor as the Landlord may appoint from time to time.

"Landlord's Works": the works to the Property described in Schedule 1.

"Lease": the lease of the Property to be granted under this Agreement in the Agreed Form.

"Lease Date": the date on which the Lease is completed under clause 9.

"Longstop Date": 31 March 2028.

"Planning Condition": the condition set out in clause 2.2.

"Planning Longstop Date": 31 December 2026.

"Practical Completion": practical completion of the Landlord's Works as certified under clause 6.

"Property": Units 4 and 5, Kestrel Wharf, 18 Ferry Lane, Northbridge NB1 2XY, shown edged red on the plan annexed to this Agreement.

"Rent Commencement Date": the date nine months after the Lease Date.

"Rent Deposit": the sum of two hundred and forty-three thousand two hundred and fifty pounds (£243,250).

"Snagging Items": minor defects and omissions which do not prevent the Property from being used for its intended purpose.

"Target Handover Date": 30 June 2027.

"Tenant's Surveyor": Linwood Carver Associates or such other chartered surveyor as the Tenant may appoint from time to time.

"Tenant's Works": the works of fitting out the Property for the Permitted Use, described in Schedule 2.

"Term": fifteen years from and including the Lease Date.

"Working Day": any day which is not a Saturday, a Sunday or a bank holiday in England.

1.2 Clause, Schedule and paragraph headings shall not affect the interpretation of this Agreement.

1.3 A reference to a clause or a Schedule is to a clause of, or a Schedule to, this Agreement.

1.4 Unless the context otherwise requires, words in the singular include the plural and words in the plural include the singular.

1.5 A reference to a statute or a statutory provision is a reference to it as amended, extended or re-enacted from time to time.

1.6 A reference to writing or written does not include email, except where expressly stated.

1.7 Any obligation on a party not to do something includes an obligation not to allow that thing to be done.

2. CONDITIONS

2.1 This Agreement, other than this clause 2 and clauses 13 to 27, is conditional on the satisfaction of the Planning Condition on or before the Planning Longstop Date.

2.2 The Planning Condition is the grant of a planning permission for the change of use of the Property to use as offices and production studios, on terms reasonably satisfactory to the Tenant.

2.3 The Landlord shall use all reasonable endeavours to satisfy the Planning Condition as soon as reasonably practicable and shall keep the Tenant informed of the progress of the application.

2.4 If the Planning Condition has not been satisfied by the Planning Longstop Date, either party may terminate this Agreement by giving written notice to the other at any time before the Planning Condition is satisfied.

2.5 The Landlord shall give the Tenant written notice within five Working Days after the Planning Condition is satisfied.

3. THE LANDLORD'S WORKS

3.1 The Landlord shall carry out the Landlord's Works, or procure that they are carried out, in a good and workmanlike manner, with good quality materials, and in accordance with all statutory requirements, the planning permission and the requirements of the insurers of the Building.

3.2 The Landlord shall use all reasonable endeavours to procure that the Landlord's Works start within six weeks after the date on which the Planning Condition is satisfied.

3.3 The Landlord shall use all reasonable endeavours to procure that Practical Completion takes place on or before the Target Handover Date.

3.4 The Landlord shall not use any deleterious materials in the Landlord's Works, and shall procure that the Contractor and every consultant gives a warranty to that effect.

3.5 The Landlord shall keep the Tenant informed of the progress of the Landlord's Works and shall send to the Tenant a copy of each monthly progress report prepared by the Contractor within five Working Days after receiving it.

3.6 The Tenant and the Tenant's Surveyor may inspect the Landlord's Works at reasonable times on giving reasonable prior notice, provided that they comply with the reasonable requirements of the Contractor and do not give any instruction to the Contractor.

4. VARIATIONS

4.1 The Landlord may make variations to the Landlord's Works which are required to comply with statutory requirements, or which are minor and do not materially affect the Tenant's use of the Property, without the consent of the Tenant.

4.2 Any other variation requires the prior written consent of the Tenant, which shall not be unreasonably withheld or delayed.

4.3 The Tenant may request variations to the Landlord's Works. The Landlord shall respond within ten Working Days with an estimate of the cost of the variation and of its effect on the Target Handover Date.

4.4 The Tenant shall pay the reasonable and proper cost of any variation it requests within twenty Working Days after written demand, together with VAT.

5. ACCESS BEFORE THE HANDOVER DATE

5.1 From the Access Date the Tenant may enter the Property to carry out the design and preparation of the Tenant's Works and the installation of its data cabling, subject to the reasonable requirements of the Contractor.

5.2 The Tenant's access under clause 5.1 is at the Tenant's own risk, and the Tenant shall indemnify the Landlord against any loss arising from that access.

5.3 Access under clause 5.1 shall not constitute occupation of the Property and shall not create any tenancy.

5.4 The Tenant shall comply with the health and safety rules of the Contractor while it is on the Property.

6. PRACTICAL COMPLETION

6.1 The Landlord shall give the Tenant at least ten Working Days' notice of the date on which the Landlord's Surveyor intends to inspect the Landlord's Works with a view to certifying Practical Completion.

6.2 The Tenant and the Tenant's Surveyor may attend the inspection and make representations to the Landlord's Surveyor, who shall have proper regard to them.

6.3 The Landlord's Surveyor shall issue the Certificate of Practical Completion when, in the reasonable opinion of the Landlord's Surveyor, the Landlord's Works have been completed except for Snagging Items.

6.4 The Landlord shall send a copy of the Certificate of Practical Completion to the Tenant on the day it is issued, together with a list of the Snagging Items.

6.5 The Landlord shall remedy the Snagging Items within twenty Working Days after the Handover Date, at times agreed with the Tenant so as to cause as little disruption as possible.

6.6 If the Tenant disputes the issue of the Certificate of Practical Completion, the dispute shall be referred to an expert under clause 17, but the Certificate shall remain valid unless and until the expert decides otherwise.

7. HANDOVER DATE AND DELAY

7.1 The Landlord shall give vacant possession of the Property to the Tenant on the Handover Date.

7.2 If the Handover Date has not occurred by the Target Handover Date, the rent-free period under the Lease shall be extended by one day for each day of delay after the Target Handover Date until the Handover Date.

7.3 The extension of the rent-free period under clause 7.2 is the sole remedy of the Tenant for any delay in the Handover Date, except where the delay is caused by the wilful default of the Landlord.

7.4 If the Handover Date has not occurred by the Longstop Date, the Tenant may terminate this Agreement by giving written notice to the Landlord at any time before the Handover Date.

7.5 The Longstop Date shall be extended by one day for each day of delay caused by any event of force majeure, up to a maximum of ninety days.

8. THE TENANT'S WORKS

8.1 The Tenant shall carry out the Tenant's Works in accordance with the plans and specifications approved by the Landlord, which approval shall not be unreasonably withheld or delayed.

8.2 The Tenant shall start the Tenant's Works within eight weeks after the Handover Date and shall use all reasonable endeavours to complete them within twenty-six weeks after the Handover Date.

8.3 The Tenant shall not carry out any works which affect the structure of the Building or its mechanical and electrical systems without the prior written consent of the Landlord.

8.4 On completion of the Tenant's Works, the Tenant shall give the Landlord a copy of the as-built drawings and of the health and safety file.

9. GRANT OF THE LEASE

9.1 The Landlord shall grant and the Tenant shall accept the Lease on the Handover Date, or within five Working Days after it.

9.2 The Lease shall be granted for the Term at the Initial Rent, payable from the Rent Commencement Date, with rent reviews on the fifth and tenth anniversaries of the Lease Date.

9.3 The Tenant may terminate the Lease on the tenth anniversary of the Lease Date by giving the Landlord not less than twelve months' written notice, subject to the conditions set out in the Lease.

9.4 The Guarantor shall execute the Lease as guarantor of the obligations of the Tenant.

9.5 The Tenant shall pay the Rent Deposit to the Landlord on the Lease Date, to be held on the terms of a rent deposit deed in the Agreed Form.

9.6 The Tenant shall pay the stamp duty land tax and registration fees payable on the Lease.

10. DEFECTS

10.1 The Landlord shall remedy, at its own cost, any defects in the Landlord's Works which appear during the Defects Liability Period and which are notified by the Tenant in writing within that period.

10.2 The Landlord shall remedy each notified defect as soon as reasonably practicable, and in the case of an urgent defect affecting the security or the weathertightness of the Property within forty-eight hours.

10.3 The Tenant shall give the Landlord and the Contractor reasonable access to the Property to remedy defects.

10.4 The Landlord shall enforce the obligations of the Contractor under the Building Contract in relation to defects for the benefit of the Tenant.

11. COLLATERAL WARRANTIES

11.1 The Landlord shall procure that the Contractor and each consultant with a design responsibility gives a collateral warranty to the Tenant in the Agreed Form within twenty Working Days after the Handover Date.

11.2 Each collateral warranty shall be capable of assignment twice without consent.

11.3 The Landlord shall procure that each consultant maintains professional indemnity insurance of not less than five million pounds (£5,000,000) for twelve years after Practical Completion.

12. INSURANCE

12.1 The Landlord shall insure the Landlord's Works and all materials on the Property against the insured risks until the Handover Date.

12.2 If the Landlord's Works are damaged by an insured risk before the Handover Date, the Landlord shall reinstate them with all reasonable speed, and the Target Handover Date and

the Longstop Date shall be extended accordingly.

12.3 From the Handover Date, the Property shall be insured in accordance with the Lease.

13. TERMINATION

13.1 Either party may terminate this Agreement by notice to the other if the other party is in material breach of its obligations and has not remedied the breach within twenty Working Days after receiving written notice of it.

13.2 Either party may terminate this Agreement by notice to the other if the other party becomes insolvent.

13.3 Termination of this Agreement shall be without prejudice to any right or remedy of either party in respect of any earlier breach.

13.4 On termination of this Agreement, the Tenant shall remove its property from the Property within ten Working Days and shall make good any damage caused by its removal.

14. NOTICES

14.1 Any notice given under this Agreement shall be in writing and delivered by hand or sent by recorded delivery to the address of the recipient given in this Agreement, or to such other address as the recipient may notify.

14.2 A notice delivered by hand is given when it is left at the address. A notice sent by recorded delivery is given on the second Working Day after posting.

14.3 A notice given under this Agreement is not valid if sent by email.

15. ASSIGNMENT

15.1 This Agreement is personal to the Tenant, and the Tenant shall not assign, charge or otherwise deal with the benefit of this Agreement.

15.2 The Landlord may assign the benefit of this Agreement to a purchaser of its interest in the Building, provided that the purchaser enters into a deed of covenant with the Tenant to observe the obligations of the Landlord.

16. VAT

16.1 All sums payable under this Agreement are exclusive of VAT, which shall be paid in addition at the rate applicable at the time.

16.2 The Landlord confirms that it has opted to tax the Building for VAT purposes.

17. DISPUTES

17.1 Any dispute about the Landlord's Works, Practical Completion, defects or the extension of the Target Handover Date shall be referred to an independent expert.

17.2 The expert shall be a chartered building surveyor with at least ten years' experience of commercial property, agreed by the parties or, failing agreement, nominated by the President of the Royal Institution of Chartered Surveyors.

17.3 The expert shall act as an expert and not as an arbitrator. The decision of the expert is final and binding on the parties, except in the case of manifest error.

17.4 The costs of the expert shall be borne as the expert directs.

18. DATA PROTECTION

18.1 Each party shall comply with data protection legislation in relation to any personal data it processes in connection with this Agreement.

18.2 Neither party shall transfer personal data received from the other outside the United Kingdom without the prior written consent of the other.

19. CONFIDENTIALITY

19.1 Each party shall keep the terms of this Agreement confidential and shall not disclose them to any person, except to its professional advisers, its lenders and prospective purchasers of its interest, or as required by law, by any regulatory authority or by the rules of any stock exchange on which its shares are listed, and in each case only to the extent necessary, and each party shall procure that any person to whom it discloses those terms keeps them confidential on the same basis as if that person were a party to this Agreement.

19.2 The obligations in this clause 19 shall continue to apply for a period of two years after the Lease Date or the earlier termination of this Agreement.

20. ANTI-BRIBERY

20.1 Each party shall comply with all applicable laws relating to anti-bribery and anti-corruption, and shall not do anything which would cause the other party to breach those laws.

21. NON-MERGER

21.1 The provisions of this Agreement shall remain in force after the grant of the Lease in so far as any of them remain to be performed.

22. ENTIRE AGREEMENT

22.1 This Agreement and the documents annexed to it constitute the whole agreement between the parties and supersede all previous agreements between them relating to its subject matter.

22.2 Each party acknowledges that in entering into this Agreement it has not relied on any representation or warranty, except those set out in this Agreement or given in written replies to enquiries by the solicitors of one party to the solicitors of the other before the date of this Agreement.

23. JOINT AND SEVERAL LIABILITY

23.1 Where a party comprises more than one person, the obligations of those persons are joint and several.

24. THIRD PARTY RIGHTS

24.1 A person who is not a party to this Agreement shall not have any rights under the Contracts (Rights of Third Parties) Act 1999 to enforce any term of this Agreement.

25. GUARANTEE

25.1 In consideration of the Landlord entering into this Agreement at its request, the Guarantor guarantees to the Landlord that the Tenant shall perform its obligations under this Agreement.

25.2 The liability of the Guarantor shall not be affected by any time or indulgence granted to the Tenant, or by any variation of this Agreement.

26. COUNTERPARTS

26.1 This Agreement may be executed in any number of counterparts, each of which when executed shall constitute a duplicate original, but all the counterparts together shall constitute one agreement.

27. GOVERNING LAW AND JURISDICTION

27.1 This Agreement and any dispute or claim arising out of or in connection with it shall be governed by the law of England and Wales.

27.2 The courts of England and Wales shall have exclusive jurisdiction to settle any dispute or claim arising out of or in connection with this Agreement, subject to clause 17.

This Agreement has been entered into on the date stated at the beginning of it.

SCHEDULE 1 THE LANDLORD'S WORKS

The Landlord's Works comprise the following works to each floor of the Property, carried out in accordance with the specification below and the drawings listed in the Building Contract.

Ref	Floor	Element	Specification
LW001	Ground floor	External walls	Repair and repoint brickwork; replace defective lintels; apply breathable masonry protection to all elevations.
LW002	Ground floor	Windows	Replace windows with thermally broken aluminium double glazed units, U-value not exceeding 1.4 W/m²K, with trickle vents.
LW003	Ground floor	Floors	Level the structural slab to SR2 tolerance; install a raised access floor with a finished floor zone of 150 mm.
LW004	Ground floor	Ceilings	Expose and clean the soffit; install acoustic rafts to 40 per cent of the floor area.
LW005	Ground floor	Mechanical	Install a variable refrigerant flow system with fresh air heat recovery, designed for one person per 8 m² of net internal area.
LW006	Ground floor	Electrical	Install the main distribution, sub-metered per floor, with small power capacity of 25 W/m².
LW007	Ground floor	Lighting	Install LED panels with daylight dimming, average maintained illuminance of 400 lux at desk height.
LW008	Ground floor	Fire safety	Install an L1 fire alarm system and an automatic sprinkler system to the relevant standard.
LW009	Ground floor	Sanitary	Provide WC cores to the ratio of one WC per 10 persons, including one accessible WC.
LW010	Ground floor	Finishes	Paint walls in an agreed white; install entrance matting and floor finishes to the common parts.
LW011	First floor	External walls	Repair and repoint brickwork; replace defective lintels; apply breathable masonry protection to all elevations.
LW012	First floor	Windows	Replace windows with thermally broken aluminium double glazed units, U-value not exceeding 1.4 W/m²K, with trickle vents.
LW013	First floor	Floors	Level the structural slab to SR2 tolerance; install a raised access floor with a finished floor zone of 150 mm.
LW014	First floor	Ceilings	Expose and clean the soffit; install acoustic rafts to 40 per cent of the floor area.
LW015	First floor	Mechanical	Install a variable refrigerant flow system with fresh air heat recovery, designed for one person per 8 m² of net internal area.
LW016	First floor	Electrical	Install the main distribution, sub-metered per floor, with small power capacity of 25 W/m².
LW017	First floor	Lighting	Install LED panels with daylight dimming, average maintained illuminance of 400 lux at desk height.
LW018	First floor	Fire safety	Install an L1 fire alarm system and an automatic sprinkler system to the relevant standard.
LW019	First floor	Sanitary	Provide WC cores to the ratio of one WC per 10 persons, including one accessible WC.
LW020	First floor	Finishes	Paint walls in an agreed white; install entrance matting and floor finishes to the common parts.
LW021	Second floor	External walls	Repair and repoint brickwork; replace defective lintels; apply breathable masonry protection to all elevations.

Ref	Floor	Element	Specification
LW022	Second floor	Windows	Replace windows with thermally broken aluminium double glazed units, U-value not exceeding 1.4 W/m²K, with trickle vents.
LW023	Second floor	Floors	Level the structural slab to SR2 tolerance; install a raised access floor with a finished floor zone of 150 mm.
LW024	Second floor	Ceilings	Expose and clean the soffit; install acoustic rafts to 40 per cent of the floor area.
LW025	Second floor	Mechanical	Install a variable refrigerant flow system with fresh air heat recovery, designed for one person per 8 m² of net internal area.
LW026	Second floor	Electrical	Install the main distribution, sub-metered per floor, with small power capacity of 25 W/m².
LW027	Second floor	Lighting	Install LED panels with daylight dimming, average maintained illuminance of 400 lux at desk height.
LW028	Second floor	Fire safety	Install an L1 fire alarm system and an automatic sprinkler system to the relevant standard.
LW029	Second floor	Sanitary	Provide WC cores to the ratio of one WC per 10 persons, including one accessible WC.
LW030	Second floor	Finishes	Paint walls in an agreed white; install entrance matting and floor finishes to the common parts.
LW031	Third floor	External walls	Repair and repoint brickwork; replace defective lintels; apply breathable masonry protection to all elevations.
LW032	Third floor	Windows	Replace windows with thermally broken aluminium double glazed units, U-value not exceeding 1.4 W/m²K, with trickle vents.
LW033	Third floor	Floors	Level the structural slab to SR2 tolerance; install a raised access floor with a finished floor zone of 150 mm.
LW034	Third floor	Ceilings	Expose and clean the soffit; install acoustic rafts to 40 per cent of the floor area.
LW035	Third floor	Mechanical	Install a variable refrigerant flow system with fresh air heat recovery, designed for one person per 8 m² of net internal area.
LW036	Third floor	Electrical	Install the main distribution, sub-metered per floor, with small power capacity of 25 W/m².
LW037	Third floor	Lighting	Install LED panels with daylight dimming, average maintained illuminance of 400 lux at desk height.
LW038	Third floor	Fire safety	Install an L1 fire alarm system and an automatic sprinkler system to the relevant standard.
LW039	Third floor	Sanitary	Provide WC cores to the ratio of one WC per 10 persons, including one accessible WC.
LW040	Third floor	Finishes	Paint walls in an agreed white; install entrance matting and floor finishes to the common parts.
LW041	Roof	External walls	Repair and repoint brickwork; replace defective lintels; apply breathable masonry protection to all elevations.
LW042	Roof	Windows	Replace windows with thermally broken aluminium double glazed units, U-value not exceeding 1.4 W/m²K, with trickle vents.
LW043	Roof	Mechanical	Install a variable refrigerant flow system with fresh air heat recovery, designed for one person per 8 m² of net internal area.
LW044	Roof	Electrical	Install the main distribution, sub-metered per floor, with small power capacity of 25 W/m².

Ref	Floor	Element	Specification
LW045	Roof	Fire safety	Install an L1 fire alarm system and an automatic sprinkler system to the relevant standard.
LW046	Roof	Finishes	Paint walls in an agreed white; install entrance matting and floor finishes to the common parts.

SCHEDULE 2 THE TENANT'S WORKS

1. Installation of partitions, meeting rooms and production studios in accordance with the approved plans.
2. Acoustic treatment of the studios to achieve a sound reduction of not less than 55 dB between the studios and the adjoining offices.
3. Installation of a kitchen and breakout area on the first floor.
4. Installation of data cabling, a communications room and supplementary cooling to the communications room.
5. Installation of furniture, signage within the Property and audio-visual equipment.
6. Any works required to the mechanical and electrical systems to serve the Tenant's layout, subject to clause 8.3.

SCHEDULE 3 PRINCIPAL TERMS OF THE LEASE

Term of the Lease	Provision
Term	Fifteen years from and including the Lease Date
Initial Rent	£486,500 a year exclusive of VAT, payable quarterly in advance
Rent-free period	Nine months from the Lease Date, extended under clause 7.2 for delay
Rent reviews	Upwards only, to open market rent, on the fifth and tenth anniversaries of the Lease Date
Tenant's break option	Tenth anniversary of the Lease Date, on twelve months' written notice
Repair	Full repairing, limited by reference to a schedule of condition
Alienation	Assignment of the whole with consent; underletting of the whole or of a floor with consent
Permitted Use	Offices and production studios
Service charge	Fair proportion of the costs of the services to the Building
Rent Deposit	£243,250, to be released on the third anniversary of the Lease Date if the Tenant meets the release conditions

SCHEDULE 4 RENT AND RENT-FREE PERIODS

The table below shows the rent payable in each year of the Term, assuming that the Lease Date is 1 July 2027 and that no rent review increases the rent. It is for information only and does not form part of the terms of the Lease.

Lease year	From	To	Rent payable (£)	Note
1	1 July 2027	30 June 2028	121,625	Nine months rent free
2	1 July 2028	30 June 2029	486,500	
3	1 July 2029	30 June 2030	486,500	
4	1 July 2030	30 June 2031	486,500	
5	1 July 2031	30 June 2032	486,500	
6	1 July 2032	30 June 2033	486,500	Rent review
7	1 July 2033	30 June 2034	486,500	
8	1 July 2034	30 June 2035	486,500	
9	1 July 2035	30 June 2036	486,500	
10	1 July 2036	30 June 2037	486,500	Break date at end of year
11	1 July 2037	30 June 2038	486,500	Rent review
12	1 July 2038	30 June 2039	486,500	
13	1 July 2039	30 June 2040	486,500	
14	1 July 2040	30 June 2041	486,500	
15	1 July 2041	30 June 2042	486,500	

SCHEDULE 5 PROGRAMME

The programme below is the Landlord's current estimate. It does not form part of the obligations of the Landlord, which are set out in clauses 3 and 7.

Activity	Start	Finish	Duration
Planning application determined	1 September 2026	30 November 2026	13 weeks
Building Contract entered into	1 December 2026	15 December 2026	2 weeks
Strip out and enabling works	4 January 2027	12 February 2027	6 weeks
External envelope and windows	15 February 2027	7 May 2027	12 weeks
Mechanical and electrical first fix	1 March 2027	30 April 2027	9 weeks
Raised floors and ceilings	3 May 2027	28 May 2027	4 weeks
Tenant access for data cabling	5 May 2027	30 June 2027	8 weeks
Mechanical and electrical second fix	3 May 2027	11 June 2027	6 weeks
Commissioning and testing	14 June 2027	25 June 2027	2 weeks
Practical Completion inspection	28 June 2027	29 June 2027	2 days
Target Handover Date	30 June 2027	30 June 2027	-

SCHEDULE 6 SCHEDULE OF CONDITION

The condition of the Property at the date of this Agreement, recorded by the Landlord's Surveyor and agreed by the Tenant's Surveyor. The photographs referred to are held by both surveyors. The Tenant shall not be required to put the Property into any better state of repair than that recorded in this Schedule, as improved by the Landlord's Works.

Ref	Floor	Area	Element	Condition
SC001	Lower ground floor	Reception	Floor	Vinyl lifting at two joints (photo 001)
SC002	Lower ground floor	Reception	Walls	Plaster damaged around redundant sockets (photo 002)
SC003	Lower ground floor	Reception	Ceiling	Ceiling tiles stained near the riser (photo 003)
SC004	Lower ground floor	Reception	Windows	Cill boards chipped (photo 004)
SC005	Lower ground floor	Reception	Doors	Door binding on the floor finish (photo 005)
SC006	Lower ground floor	Open plan office (north)	Floor	Vinyl lifting at two joints (photo 006)
SC007	Lower ground floor	Open plan office (north)	Walls	Paint scuffed at low level (photo 007)
SC008	Lower ground floor	Open plan office (north)	Ceiling	Ceiling tiles stained near the riser (photo 008)
SC009	Lower ground floor	Open plan office (north)	Windows	Sealed units misted in two panes (photo 009)
SC010	Lower ground floor	Open plan office (north)	Doors	Door binding on the floor finish (photo 010)
SC011	Lower ground floor	Open plan office (south)	Floor	Fair condition
SC012	Lower ground floor	Open plan office (south)	Walls	Plaster damaged around redundant sockets (photo 012)
SC013	Lower ground floor	Open plan office (south)	Ceiling	Ceiling tiles stained near the riser (photo 013)
SC014	Lower ground floor	Open plan office (south)	Windows	Ironmongery missing on one opening light (photo 014)
SC015	Lower ground floor	Open plan office (south)	Doors	Fair condition
SC016	Lower ground floor	Open plan office (east)	Floor	Fair condition
SC017	Lower ground floor	Open plan office (east)	Walls	Plaster damaged around redundant sockets (photo 017)
SC018	Lower ground floor	Open plan office (east)	Ceiling	Grid bent at the light fittings (photo 018)
SC019	Lower ground floor	Open plan office (east)	Windows	Ironmongery missing on one opening light (photo 019)
SC020	Lower ground floor	Open plan office (east)	Doors	Door closer leaking oil (photo 020)
SC021	Lower ground floor	Meeting room 1	Floor	Raised floor panels rocking in three places (photo 021)
SC022	Lower ground floor	Meeting room 1	Walls	Minor hairline cracks above the door head (photo 022)
SC023	Lower ground floor	Meeting room 1	Ceiling	Ceiling tiles stained near the riser (photo 023)
SC024	Lower ground floor	Meeting room 1	Windows	Seals perished on the north elevation (photo 024)

Ref	Floor	Area	Element	Condition
SC025	Lower ground floor	Meeting room 1	Doors	Frame damaged at the latch side (photo 025)
SC026	Lower ground floor	Meeting room 2	Floor	Vinyl lifting at two joints (photo 026)
SC027	Lower ground floor	Meeting room 2	Walls	Minor hairline cracks above the door head (photo 027)
SC028	Lower ground floor	Meeting room 2	Ceiling	Grid bent at the light fittings (photo 028)
SC029	Lower ground floor	Meeting room 2	Windows	Seals perished on the north elevation (photo 029)
SC030	Lower ground floor	Meeting room 2	Doors	Frame damaged at the latch side (photo 030)
SC031	Lower ground floor	Meeting room 3	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 031)
SC032	Lower ground floor	Meeting room 3	Walls	Fair condition
SC033	Lower ground floor	Meeting room 3	Ceiling	Grid bent at the light fittings (photo 033)
SC034	Lower ground floor	Meeting room 3	Windows	Cill boards chipped (photo 034)
SC035	Lower ground floor	Meeting room 3	Doors	Fair condition
SC036	Lower ground floor	Kitchen	Floor	Vinyl lifting at two joints (photo 036)
SC037	Lower ground floor	Kitchen	Walls	Minor hairline cracks above the door head (photo 037)
SC038	Lower ground floor	Kitchen	Ceiling	Missing tiles in the grid (photo 038)
SC039	Lower ground floor	Kitchen	Windows	Cill boards chipped (photo 039)
SC040	Lower ground floor	Kitchen	Doors	Frame damaged at the latch side (photo 040)
SC041	Lower ground floor	WC core A	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 041)
SC042	Lower ground floor	WC core A	Walls	Fair condition
SC043	Lower ground floor	WC core A	Ceiling	Grid bent at the light fittings (photo 043)
SC044	Lower ground floor	WC core A	Windows	Sealed units misted in two panes (photo 044)
SC045	Lower ground floor	WC core A	Doors	Frame damaged at the latch side (photo 045)
SC046	Lower ground floor	WC core B	Floor	Fair condition
SC047	Lower ground floor	WC core B	Walls	Plaster damaged around redundant sockets (photo 047)
SC048	Lower ground floor	WC core B	Ceiling	Fair condition
SC049	Lower ground floor	WC core B	Windows	Ironmongery missing on one opening light (photo 049)
SC050	Lower ground floor	WC core B	Doors	Door binding on the floor finish (photo 050)
SC051	Lower ground floor	Shower room	Floor	Screed exposed, minor cracking (photo 051)
SC052	Lower ground floor	Shower room	Walls	Fair condition
SC053	Lower ground floor	Shower room	Ceiling	Grid bent at the light fittings (photo 053)
SC054	Lower ground floor	Shower room	Windows	Cill boards chipped (photo 054)
SC055	Lower ground floor	Shower room	Doors	Door binding on the floor finish (photo 055)
SC056	Lower ground floor	Stair core 1	Floor	Vinyl lifting at two joints (photo 056)
SC057	Lower ground floor	Stair core 1	Walls	Minor hairline cracks above the door head (photo 057)
SC058	Lower ground floor	Stair core 1	Ceiling	Grid bent at the light fittings (photo 058)

Ref	Floor	Area	Element	Condition
SC059	Lower ground floor	Stair core 1	Windows	Seals perished on the north elevation (photo 059)
SC060	Lower ground floor	Stair core 1	Doors	Door closer leaking oil (photo 060)
SC061	Lower ground floor	Stair core 2	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 061)
SC062	Lower ground floor	Stair core 2	Walls	Paint scuffed at low level (photo 062)
SC063	Lower ground floor	Stair core 2	Ceiling	Exposed soffit, old fixings left in place (photo 063)
SC064	Lower ground floor	Stair core 2	Windows	Seals perished on the north elevation (photo 064)
SC065	Lower ground floor	Stair core 2	Doors	Fair condition
SC066	Lower ground floor	Lift lobby	Floor	Fair condition
SC067	Lower ground floor	Lift lobby	Walls	Damp staining below the window cill (photo 067)
SC068	Lower ground floor	Lift lobby	Ceiling	Grid bent at the light fittings (photo 068)
SC069	Lower ground floor	Lift lobby	Windows	Ironmongery missing on one opening light (photo 069)
SC070	Lower ground floor	Lift lobby	Doors	Vision panel cracked (photo 070)
SC071	Lower ground floor	Riser 1	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 071)
SC072	Lower ground floor	Riser 1	Walls	Damp staining below the window cill (photo 072)
SC073	Lower ground floor	Riser 1	Ceiling	Missing tiles in the grid (photo 073)
SC074	Lower ground floor	Riser 1	Windows	Cill boards chipped (photo 074)
SC075	Lower ground floor	Riser 1	Doors	Frame damaged at the latch side (photo 075)
SC076	Lower ground floor	Riser 2	Floor	Vinyl lifting at two joints (photo 076)
SC077	Lower ground floor	Riser 2	Walls	Plaster damaged around redundant sockets (photo 077)
SC078	Lower ground floor	Riser 2	Ceiling	Exposed soffit, old fixings left in place (photo 078)
SC079	Lower ground floor	Riser 2	Windows	Fair condition
SC080	Lower ground floor	Riser 2	Doors	Frame damaged at the latch side (photo 080)
SC081	Ground floor	Reception	Floor	Fair condition
SC082	Ground floor	Reception	Walls	Minor hairline cracks above the door head (photo 082)
SC083	Ground floor	Reception	Ceiling	Grid bent at the light fittings (photo 083)
SC084	Ground floor	Reception	Windows	Sealed units misted in two panes (photo 084)
SC085	Ground floor	Reception	Doors	Door closer leaking oil (photo 085)
SC086	Ground floor	Open plan office (north)	Floor	Vinyl lifting at two joints (photo 086)
SC087	Ground floor	Open plan office (north)	Walls	Plaster damaged around redundant sockets (photo 087)
SC088	Ground floor	Open plan office (north)	Ceiling	Fair condition
SC089	Ground floor	Open plan office (north)	Windows	Fair condition
SC090	Ground floor	Open plan office (north)	Doors	Vision panel cracked (photo 090)

Ref	Floor	Area	Element	Condition
SC091	Ground floor	Open plan office (south)	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 091)
SC092	Ground floor	Open plan office (south)	Walls	Plaster damaged around redundant sockets (photo 092)
SC093	Ground floor	Open plan office (south)	Ceiling	Missing tiles in the grid (photo 093)
SC094	Ground floor	Open plan office (south)	Windows	Seals perished on the north elevation (photo 094)
SC095	Ground floor	Open plan office (south)	Doors	Door binding on the floor finish (photo 095)
SC096	Ground floor	Open plan office (east)	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 096)
SC097	Ground floor	Open plan office (east)	Walls	Paint scuffed at low level (photo 097)
SC098	Ground floor	Open plan office (east)	Ceiling	Grid bent at the light fittings (photo 098)
SC099	Ground floor	Open plan office (east)	Windows	Sealed units misted in two panes (photo 099)
SC100	Ground floor	Open plan office (east)	Doors	Frame damaged at the latch side (photo 100)
SC101	Ground floor	Meeting room 1	Floor	Raised floor panels rocking in three places (photo 101)
SC102	Ground floor	Meeting room 1	Walls	Paint scuffed at low level (photo 102)
SC103	Ground floor	Meeting room 1	Ceiling	Grid bent at the light fittings (photo 103)
SC104	Ground floor	Meeting room 1	Windows	Seals perished on the north elevation (photo 104)
SC105	Ground floor	Meeting room 1	Doors	Frame damaged at the latch side (photo 105)
SC106	Ground floor	Meeting room 2	Floor	Vinyl lifting at two joints (photo 106)
SC107	Ground floor	Meeting room 2	Walls	Damp staining below the window cill (photo 107)
SC108	Ground floor	Meeting room 2	Ceiling	Fair condition
SC109	Ground floor	Meeting room 2	Windows	Sealed units misted in two panes (photo 109)
SC110	Ground floor	Meeting room 2	Doors	Frame damaged at the latch side (photo 110)
SC111	Ground floor	Meeting room 3	Floor	Fair condition
SC112	Ground floor	Meeting room 3	Walls	Minor hairline cracks above the door head (photo 112)
SC113	Ground floor	Meeting room 3	Ceiling	Exposed soffit, old fixings left in place (photo 113)
SC114	Ground floor	Meeting room 3	Windows	Seals perished on the north elevation (photo 114)
SC115	Ground floor	Meeting room 3	Doors	Vision panel cracked (photo 115)
SC116	Ground floor	Kitchen	Floor	Raised floor panels rocking in three places (photo 116)
SC117	Ground floor	Kitchen	Walls	Damp staining below the window cill (photo 117)
SC118	Ground floor	Kitchen	Ceiling	Fair condition
SC119	Ground floor	Kitchen	Windows	Ironmongery missing on one opening light (photo 119)
SC120	Ground floor	Kitchen	Doors	Frame damaged at the latch side (photo 120)
SC121	Ground floor	WC core A	Floor	Fair condition
SC122	Ground floor	WC core A	Walls	Paint scuffed at low level (photo 122)

Ref	Floor	Area	Element	Condition
SC123	Ground floor	WC core A	Ceiling	Grid bent at the light fittings (photo 123)
SC124	Ground floor	WC core A	Windows	Sealed units misted in two panes (photo 124)
SC125	Ground floor	WC core A	Doors	Door binding on the floor finish (photo 125)
SC126	Ground floor	WC core B	Floor	Vinyl lifting at two joints (photo 126)
SC127	Ground floor	WC core B	Walls	Plaster damaged around redundant sockets (photo 127)
SC128	Ground floor	WC core B	Ceiling	Grid bent at the light fittings (photo 128)
SC129	Ground floor	WC core B	Windows	Seals perished on the north elevation (photo 129)
SC130	Ground floor	WC core B	Doors	Fair condition
SC131	Ground floor	Shower room	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 131)
SC132	Ground floor	Shower room	Walls	Damp staining below the window cill (photo 132)
SC133	Ground floor	Shower room	Ceiling	Missing tiles in the grid (photo 133)
SC134	Ground floor	Shower room	Windows	Cill boards chipped (photo 134)
SC135	Ground floor	Shower room	Doors	Vision panel cracked (photo 135)
SC136	Ground floor	Stair core 1	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 136)
SC137	Ground floor	Stair core 1	Walls	Paint scuffed at low level (photo 137)
SC138	Ground floor	Stair core 1	Ceiling	Ceiling tiles stained near the riser (photo 138)
SC139	Ground floor	Stair core 1	Windows	Sealed units misted in two panes (photo 139)
SC140	Ground floor	Stair core 1	Doors	Vision panel cracked (photo 140)
SC141	Ground floor	Stair core 2	Floor	Fair condition
SC142	Ground floor	Stair core 2	Walls	Minor hairline cracks above the door head (photo 142)
SC143	Ground floor	Stair core 2	Ceiling	Fair condition
SC144	Ground floor	Stair core 2	Windows	Sealed units misted in two panes (photo 144)
SC145	Ground floor	Stair core 2	Doors	Fair condition
SC146	Ground floor	Lift lobby	Floor	Screed exposed, minor cracking (photo 146)
SC147	Ground floor	Lift lobby	Walls	Fair condition
SC148	Ground floor	Lift lobby	Ceiling	Missing tiles in the grid (photo 148)
SC149	Ground floor	Lift lobby	Windows	Seals perished on the north elevation (photo 149)
SC150	Ground floor	Lift lobby	Doors	Door closer leaking oil (photo 150)
SC151	Ground floor	Riser 1	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 151)
SC152	Ground floor	Riser 1	Walls	Fair condition
SC153	Ground floor	Riser 1	Ceiling	Grid bent at the light fittings (photo 153)
SC154	Ground floor	Riser 1	Windows	Cill boards chipped (photo 154)
SC155	Ground floor	Riser 1	Doors	Vision panel cracked (photo 155)
SC156	Ground floor	Riser 2	Floor	Screed exposed, minor cracking (photo 156)
SC157	Ground floor	Riser 2	Walls	Minor hairline cracks above the door head (photo 157)

Ref	Floor	Area	Element	Condition
SC158	Ground floor	Riser 2	Ceiling	Missing tiles in the grid (photo 158)
SC159	Ground floor	Riser 2	Windows	Cill boards chipped (photo 159)
SC160	Ground floor	Riser 2	Doors	Door binding on the floor finish (photo 160)
SC161	First floor	Reception	Floor	Screed exposed, minor cracking (photo 161)
SC162	First floor	Reception	Walls	Paint scuffed at low level (photo 162)
SC163	First floor	Reception	Ceiling	Missing tiles in the grid (photo 163)
SC164	First floor	Reception	Windows	Cill boards chipped (photo 164)
SC165	First floor	Reception	Doors	Door binding on the floor finish (photo 165)
SC166	First floor	Open plan office (north)	Floor	Vinyl lifting at two joints (photo 166)
SC167	First floor	Open plan office (north)	Walls	Damp staining below the window cill (photo 167)
SC168	First floor	Open plan office (north)	Ceiling	Missing tiles in the grid (photo 168)
SC169	First floor	Open plan office (north)	Windows	Cill boards chipped (photo 169)
SC170	First floor	Open plan office (north)	Doors	Vision panel cracked (photo 170)
SC171	First floor	Open plan office (south)	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 171)
SC172	First floor	Open plan office (south)	Walls	Paint scuffed at low level (photo 172)
SC173	First floor	Open plan office (south)	Ceiling	Grid bent at the light fittings (photo 173)
SC174	First floor	Open plan office (south)	Windows	Seals perished on the north elevation (photo 174)
SC175	First floor	Open plan office (south)	Doors	Vision panel cracked (photo 175)
SC176	First floor	Open plan office (east)	Floor	Fair condition
SC177	First floor	Open plan office (east)	Walls	Minor hairline cracks above the door head (photo 177)
SC178	First floor	Open plan office (east)	Ceiling	Missing tiles in the grid (photo 178)
SC179	First floor	Open plan office (east)	Windows	Cill boards chipped (photo 179)
SC180	First floor	Open plan office (east)	Doors	Frame damaged at the latch side (photo 180)
SC181	First floor	Meeting room 1	Floor	Vinyl lifting at two joints (photo 181)
SC182	First floor	Meeting room 1	Walls	Plaster damaged around redundant sockets (photo 182)
SC183	First floor	Meeting room 1	Ceiling	Ceiling tiles stained near the riser (photo 183)
SC184	First floor	Meeting room 1	Windows	Seals perished on the north elevation (photo 184)
SC185	First floor	Meeting room 1	Doors	Fair condition
SC186	First floor	Meeting room 2	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 186)
SC187	First floor	Meeting room 2	Walls	Fair condition

Ref	Floor	Area	Element	Condition
SC188	First floor	Meeting room 2	Ceiling	Exposed soffit, old fixings left in place (photo 188)
SC189	First floor	Meeting room 2	Windows	Sealed units misted in two panes (photo 189)
SC190	First floor	Meeting room 2	Doors	Door binding on the floor finish (photo 190)
SC191	First floor	Meeting room 3	Floor	Screed exposed, minor cracking (photo 191)
SC192	First floor	Meeting room 3	Walls	Paint scuffed at low level (photo 192)
SC193	First floor	Meeting room 3	Ceiling	Exposed soffit, old fixings left in place (photo 193)
SC194	First floor	Meeting room 3	Windows	Ironmongery missing on one opening light (photo 194)
SC195	First floor	Meeting room 3	Doors	Fair condition
SC196	First floor	Kitchen	Floor	Vinyl lifting at two joints (photo 196)
SC197	First floor	Kitchen	Walls	Plaster damaged around redundant sockets (photo 197)
SC198	First floor	Kitchen	Ceiling	Grid bent at the light fittings (photo 198)
SC199	First floor	Kitchen	Windows	Cill boards chipped (photo 199)
SC200	First floor	Kitchen	Doors	Frame damaged at the latch side (photo 200)
SC201	First floor	WC core A	Floor	Screed exposed, minor cracking (photo 201)
SC202	First floor	WC core A	Walls	Fair condition
SC203	First floor	WC core A	Ceiling	Missing tiles in the grid (photo 203)
SC204	First floor	WC core A	Windows	Seals perished on the north elevation (photo 204)
SC205	First floor	WC core A	Doors	Frame damaged at the latch side (photo 205)
SC206	First floor	WC core B	Floor	Screed exposed, minor cracking (photo 206)
SC207	First floor	WC core B	Walls	Damp staining below the window cill (photo 207)
SC208	First floor	WC core B	Ceiling	Ceiling tiles stained near the riser (photo 208)
SC209	First floor	WC core B	Windows	Seals perished on the north elevation (photo 209)
SC210	First floor	WC core B	Doors	Vision panel cracked (photo 210)
SC211	First floor	Shower room	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 211)
SC212	First floor	Shower room	Walls	Damp staining below the window cill (photo 212)
SC213	First floor	Shower room	Ceiling	Fair condition
SC214	First floor	Shower room	Windows	Ironmongery missing on one opening light (photo 214)
SC215	First floor	Shower room	Doors	Frame damaged at the latch side (photo 215)
SC216	First floor	Stair core 1	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 216)
SC217	First floor	Stair core 1	Walls	Minor hairline cracks above the door head (photo 217)
SC218	First floor	Stair core 1	Ceiling	Exposed soffit, old fixings left in place (photo 218)
SC219	First floor	Stair core 1	Windows	Fair condition
SC220	First floor	Stair core 1	Doors	Door binding on the floor finish (photo 220)
SC221	First floor	Stair core 2	Floor	Screed exposed, minor cracking (photo 221)
SC222	First floor	Stair core 2	Walls	Damp staining below the window cill (photo 222)

Ref	Floor	Area	Element	Condition
SC223	First floor	Stair core 2	Ceiling	Missing tiles in the grid (photo 223)
SC224	First floor	Stair core 2	Windows	Sealed units misted in two panes (photo 224)
SC225	First floor	Stair core 2	Doors	Vision panel cracked (photo 225)
SC226	First floor	Lift lobby	Floor	Vinyl lifting at two joints (photo 226)
SC227	First floor	Lift lobby	Walls	Paint scuffed at low level (photo 227)
SC228	First floor	Lift lobby	Ceiling	Fair condition
SC229	First floor	Lift lobby	Windows	Seals perished on the north elevation (photo 229)
SC230	First floor	Lift lobby	Doors	Door closer leaking oil (photo 230)
SC231	First floor	Riser 1	Floor	Screed exposed, minor cracking (photo 231)
SC232	First floor	Riser 1	Walls	Damp staining below the window cill (photo 232)
SC233	First floor	Riser 1	Ceiling	Missing tiles in the grid (photo 233)
SC234	First floor	Riser 1	Windows	Fair condition
SC235	First floor	Riser 1	Doors	Door closer leaking oil (photo 235)
SC236	First floor	Riser 2	Floor	Vinyl lifting at two joints (photo 236)
SC237	First floor	Riser 2	Walls	Minor hairline cracks above the door head (photo 237)
SC238	First floor	Riser 2	Ceiling	Fair condition
SC239	First floor	Riser 2	Windows	Seals perished on the north elevation (photo 239)
SC240	First floor	Riser 2	Doors	Fair condition
SC241	Second floor	Reception	Floor	Screed exposed, minor cracking (photo 241)
SC242	Second floor	Reception	Walls	Fair condition
SC243	Second floor	Reception	Ceiling	Exposed soffit, old fixings left in place (photo 243)
SC244	Second floor	Reception	Windows	Sealed units misted in two panes (photo 244)
SC245	Second floor	Reception	Doors	Door closer leaking oil (photo 245)
SC246	Second floor	Open plan office (north)	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 246)
SC247	Second floor	Open plan office (north)	Walls	Fair condition
SC248	Second floor	Open plan office (north)	Ceiling	Ceiling tiles stained near the riser (photo 248)
SC249	Second floor	Open plan office (north)	Windows	Cill boards chipped (photo 249)
SC250	Second floor	Open plan office (north)	Doors	Fair condition
SC251	Second floor	Open plan office (south)	Floor	Raised floor panels rocking in three places (photo 251)
SC252	Second floor	Open plan office (south)	Walls	Fair condition
SC253	Second floor	Open plan office (south)	Ceiling	Missing tiles in the grid (photo 253)
SC254	Second floor	Open plan office (south)	Windows	Sealed units misted in two panes (photo 254)

Ref	Floor	Area	Element	Condition
SC255	Second floor	Open plan office (south)	Doors	Frame damaged at the latch side (photo 255)
SC256	Second floor	Open plan office (east)	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 256)
SC257	Second floor	Open plan office (east)	Walls	Fair condition
SC258	Second floor	Open plan office (east)	Ceiling	Ceiling tiles stained near the riser (photo 258)
SC259	Second floor	Open plan office (east)	Windows	Seals perished on the north elevation (photo 259)
SC260	Second floor	Open plan office (east)	Doors	Frame damaged at the latch side (photo 260)
SC261	Second floor	Meeting room 1	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 261)
SC262	Second floor	Meeting room 1	Walls	Paint scuffed at low level (photo 262)
SC263	Second floor	Meeting room 1	Ceiling	Fair condition
SC264	Second floor	Meeting room 1	Windows	Cill boards chipped (photo 264)
SC265	Second floor	Meeting room 1	Doors	Door binding on the floor finish (photo 265)
SC266	Second floor	Meeting room 2	Floor	Vinyl lifting at two joints (photo 266)
SC267	Second floor	Meeting room 2	Walls	Plaster damaged around redundant sockets (photo 267)
SC268	Second floor	Meeting room 2	Ceiling	Exposed soffit, old fixings left in place (photo 268)
SC269	Second floor	Meeting room 2	Windows	Ironmongery missing on one opening light (photo 269)
SC270	Second floor	Meeting room 2	Doors	Door binding on the floor finish (photo 270)
SC271	Second floor	Meeting room 3	Floor	Screed exposed, minor cracking (photo 271)
SC272	Second floor	Meeting room 3	Walls	Paint scuffed at low level (photo 272)
SC273	Second floor	Meeting room 3	Ceiling	Ceiling tiles stained near the riser (photo 273)
SC274	Second floor	Meeting room 3	Windows	Sealed units misted in two panes (photo 274)
SC275	Second floor	Meeting room 3	Doors	Fair condition
SC276	Second floor	Kitchen	Floor	Raised floor panels rocking in three places (photo 276)
SC277	Second floor	Kitchen	Walls	Fair condition
SC278	Second floor	Kitchen	Ceiling	Exposed soffit, old fixings left in place (photo 278)
SC279	Second floor	Kitchen	Windows	Cill boards chipped (photo 279)
SC280	Second floor	Kitchen	Doors	Door binding on the floor finish (photo 280)
SC281	Second floor	WC core A	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 281)
SC282	Second floor	WC core A	Walls	Minor hairline cracks above the door head (photo 282)
SC283	Second floor	WC core A	Ceiling	Grid bent at the light fittings (photo 283)
SC284	Second floor	WC core A	Windows	Cill boards chipped (photo 284)
SC285	Second floor	WC core A	Doors	Door binding on the floor finish (photo 285)
SC286	Second floor	WC core B	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 286)
SC287	Second floor	WC core B	Walls	Fair condition

Ref	Floor	Area	Element	Condition
SC288	Second floor	WC core B	Ceiling	Missing tiles in the grid (photo 288)
SC289	Second floor	WC core B	Windows	Seals perished on the north elevation (photo 289)
SC290	Second floor	WC core B	Doors	Vision panel cracked (photo 290)
SC291	Second floor	Shower room	Floor	Vinyl lifting at two joints (photo 291)
SC292	Second floor	Shower room	Walls	Minor hairline cracks above the door head (photo 292)
SC293	Second floor	Shower room	Ceiling	Grid bent at the light fittings (photo 293)
SC294	Second floor	Shower room	Windows	Cill boards chipped (photo 294)
SC295	Second floor	Shower room	Doors	Frame damaged at the latch side (photo 295)
SC296	Second floor	Stair core 1	Floor	Raised floor panels rocking in three places (photo 296)
SC297	Second floor	Stair core 1	Walls	Fair condition
SC298	Second floor	Stair core 1	Ceiling	Ceiling tiles stained near the riser (photo 298)
SC299	Second floor	Stair core 1	Windows	Ironmongery missing on one opening light (photo 299)
SC300	Second floor	Stair core 1	Doors	Door closer leaking oil (photo 300)
SC301	Second floor	Stair core 2	Floor	Raised floor panels rocking in three places (photo 301)
SC302	Second floor	Stair core 2	Walls	Paint scuffed at low level (photo 302)
SC303	Second floor	Stair core 2	Ceiling	Fair condition
SC304	Second floor	Stair core 2	Windows	Sealed units misted in two panes (photo 304)
SC305	Second floor	Stair core 2	Doors	Door binding on the floor finish (photo 305)
SC306	Second floor	Lift lobby	Floor	Fair condition
SC307	Second floor	Lift lobby	Walls	Damp staining below the window cill (photo 307)
SC308	Second floor	Lift lobby	Ceiling	Fair condition
SC309	Second floor	Lift lobby	Windows	Sealed units misted in two panes (photo 309)
SC310	Second floor	Lift lobby	Doors	Fair condition
SC311	Second floor	Riser 1	Floor	Vinyl lifting at two joints (photo 311)
SC312	Second floor	Riser 1	Walls	Damp staining below the window cill (photo 312)
SC313	Second floor	Riser 1	Ceiling	Grid bent at the light fittings (photo 313)
SC314	Second floor	Riser 1	Windows	Seals perished on the north elevation (photo 314)
SC315	Second floor	Riser 1	Doors	Vision panel cracked (photo 315)
SC316	Second floor	Riser 2	Floor	Vinyl lifting at two joints (photo 316)
SC317	Second floor	Riser 2	Walls	Paint scuffed at low level (photo 317)
SC318	Second floor	Riser 2	Ceiling	Ceiling tiles stained near the riser (photo 318)
SC319	Second floor	Riser 2	Windows	Fair condition
SC320	Second floor	Riser 2	Doors	Frame damaged at the latch side (photo 320)
SC321	Third floor	Reception	Floor	Fair condition
SC322	Third floor	Reception	Walls	Damp staining below the window cill (photo 322)
SC323	Third floor	Reception	Ceiling	Fair condition

Ref	Floor	Area	Element	Condition
SC324	Third floor	Reception	Windows	Seals perished on the north elevation (photo 324)
SC325	Third floor	Reception	Doors	Fair condition
SC326	Third floor	Open plan office (north)	Floor	Screed exposed, minor cracking (photo 326)
SC327	Third floor	Open plan office (north)	Walls	Fair condition
SC328	Third floor	Open plan office (north)	Ceiling	Fair condition
SC329	Third floor	Open plan office (north)	Windows	Cill boards chipped (photo 329)
SC330	Third floor	Open plan office (north)	Doors	Door binding on the floor finish (photo 330)
SC331	Third floor	Open plan office (south)	Floor	Vinyl lifting at two joints (photo 331)
SC332	Third floor	Open plan office (south)	Walls	Plaster damaged around redundant sockets (photo 332)
SC333	Third floor	Open plan office (south)	Ceiling	Fair condition
SC334	Third floor	Open plan office (south)	Windows	Seals perished on the north elevation (photo 334)
SC335	Third floor	Open plan office (south)	Doors	Frame damaged at the latch side (photo 335)
SC336	Third floor	Open plan office (east)	Floor	Vinyl lifting at two joints (photo 336)
SC337	Third floor	Open plan office (east)	Walls	Damp staining below the window cill (photo 337)
SC338	Third floor	Open plan office (east)	Ceiling	Ceiling tiles stained near the riser (photo 338)
SC339	Third floor	Open plan office (east)	Windows	Fair condition
SC340	Third floor	Open plan office (east)	Doors	Vision panel cracked (photo 340)
SC341	Third floor	Meeting room 1	Floor	Fair condition
SC342	Third floor	Meeting room 1	Walls	Minor hairline cracks above the door head (photo 342)
SC343	Third floor	Meeting room 1	Ceiling	Grid bent at the light fittings (photo 343)
SC344	Third floor	Meeting room 1	Windows	Seals perished on the north elevation (photo 344)
SC345	Third floor	Meeting room 1	Doors	Vision panel cracked (photo 345)
SC346	Third floor	Meeting room 2	Floor	Fair condition
SC347	Third floor	Meeting room 2	Walls	Plaster damaged around redundant sockets (photo 347)
SC348	Third floor	Meeting room 2	Ceiling	Fair condition
SC349	Third floor	Meeting room 2	Windows	Sealed units misted in two panes (photo 349)
SC350	Third floor	Meeting room 2	Doors	Door closer leaking oil (photo 350)
SC351	Third floor	Meeting room 3	Floor	Screed exposed, minor cracking (photo 351)
SC352	Third floor	Meeting room 3	Walls	Minor hairline cracks above the door head (photo 352)
SC353	Third floor	Meeting room 3	Ceiling	Grid bent at the light fittings (photo 353)

Ref	Floor	Area	Element	Condition
SC354	Third floor	Meeting room 3	Windows	Seals perished on the north elevation (photo 354)
SC355	Third floor	Meeting room 3	Doors	Frame damaged at the latch side (photo 355)
SC356	Third floor	Kitchen	Floor	Vinyl lifting at two joints (photo 356)
SC357	Third floor	Kitchen	Walls	Plaster damaged around redundant sockets (photo 357)
SC358	Third floor	Kitchen	Ceiling	Ceiling tiles stained near the riser (photo 358)
SC359	Third floor	Kitchen	Windows	Fair condition
SC360	Third floor	Kitchen	Doors	Door closer leaking oil (photo 360)
SC361	Third floor	WC core A	Floor	Fair condition
SC362	Third floor	WC core A	Walls	Paint scuffed at low level (photo 362)
SC363	Third floor	WC core A	Ceiling	Grid bent at the light fittings (photo 363)
SC364	Third floor	WC core A	Windows	Sealed units misted in two panes (photo 364)
SC365	Third floor	WC core A	Doors	Vision panel cracked (photo 365)
SC366	Third floor	WC core B	Floor	Vinyl lifting at two joints (photo 366)
SC367	Third floor	WC core B	Walls	Fair condition
SC368	Third floor	WC core B	Ceiling	Exposed soffit, old fixings left in place (photo 368)
SC369	Third floor	WC core B	Windows	Fair condition
SC370	Third floor	WC core B	Doors	Door closer leaking oil (photo 370)
SC371	Third floor	Shower room	Floor	Carpet tiles worn at the entrance, staining near the doors (photo 371)
SC372	Third floor	Shower room	Walls	Minor hairline cracks above the door head (photo 372)
SC373	Third floor	Shower room	Ceiling	Exposed soffit, old fixings left in place (photo 373)
SC374	Third floor	Shower room	Windows	Ironmongery missing on one opening light (photo 374)
SC375	Third floor	Shower room	Doors	Fair condition
SC376	Third floor	Stair core 1	Floor	Raised floor panels rocking in three places (photo 376)
SC377	Third floor	Stair core 1	Walls	Damp staining below the window cill (photo 377)
SC378	Third floor	Stair core 1	Ceiling	Fair condition
SC379	Third floor	Stair core 1	Windows	Ironmongery missing on one opening light (photo 379)
SC380	Third floor	Stair core 1	Doors	Door binding on the floor finish (photo 380)
SC381	Third floor	Stair core 2	Floor	Vinyl lifting at two joints (photo 381)
SC382	Third floor	Stair core 2	Walls	Plaster damaged around redundant sockets (photo 382)
SC383	Third floor	Stair core 2	Ceiling	Grid bent at the light fittings (photo 383)
SC384	Third floor	Stair core 2	Windows	Ironmongery missing on one opening light (photo 384)
SC385	Third floor	Stair core 2	Doors	Frame damaged at the latch side (photo 385)
SC386	Third floor	Lift lobby	Floor	Fair condition
SC387	Third floor	Lift lobby	Walls	Fair condition

Ref	Floor	Area	Element	Condition
SC388	Third floor	Lift lobby	Ceiling	Exposed soffit, old fixings left in place (photo 388)
SC389	Third floor	Lift lobby	Windows	Cill boards chipped (photo 389)
SC390	Third floor	Lift lobby	Doors	Fair condition
SC391	Third floor	Riser 1	Floor	Screed exposed, minor cracking (photo 391)
SC392	Third floor	Riser 1	Walls	Plaster damaged around redundant sockets (photo 392)
SC393	Third floor	Riser 1	Ceiling	Grid bent at the light fittings (photo 393)
SC394	Third floor	Riser 1	Windows	Cill boards chipped (photo 394)
SC395	Third floor	Riser 1	Doors	Door binding on the floor finish (photo 395)
SC396	Third floor	Riser 2	Floor	Fair condition
SC397	Third floor	Riser 2	Walls	Paint scuffed at low level (photo 397)
SC398	Third floor	Riser 2	Ceiling	Grid bent at the light fittings (photo 398)
SC399	Third floor	Riser 2	Windows	Ironmongery missing on one opening light (photo 399)
SC400	Third floor	Riser 2	Doors	Fair condition

SCHEDULE 7 FORM OF COLLATERAL WARRANTY

THIS DEED is made between (1) the Contractor or consultant giving the warranty (the "Warrantor"), (2) BRIGHTQUAY STUDIOS LIMITED (the "Beneficiary") and (3) FERNHOLLOW PROPERTIES LIMITED (the "Employer").

1. The Warrantor warrants to the Beneficiary that it has performed and will continue to perform its obligations under its appointment or building contract with the Employer, and that it has exercised and will continue to exercise all the reasonable skill, care and diligence to be expected of a properly qualified and competent member of its profession or trade experienced in carrying out works or services of a similar size, scope and complexity.

2. The Warrantor warrants that it has not specified or used, and will not specify or use, any materials which are generally accepted in the construction industry at the time of specification or use as deleterious to health and safety or to the durability of buildings in the particular circumstances in which they are used.

3. The Warrantor shall have no greater liability to the Beneficiary under this deed than it would have had if the Beneficiary had been named as a joint employer with the Employer under the appointment or building contract.

4. The Warrantor may rely on any limit of liability or other term of the appointment or building contract, and may raise the equivalent rights of defence as it would have had if the Beneficiary had been named as a joint employer.

5. The Warrantor shall maintain professional indemnity insurance with a limit of indemnity of not less than five million pounds (£5,000,000) for each and every claim for a period of twelve years from the date of practical completion of the works, provided that such insurance remains available at commercially reasonable rates.

6. The Beneficiary shall have an irrevocable, royalty-free, non-exclusive licence to copy and use the drawings, specifications and other documents prepared by or on behalf of the Warrantor for any purpose related to the Property, including its use, maintenance, repair, letting and reinstatement.

7. The Beneficiary may assign the benefit of this deed without the consent of the Warrantor on two occasions only, by way of absolute legal assignment, to a person who takes an assignment of the Beneficiary's interest in the Property.

8. No action or proceedings for any breach of this deed shall be commenced against the Warrantor after the expiry of twelve years from the date of practical completion of the works.

9. Any notice to be given under this deed shall be in writing and delivered by hand or sent by recorded delivery to the registered office of the recipient.

10. This deed and any dispute or claim arising out of or in connection with it shall be governed by the law of England and Wales, and the courts of England and Wales shall have exclusive jurisdiction.

EXECUTION

Executed as a deed by FERNHOLLOW PROPERTIES LIMITED acting by a director, in the presence of a witness:

Director .....

Witness signature .....

Witness name .....

Witness address .....

Executed as a deed by BRIGHTQUAY STUDIOS LIMITED acting by a director, in the presence of a witness:

Director .....

Witness signature .....

Witness name .....

Witness address .....

Executed as a deed by GARROW HOLDINGS PLC acting by a director, in the presence of a witness:

Director .....

Witness signature .....

Witness name .....

Witness address .....