Hartwell Heating Services Ltd

7 Tanner Row, Ashby Vale, AV2 6HT. Gas safe registered engineers.

Facilities Department
Larkfield Estates Ltd
River Court, 3 Weir Lane
Ashby Vale AV1 2RC

21 October 2026

Our reference: HHS/RC/2026-114

Boiler inspection, River Court: annual service report

Dear Mr Ashworth,

Our engineer, Martin Clegg, serviced the two gas boilers in the River Court plant room on 14 October 2026. Boiler 1 is in good condition. Boiler 2 is safe to use, but two findings need action before the next heating season.

Findings

1. The expansion vessel of boiler 2 has lost pressure (0.4 bar against 1.0 bar required). We recommend replacing the expansion vessel within three months.

2. The flue gas analysis of boiler 2 shows a carbon monoxide reading of 62 ppm. This is below the action level of 100 ppm, but higher than last year, and the burner should be cleaned at the next visit.

Measurements

Reading	Boiler 1	Boiler 2	Limit
Carbon monoxide (ppm)	18	62	100
CO/CO2 ratio	0.0011	0.0039	0.0080
Combustion efficiency (%)	91.2	88.4	-
System pressure (bar)	1.4	1.3	1.0 - 2.0
Expansion vessel (bar)	1.0	0.4	1.0

Next service

The next annual service of both boilers is due by 14 March 2027. The quotation for the expansion vessel replacement is GBP 1,240 excluding VAT, parts and labour included.

Yours sincerely,

Helen Marsh
Service Manager, Hartwell Heating Services Ltd