Mechanical interface

Mechanical interface of the Conveyor Belt

Mechanical Overview

This chapter introduces the mechanical interfaces of the Conveyor Belt which is composed of:

- IR sensor
- Vision workspace landmarks
- End stopper
- Slope
- Mechanical links

The environment is illustrate as follow.

3D view of the Conveyor Belt

Installation

The Conveyor Belt must be placed on a table or flat surface that is larger than the surface of its support unit to prevent the product from falling.

Mechanical Connectors

The conveyor's ecosystem is easy and quick to install thanks to magnetic mechanical connectors.

- Magnetic mechanical connectors give you a stable and precise environment by connecting your Conveyor Belt and your Ned2. You will need to screw the first part on the robot and then link the robot to the conveyor with the magnetic mechanical connectors, as illustrated on the following pictures.

- The slope allows the robot to perform sequences in a rough environment while ensuring stability thanks to the magnetic connection to the conveyor. You can also use the slope freely.

- Vision workspace landmarks are also easy to use and easy to move. They allow you to work on the entire length of the conveyor.

Infrared sensor (IR) setup

To mount it with the Conveyor Belt, please follow the steps below:

Step 1. Screw the first ring

Step 2. Add the sensor support

Step 3. Screw the second ring

Step 4. Fix the IR sensor on the conveyor with the magnetic support.

Made with Docsie.io