

MEASUREMENT CHART — POINTS OF MEASURE

ST-2815 · NK-90455 · Rev 2 · all measurements in cm, garment measured flat

Style	ST-2815	Issued	2026-09-05
Description	ladies' brushed-fleece full-zip hoodie	Unit	cm
Sample stage	PP and bulk	Grade rule	as printed per size — do not interpolate

POM	Point of measure	XS	S	M	L	XL	Tol ±
A	Chest width, 1 cm below armhole	51.0	53.5	56.0	58.5	61.0	1.5
B	Body length from HPS	62.0	64.0	66.0	68.0	70.0	1.0
C	Across shoulder	40.5	42.0	43.5	45.0	46.5	1.0
D	Sleeve length from CB	78.0	80.0	82.0	84.0	86.0	1.0
E	Armhole straight	22.5	23.5	24.5	25.5	26.5	0.8
F	Cuff width relaxed	8.5	8.5	9.0	9.0	9.5	0.5
G	Bottom rib width relaxed	38.0	40.5	43.0	45.5	48.0	1.5
H	Hood height	35.0	35.5	36.0	36.5	37.0	0.8
I	Hood width at base	24.0	24.5	25.0	25.5	26.0	0.5
J	Pocket opening	15.5	16.0	16.5	17.0	17.5	0.5

How these are taken

- A — lay flat, measure 1 cm below the armhole seam, edge to edge.
- B — from the high point of shoulder straight down to the bottom edge of the rib.
- C — seam to seam across the back.
- D — from the centre back neck along the shoulder and down the sleeve to the cuff edge.
- E — straight from the shoulder point to the underarm point.
- F, G — relaxed, not stretched. Allow the rib to settle 10 seconds before measuring.
- H — from the top of the hood seam to the bottom of the hood opening.
- J — along the pocket opening edge, one side.

Tolerance is symmetric unless stated otherwise. A measurement outside tolerance on any graded point is a major defect at final inspection. Measure a minimum of 3 pieces per size per colour at inline and 8 pieces per size at final.

TEST FIXTURE — this document was generated for FabricXAI platform testing. Nordkap Apparel AB and every counterparty named here are invented. It is not real business paper and carries no legal meaning.