

STANDARD OPERATING PROCEDURE			
SOP No.:	SOP-QC-054-00	Effective Date:	01.08.2017
Supersedes:	Nil	Next Review Date:	31.07.2020
Department:	Quality Control	Page:	1 of 2

TITLE: OPERATION AND CALIBRATION OF HOT AIR OVEN

1.0 PURPOSE:

To provide the procedure Operation and calibration of Hot Air Oven.

2.0 SCOPE:

This procedure is applicable to the operation and calibration of Hot air Oven at Discovery Laboratories Pvt. Ltd.

Make : Bio-Techniques India

ID No. : DIPL/QC/INS/HAO/002

Serial No. : 172524

3.0 RESPONSIBILITY:

3.1 Analyst-QC is responsible to follow this SOP.

- 3.2 Head-QC/Designee is responsible for ensuring implementation of this SOP.
- 3.3 Head-QA/Designee is responsible for monitoring overall compliance of this SOP.

4.0 **DEFINITIONS**:

Nil.

5.0 PROCEDURE:

5.1 Precaution

- 5.1.1 Ensure that the power supply to the equipment is switch off before cleaning.
- 5.1.2 Check that the instrument and surroundings are clean, if not, clean with a soft cloth with duster.
- 5.1.3 Clean the equipment with a clean dry cloth every day.

5.2 **Operation:**

- 5.2.1 Ensure that the instrument is properly connected to the power supply.
- 5.2.2 Switch ON the main switch.
- 5.2.3 Main indicator red button will glow.
- 5.2.4 Ensure that the set knobs & thermostat knobs are in zero position.
- 5.2.5 Set the temperature by using the digital temperature control.

	Prepared by	Reviewed by	Approved by
Sign & Date			
Name	S.Prasad	M.Seshugiri Rao	Ch.Mahendar Reddy
Department	Quality Control	Quality Control	Quality Assurance



STANDARD OPERATING PROCEDURE			
SOP No.:	SOP-QC-054-00	Effective Date:	01.08.2017
Supersedes:	Nil	Next Review Date:	31.07.2020
Department:	Quality Control	Page:	2 of 2

TITLE: OPERATION AND CALIBRATION OF HOT AIR OVEN

- 5.2.6 Press the set button and use the coarse and fine buttons for small increments of temperature.
- 5.2.7 Switch ON the fan switch button.
- 5.2.8 Let the temperature come to desired temperature and counter check using a thermometer or Digital temperature indicator.
- 5.2.9 Keep the test samples and close the door of the oven properly and tightly.
- 5.2.10 Switch OFF the oven after completion of testing.
- 5.2.11 In case of any break down, inform the defect to Manager-QC
- 5.2.12 Check the performance after rectification.

5.3 Calibration: Frequency: Once in 3 Months.

- 5.3.1 Set the oven to 100°C, wait till the set temperature is reached
- 5.3.2 Put the standard thermometer or Digital temperature indicator in right side of hot air oven, close the oven door.
- 5.3.3 Allow the temperature to equilibrate for 30 minutes.
- 5.3.4 Set the following temperature : 50°C, 100°C, 150°C and 200°C
- 5.3.5 Observe the temperature shown by the thermometer or Digital temperature indicator.
- 5.3.6 The temperature shall not differ by more than $\pm 2^{\circ}$ C
- 5.3.7 Record the temperature observed in calibration record of Hot air oven.

6.0 FORMATS / ANNEXURE(S):

6.1 Digital temperature indicator (HOT AIR OVEN) calibration : QC054-FM114

7.0 CHANGE HISTORY:

Revision No.	Effective Date	Details of Revision	Ref CCF No.
00	01.08.2017	New SOP introduced	CCF/GEN/17011

	Prepared by	Reviewed by	Approved by
Sign & Date			
Name	S.Prasad	M.Seshugiri Rao	Ch.Mahendar Reddy
Department	Quality Control	Quality Control	Quality Assurance