shifthelper_smartfact_mockup_test/test_sheet.m...

M BiasChannelsInOverCurrent

ContainerTooWarm

Branch master - shifthelper_smartfact_mockup_lest / test_sheet.md	□ fact-project / shifthelper_smartfact_mockup_test	
Find file		
Copy path		

66 lines (54 sloc) 3.19 KE

aneise Update test_sheet.md

Branch: master ~ | shifthelper_smartfact_mockup_test / test_sheet.md

1 contributor

Test Sheet D.Neise A.M. 2017 ~ 10h

shiftelan: 1.21-1 webinterface 1.0.1-5

46d9148 9 minutes ago

The following credentials are needed to conduct this test

- fact@gate: in order to start and stop smartfact
- cloudadmin@infra-1: in order to start and stop the shifthelper and edit the config file

Make sure you are fallback shifter (office phone A)

- Make sure you are SH expert (office phone B)
- V Prepare your logbook user account for being shilter (add telegram and mobile phone number) was Set up releasely
- Switch off the FACT++ program smartfact
- √ Start the st_test_one_by_one script, it takes over and updates the relevant files, so it looks like we are taking data.
- Make sure you have time to conduct this test without being disturbed for 1 or 2 hours
- W Remove the current shifter from the shift scheduler
- Kenter a "Startup" task for "right now" in the observation schedule
- Restart the SH, so it reads its config file.
- V wait for the SH to call you as an expert, since no shifter is in the schedule. $\sim 3:44~VTC$
- MEnter yourself as a shifter and acknowledge that alert.
- Do a Dummy Alert and wait ... the SH has to update its view of the shift scheduler, to realize you are on shift, Once it realizes you are on shift and you pressed the Dummy Alert within the last 3 minutes you should get a dummy alert call

- V start each test by pressing enter and wailing for Call, Telegram, Alert on the website:
- √ SmartFactUpToDate
- ✓ MAGICWeatherUpToDate
- ✓ MainJsStatusCheck
- WindSpeedCheck
- ✓ WindGustCheck
- V MedianCurrentCheck
- MaximumCurrentCheck

 RelativeCameraTemperatureCheck
- ✓ BiasNotOperatingDuringDataRun

Tear Down

✓ start the FACT++ program smartfact again

M make sure the SH_test_one_by_one script is not running anymore.

Vdo the shutdown checklist, just like you would normally during shutdown.

√ wait for the time of the shutdown to pass and add 10 minutes, expect a call, due to no shutdown checklist entry.

click the I am awake button and acknowledge the alert.

wait for the SH to detect that there is a shutdown but nowbody is awake call.

schedule a "Shuldown" Task in the observation schedule in 15minutes from now.

TriggerRateLowForTenMinutes ... need to wait 10 minutes

NoDimCirlServerAvailable

▼ DIMNetworkNotAvailable

BiasVoltageOnButNotCalibrated - DriveInErrorDuringDataRun

And not acknowledge for > 15" - fallback was

make sure you reset the SH expert in the SH config file make sure you reset the fallback shifter in the SH config file M make sure you reset todays shifter in the shift scheduler

restart the SH so it reads its config file.

Total Time ~ 4.54

2 of 2