IR-Opflow Flow Meters

IMPORTANT: READ INSTRUCTIONS THOROUGHLY BEFORE INSTALLING FLOW METER

1. Description

A. General

The IR-Opflow is an axial paddle wheel turbine type flow meter based on the Pelton wheel principle. This unique patented design makes the IR-Opflow a very accurate, repeatable, linear device. Not only is the IR-Opflow precise, but it is also a rugged, trouble-free flow meter, which can be used in a wide variety of industries including: medical, pharmaceutical, chemical processing, pulp & paper, semi-conductor, biotech, agriculture etc.

B. Principle of operation

Fluid flows through the meter, first passing through a helical nozzle, which causes flow to spiral, rotating in a helical pattern. The spiraling fluid then impacts on the flat blade rotor causing the rotor to spin. The rotor is designed to immediately develop a rotation-induced friction-free fluid bearing, thus eliminating any potential bearing wear. An infrared electro-optical transmitter and receiver are molded into the body of the meter along with a pair of miniature circuit boards, providing voltage

This design inherently bleeds off entrained gas, improving the accuracy of the meter. It also eliminates the need for flow straighteners or special lengths of inlet piping to stabilize turbulent flow.

stabilizers.*

2. Material Characteristics

A. Material of construction

Chemical name: Polyvinylidene Fluoride)

Trade name - Solef

All wetted parts of the IR-Opflow are PVDF, excluding the O-ring. Wetted parts include any part of the meter that will or could come in contact with the fluid.

List of wetted parts:

- 1. Barbed fittings 5. End caps
- 2. End caps
- 3. Flow meter body
- 4. Strainer
- 5. Rotor
- 6. Bearings
- 7. Helical nozzle (Viton O-ring seal)

B. Chemical Composition

Polyvinylidene Fluoride is a fluorpolymer consisting of three basic materials (carbon, hydrogen and fluorine)

C. Chemical Compatibility

For a complete list of compatible fluids contact JLC International, Inc.

D. Effects of Various Fluids

- Weak acids no effects
- Strong acids attacked by fuming sulfuric & nitric acids at high temperature
- Weak alkalis no effects
- Strong alkalis no effects
- Organic solvents Resistant to most. Slight attack by some. Imbrittled by some amines, keystone and esters. (Ref: Compass Corrosion Guide II)

^{*} Clear, transparent & translucent fluids; must transmit infrared light.

3. Operating Parameters

A. Temperature

Since the IR-Opflow has printed circuit boards molded into the body of the meter it is strongly recommended that 180°F not be exceeded. Exceeding 180°F can cause irreparable damage to the circuit boards.

B. Flow ranges

The IR-Opflow is available in six different sizes, which cover a flow range from 0.1 – 120 lpm (0.3 – 32 gpm)

Specific flow ranges

Type 1 0.1 - 2 lpm (.03 - 0.53 gpm)

Type 2 0.3 - 9 lpm (.08 - 2.38 gpm)

Type 3 0.5 - 15 lpm (.13 - 3.96 gpm)

Type 4 1.0 - 30 lpm (.26 - 7.93 gpm)

Type 5 2.5 – 75 lpm (.66 – 19.8 gpm)

Type 6 4.0 – 120 lpm (1.32 – 32 gpm)

Consult factory for specific applications requiring an extended flow range. Warning: Over range may permanently damage the flow meter.

C. Recommended viscosity

Range 1-5 cSt (w/o correction) The effects of changing viscosity on the IR-Opflow are the same as any other turbine flow meter. It is important to remember that a turbine meter is a viscosity dependent device, where as the viscosity increases the linearity of the flow meter will decrease. (Water like viscosities are ideally suited for use with the IR-Opflow) The IR-Opflow is factory calibrated with water.

Correction procedure for higher viscosity

For viscosities greater than 5 cSt consult the factory. The IR Opflow can be used for viscosities greater than 5 cSt. however, the K-factor (linearity) will change. This requires a recalibration of the IR Opflow at the known viscosity to determine the new K-Factor.

D. Filter Recommendations

Meter	Micron	Mesh
Type 1	35	400
Type 2	50	300
Type 3	100	80
Type 4	100	80
Type 5	100	80
Type 6	100	80

IR-Opflow sizes 2 – 6 are fitted with strainers* to help protect against dirt, fiber and other contaminants. Due to space restrictions it is not possible to fit size 1 with a strainer. Removal of the strainer will reduce pressure drop through the flow meter and may also change the linearity of the meter to solid contaminant, which could damage the meter. * The strainer is a 30 mesh filter / 550 micrometer. Cartridge models have no strainer.

E. Cleaning

1. Steam cleaning

Steam sterilization is not possible with IR-Opflow due to the high temperature of the steam. Steam sterilization will permanently damage the flow meter bearings and printed circuit boards.

2. Chemical cleaning

Chemical cleaning the IR-Opflow is permissible, provided the chemicals are compatible with PVDF (polyvinylidene fluoride).

F. Bi-directional flow

The IR-Opflow is designed to only provide fluid readings in the forward flow direction. Reverse flow will not unduly restrict fluid flow.

4. Silicone Treatment

Silicone treatment is standard for all types of the IR-Opflow series electronics.

5. Infrared Sensor

A. Supply voltage

5-12 Vdc or 8 - 24 Vdc. Do not exceed 12 / 24 Vdc. Doing so can cause overheating and eventual failure of all PC boards. Printed circuit boards are non-repairable.

B. Frequency output

- Square wave pulse, unscaled
- 2. Output impedance 75 ohms
- 3. Directly proportional to flow rate
- 4. Output dc frequency
- 5. Offset 0.64 volts
- 6. Peak voltage = Supply voltage 1.2 volts
- Peak to peak voltage = Supply voltage – 1.2 volts – 0.64 volts
- 8. Output signal cycle 66.7% (i.e. at 100Hz there is a 6 millisecond "on" time and a 4 millisecond "off" time)
- TTL/CMOS circuit compatibility. The IR-Opflow has an operational amplifier output, which has high input impedance and low output impedance.

C. Frequency Ranges *) for:

Model	Freq.(Hz)	K-Factor (1/I)
Type 1	60 - 1,20	36,000
Type 2	40 – 1,20	8,000
Type 3	27 – 800	3,200
Type 4	20 – 600	1,200
Type 5	18.75 – 5	562 450
Type 6	15 – 450	225

^{*)} Non cartridge models only

D. Cable requirements


- 1. 20 22 AWG (American Wire Gauge)
- 2. 4 conductor-shielded cable.

Note: Avoid influences of strong electromagnetic forces as they can damage components on the PC boards.

6. Installing the IR-Opflow

- Make sure the fluid is compatible with PVDF (polyvinylidene fluoride) and meets viscosity, pressure and temperature parameters of the IR-Opflow. The fluid must also meet filtration requirements as listed in 3D.
- Install the IR-Opflow in the fluid line with the arrow pointing in the direction of the flow.
- While installing the IR Opflow in the fluid line be careful not to over-torque the end caps (on hose-barbed flowmeters) or other fittings on the flowmeter. Due to the relatively soft composition of PVDF the body or threads can be permanently distorted.
- Attach wires to the readout display with the display and power off. Not only will this help to avoid a potential shock hazard, but it can also help prevent an error in hooking the flow meter to an incorrect 115 Vac supply.
- Connect digital display to power supply and enter scaling factors for both the rate and total. Follow the manufacturer's instructions for programming the digital display.
- The IR-Opflow is now ready for use.

Supply voltage and Signal Output Connections



JLC International Phone: 215-340-2650 Fax: 215-340-3670

jlcusa@jlcinternational.com www.jlcinternational.com