```
.MODEL SMALL
.STACK 100H
.DATA
a db 1,2,3,4,5
.CODE
MAIN PROC
  mov cx, 0
again:
  mov ah,1
  int 21h
  cmp al, 0Dh
  je store
  mov ah,0
  push ax
  inc cx
  jmp again
store:
  mov ah, 2
  mov dl, 0ah
  int 21h
  mov dl, 0dh
  int 21h
exit:
  pop bx
  cmp bx, 20h
  je skip
  cmp bx, 61h
  jl skip
  sub bx, 20h
skip:
  mov dx, bx
  mov ah, 2
  int 21h
  loop exit
```

;exit to DOS

MOV AX,4C00H INT 21H

MAIN ENDP END MAIN