

GRAPHICS TECHNOLOGY

James H. Earle

Texas A&M University



ADDISON-WESLEY PUBLISHING COMPANY

Reading, Massachusetts • "Menio Park, California • New York

Don Mills, Ontano • Wokingham, England • Amsterdam • Bonn

Sydney • Singapore • Tokyo • Mudne • San Juan • Aslan • Fans

Brief Contents

7	Introduction to Engineering and	18	Three-Dimensional Pictorials 367
	Technology 1	. 19	Points, Lines, and Planes 389
2	The Design Process 15	20	Primary Auxiliary Views in
3	Drawing Instruments 41		Descriptive Geometry 403
4	Lettering 61	21	Successive Auxiliary Views 429
5	Geometric Construction 69	22	Revolution 443
6	Orthographic Sketching 95	23	Vector Graphics 457
7	Orthographic Drawing with Instruments 113	24	Intersections and Developments 473
8	Auxiliary Views 141	25	Graphs 499
9	Sections 159	26	Nomography 515
	Screws, Fasteners, and Springs 177	27	Empirical Equations and Calculus 527
11	Gears and Cams 209	28	Pipe Drafting 541
12	Materials and Processes 223	29	Electric/Electronics Graphics 561
13	Dimensioning 241	30	The Computer in Design and
14	Tolerances 267		Graphics 583
15	Welding 301		Appendixes A-1
16	Working Drawings 311		Index I-1
17	Reproduction of Drawings 361		

Contents

1	Introduction to Engineering and	2.4	Design Worksheets 20
	Technology 1	2.5	Design Example: Exercise Bench 20
1.1	Introduction 1	2.6	Preliminary Ideas: Exercise Bench 2
1.2	Engineering Graphics 1	2.7	Refinement: Exercise Bench 24
1.3	Technological Advances 2	2.8	Analysis: Exercise Bench 25
1,4	The Technological and Design Team 3	2.9	Decision: Exercise Bench 27
1.5	Engineering Fields 6	2.10	Implementation: Exercise Bench 28
1.6	Aerospace Engineering 6	2.11	Design Problems 31
1.7	Agricultural Engineering 6		
1.8	Chemical Engineering 7	3	Drawing Instruments 41
1.9	Civil Engineering 8	3.1	Introduction 41
1.10	Electrical Engineering 9	3.2	Drafting Media 41
1.11	Industrial Engineering 10	3.3	Drafting Equipment 44
1.12	Mechanical Engineering 10	3.4	Lines 49
1.13	Mining and Metallurgical Engineering 11	3.5	Measurement 52
1.14	Nuclear Engineering 12	3.6	Presentation of Drawings 58
1.15	Petroleum Engineering 12	3.0	PROBLEMS 59
1.16	Drafting 13		PROBLEMS 39
	PROBLEMS 14		
		4	Lettering 61
2	The Davis Branch	4.1	Introduction 61
	The Design Process 15	4.2	Lettering Tools 61
1.5	Introduction 15	4.3	Guidelines 62
.2	Types of Design Problems 16	4.4	Freehand Gothic Lettering 63
3	The Design Process 18		DDCS FAR C

5	Geometric Construction 69	7.5	Three-View Drawings 116
5.1	Introduction 69	7.6	Arrangement of Views 116
5.2	Angles 69	7.7	Selection of Views 118
5.3	Polygons 70	7.8	Line Techniques 118
5.4	Circles 70	7.9	Point Numbering 119
5.5	Geometric Solids 71	7.10	Lines and Planes 119
5.6	Constructing Polygons 72	7.11	Views by Subtraction 120
5.7	Bisecting Lines and Angles 74	7.12	Laying Out Three-View Drawings 120
5.8	Revolution of Shapes 74	7.13	Two-View Drawings 122
5.9	Enlargement and Reduction of Shapes 75	7.14	One-View Drawings 122
5.10	Division of Lines 75	7.15	Simplified and Removed Views 122
5,11	Arcs 76	7.16	Partial Views 124
5.12	Parallel Lines 77	7.17	Curve Plotting 124
5.13	Tangents 77	7.18	Conventional Practices 124
5.14	Conic Sections 81	7.19	Conventional Intersections 126
5.15	Spirals 87	7,20	Fillets and Rounds 127
5,16	Helixes 87	7.21	Left-Hand and Right-Hand Views 130
	PROBLEMS 88	7.22	First Angle Projection 131
			PROBLEMS 132
6	Orthographic Sketching 95		
6.1	Introduction 95		
6.2	Shape Description 95		
6.3	Sketching Techniques 97	8	Auxiliary Views 141
6.4	Six-View Sketching 98	8.1	Introduction 141
6.5	Three-View Sketching 98	B.2	Folding-Line Theory 142
6.6	Circular Features 102	0.3	Auxiliary Views from the Top View 142
6.7	Oblique Pictorial Sketching 105	8.4	Rules of Auxillary View Construction 143
6.8	Isometric Pictorial Sketching 106	8.5	Auxiliary Views from the Top View: Application 143
	PROBLEMS 109	8.6	Auxiliary Views from the Front View 144
		8.7	Auxiliary Views from the Profile View 149
7	Orthographic Drawing with	8.8	Auxiliary Views of Curved Shapes 150
	Instruments 113	8.9	Partial Views 152
7.1	Introduction 113	8.10	Auxiliary Sections 152
7.2	Orthographic Projection 113	8.11	Secondary Auxiliary Views 152
7.3	Alphabet of Lines 115	8.12	Elliptical Features 153
7.4	Six-View Drawings 115	201022	PROBLEMS 154
13000	SANGENALISSON MARKED MAY		William Thomas Control

9	Sections 159	11.4	Worm Gears 214
9.1	Introduction 159	11.5	Cams 217
9.2	Basics of Sectioning 159		PROBLEMS 221
9.3	Sectioning Symbols 160		
9.4	Sectioning Assemblies of Parts 162	42	Materials and Processes 223
9.5	Full Sections 162	12	
9.6	Half Sections 164	12.1	Introduction 223 Commonly Used Metals 223
9.7	Half Views 165	12.2	Properties of Metals 226
9.8	Offset Sections 166	12.3	Forming Metal Shapes 227
9.9	Broken-Out Sections 166	12.4	
9.10	Revolved Sections 167	12.5	Machining Operations 232
9.11	Conventional Revolutions 168	12.6	Surface Finishing 239
9.12	Removed Sections 171	12.7	Plastics and Other Materials 240
9.13	Conventional Breaks 172		
	PROBLEMS 173	13	Dimensioning 241
		13.1	Introduction 241
10	Screws, Fasteners, and	13.2	Terminology 241
	Springs 177	13.3	Units of Measurement 242
10.1	Introduction 177	13.4	English/Metric Conversions 243
10.2	Threads 177	13.5	Duel Dimensioning 243
10.3	Drawing Threads 185	13.6	Metric Designation 243
10.4	Nuts and Bolts 190	13.7	Numeric and Symbolic
10.5	Screws 194	200	Dimensioning 244
10.6	Other Threaded Fasteners 197	13.8	Dimensioning Rules 246
10.7	Tapping a Hole 197	13.9	Dimensioning Other Features 253
8.01	Washers, Lock Washers, and Pins 198		Finished Surfaces 254
0.9	Pipe Threads and Fittings 199	1,100,000	Location Dimensions 255
0.10	Keys 200	12.17	Outline No.
0.11	Rivets 201	13.12	Outline Dimensioning 257
0.12	Springs 201		Machined Holes 259
	PROBLEMS 204		Chamlers 261
			Keyseats 261
1	Gears and Cams 209	13.16	Knurling 262
1.1	Introduction 209	13.17	Necks and Undercuts 262
1.2	Spur Gears 209	13.18	Tapers 263
1.3	Bevel Gears 212	13.19	Miscellaneous Notes 263
1000	2021 3000 202		PROBLEMS 264
			TOTAL LOS

14	Tolerances 267	16	Working Drawings 311
14.1	Introduction 267	16.1	Introduction 311
14.2	Tolerance Dimensions 267	16.2	Working Drawings as Legal
14.3	Mating Parts 268		Documents 311
14.4	Tolerancing: English Units 269	16.3	Dimensions and Units 312
14.5	Basic Hole System 270	16.4	Laying Out a Detail Drawing 315
14.6	Basic Shaft System 271	16.5	Notes and Other Information 317
14.7	Cylindrical Fits 271	16.6	Checking a Drawing 320
14.8	Tolerancing: Metric System 272	16.7	Drafter's Log 321
14.9	Chain Versus Datum-Plane	16.8	Assembly Drawings 322
	Dimensions 277	15.9	Freehand Working Drawings 325
14.10	Conical Tapers 278	16.10	Working Drawings for Forged
14.11	Tolerance Notes 278		Parts and Castings 325
14.12	General Tolerances— Metric Units 278		PROBLEMS 326
14.13	Geometric Tolerances 280		
14.14	Rules for Tolerancing 283	17	Reproduction of Drawings 361
14.15	Cylindrical Datum Features 284	17.1	Introduction 361
14.16	Location Tolerancing 286	17.2	Types of Reproduction 361
14.17	Form Tolerancing 289	57.3	Assembling Drawing Sets 364
14.18	Profile Tolerancing 290	17.4	Transmittal of Drawings 365
14.19	Orientation Tolerancing 291		
14.20	Runout Tolerancing 292	18	Three-Dimensional
14.21	Surface Texture 293		Pictorials 367
	PROBLEMS 297	16.1	Introduction 367
		18.2	Oblique Drawings 368
		18.3	Oblique Projection Theory 374
15	Welding 301	18.4	Isometric Pictorials 374
15.1	Introduction 301	18.5	Isometric Drawings 376
15.2	Welding Processes 301	18.6	Technical Illustration 383
15.3	Weld Joints and Welds 303	18.7	Axonometric Projection 386
15.4	Welding Symbols 304		PROBLEMS 387
15.5	Application of Symbols 305		
15.6	Surface Contouring 308	19	Points, Lines, and Planes 389
15.7	Brazing 309	19.1	Introduction 389
15.8	Soft Soldering 309	19.2	Projection of Points 390
	PROBLEMS 310	19.3	Lines 391

		21.10	Angular Distance to a Line 437
19.4	Visibility 393	21.11	Angle Between a Line and a pu
19.5		21.11	Fidire Michigan
19.6	Parallelism 397	21.12	Angle Between a Line and a Plane: Line Method 438
19.7			PROBLEMS 440
	PROBLEMS 400		
20	Primary Auxiliary Views in	22	Revolution 443
	Descriptive Geometry 403	22.1	Introduction 443
20.1	Introduction 403	22.2	True-Length Lines 443
20.2		22.3	Angles with a Line and Principal Planes 445
2010	Planes 405	22.4	True Size of a Plane 445
20.4	Sloping Lines 406	22.5	Angle Between Planes 447
20.5	Bearings and Azimuths of Lines 408	22.6	Determining Direction 448
20.6	Contour Maps and Profiles 409	22.7	Revolution About an Axis 450
20.7	Plan-Profiles 411	22.8	A Line at a Specified Angle with Two
20.8	Edge Views of Planes 413	-	Principal Planes 453
20.9	Planes and Lines 414		PROBLEMS 454
20.10	Sloping Planes 416		
20.11	Ore-Vein Applications 418	22	Vector Craphics
20.12	Intersections Between Planes 423	23	Vector Graphics 457
	PROBLEMS 423	23.1	Introduction 457
		23.2	Definitions 457
21	Successive Auxiliary Views 429	23.3	Coplanar, Concurrent Force Systems 458
21.1	Introduction 429	23.4	Noncoplanar, Concurrent Force
21.2	Point View of a Line 429		Systems 459
21.3	Dihedral Angles 430	23.5	Forces in Equilibrium 461
21.4	True Size of a Plane 431	23.6	Coplanar Truss Analysis 462
21.5	Shortest Distance from a Point to a Line: Line Method 432	23.7	Noncoplanar Vector Analysis 464
21.6	Shortest Distance Between Skewed	23.8	Resultant of Parallel, Nonconcurrent Forces 467
21.7	Lines: Line Method 433		PROBLEMS 469
	Shortest Distance Between Skewed Lines: Plane Method 434		Caran
21.8	Shortest Level Distance Between Skewed Lines 435	24	Intersections and
21.9	Shortest Grade Distance Between	24.1	Developments 473
	Skewed Lines 436	24.2	Introduction 473
		W. A. I.	Intersections of Lines and Dianes 473

24.3	Intersections Between Prisms 475	26.4	Alignment Graphs with Three
24.4	Intersections Between Planes and		Variables 519
	Cylinders 477	26.5	Parallel Scale Graphs 519
24.5	Intersections Between Cylinders and Prisms 478	26.6	N or Z Nomographs 521 PROBLEMS 524
24.6	Intersections Between Two Cylinders 478		
24.7	Intersections Between Planes and Cones 481		
24.8	Intersections Between Cones and Prisms 482	27	Empirical Equations and Calculus 527
24.9	Intersections Between Prisms and	27.1	Introduction 527
	Pyramids 484	27.2	Curve Equations 527
24.10	Principles of Developments 485	27.3	The Linear Equation: Y = MX + B 529
24.11	Development of Rectangular	27.4	The Power Equation: Y = 8X" 529
	Prisms 486	27.5	The Exponential Equation: Y = BM* 530
24.12	Development of Oblique Prisms 489	27.6	Graphical Calculus 532
24.13	Development of Cylinders 490	27.7	Graphical Differentiation 532
24.14	Development of Oblique Cylinders 490	27.8	Graphical Integration 536
24,15	Development of Pyramids 491		PROBLEMS 538
24.16	Development of Cones 493		
24.17	Development of Transition Pieces 495		
	PROBLEMS 496	100	
		28	Pipe Drafting 541
25	Graphs 499	28,1	Introduction 541
		28.2	Welded and Seamless Steel Pipe 541
25.1	Introduction 499	28.3	Cast-Iron Pipe 542
25.2	Ple Graphs 500	28.4	Copper, Brass, and Bronze Piping 543
25.3	Bar Graphs 501	28.5	Miscellaneous Pipes 543
25.4	Linear Coordinate Graphs 502	28.6	Pipe Joints 543
25.5	Semilogarithmic Coordinate Graphs 508	28.7	Pipe Fittings 544
25.6	Polar Graphs 510	28.8	Screwed Fittings 545
25.7	Schematics 510	28.9	Flanged Fittings 545
23.5	PROBLEMS 511	28.10	Welded Fittings 545
	PRODUCENTS 311	28.11	Valves 547
		28.12	Fittings in Orthographic Views 549
26	Nomography 515	28.13	Piping Systems in Pictorial 551
26.1	Introduction 515	28.14	Dimensioned Isometrics 551
26.2	Alignment Graph Scales 515	28,15	Summary 552
26.3	Concurrent Scales 517		PROBLEMS 558

	The second secon	30.4	Hardware Systems 200
29	Electric/Electronics Graphics 561	30.5	Introduction to Software 589
29.1	Introduction 561	30.5	An Example Session 591
29.2	Types of Diagrams 561	30.7	Introduction to 2D Drawing 593
29.3	Schematic Diagram Connecting Symbols 563	30.8	Basic Operations and Commands 593 Drawing Lines 598
29.4	Graphic Symbols 565	30.9	Drawing Circles 599
29.5	Terminals 568	30,10	Drawing Fillets and Rounds 599
29.6	Separation of Parts 571	30.11	
29.7	Reference Designations 573	30.12	Text and Numerals 599
29.8	Numerical Units of Function 574	30.13	Zooming and Panning 600
29.9	Functional Identification of Parts 575	30.14	MOVE and COPY 601
29.10	Printed Circuits 575	30.15	Dimensioning 601
29.11	Shortcut Symbols 576	30.16	Introduction to 3D Graphics 603
29.12	Installation Drawings 576	30.17	3D Drawing: Wire Diagrams 604
	PROBLEMS 578	30.18	Introduction to Solid Modeling 605
	THE PARTY OF THE P	30.19	An Example of Solid Modeling 606
30	The Computer in Design and Graphics 583	30.20	Advanced Applications 608
30.1	Introduction 583		Appendixes A-1
30.2	Terminology of Computer-Aided Design 583		Appendixes A-1
30.3	Computer-Aided Design/ Computer-Aided Manufacturing 585		Index I-1