STATISTICAL QUALITY

CONTROL

FIFTH EDITION

Eugene L. Grant

Richard S. Leavenworth

International Student Edition

STATISTICAL QUALITY CONTROL

Fifth Edition

Department of Computer Science UNIVERSITY OF KARACHI 23.10.94

SEMINAR COMPUTER SCIENCE Stanford University Department of Computer Science

Professor of Industrial and Systems Engineering University of Florida

UNIVERSITY OF KARACHI With Countingnis of

Machine Book Ca

Room Rex America

Abdullah Francis Road,

Karachi-3

INTERNATIONAL STUDENT EDITION

McGRAW-HILL KOGAKUSHA, LTD.

Tokyo Auckland Bogota Guatemala Hamburg Johannesburg Lisbon London Madrid Mexico New Delhi Panama

	List of Examples Preface	xi xiii
1	Introduction	
Part 1	Process Control	
2	Why the Control Chart Works; Some	
	Statistical Concepts	33
3	Why the Control Chart Works; Some Examples	75
4	Directions for Simple \bar{X} and R Charts	116
5	Rational Subgrouping; Analyzing and	
	Controlling Variation	152
6	Some Fundamentals of the Theory of Probability	170
7	The Control Chart for Fraction Rejected	221
8	The Control Chart for Nonconformities	254
9	Some Special Process Control Procedures	276
10	Some Aspects of Specifications and Tolerances	317
11	Some Aspects of the Relationship between	
	Control Charts and Certain Other	247
	Statistical Techniques	347
Part 2	Acceptance Sampling	
12	Some Fundamental Concepts in Acceptance	250
ME BOOK	Sampling	359
13	The Dodge-Romig System for Lot-by-Lot	400
	Acceptance Sampling by Attributes	390
	THE RESERVE THE PARTY OF THE PA	-11

	14	AUL System for Lot by Lot Assentance	
	15	Pank by Allinning (ABC STD 105)	
	Hi.	The Plans for Lot by Lot Acceptance	412
	16	Pring by Attributes	16.00
	17	Prance Inspection for Continuous Production	447
		Acceptance Sampling by Variables	475
	18	Some Aspects of Life Testing and Reliability	492
			534
art	3	Some Related Topics	
	-	Topics	_
	19	Some Economic Aspects of Quality Decisions	579
	20	Demonstrating the Operation of Systems of	3.30
		Chance Causes	599
	21	The Widespread Usefulness of Control Charts and	
		Acceptance Sampling Procedures	605
		Appendixes	
	1	Glossary of Symbols	615
	2	Bibliography	621
	3	Tables	627
		A Area under the Normal Curve	628
		B Factors for Estimating σ' from \tilde{R} or $\tilde{\sigma}$	630
		C Factors for Determining from R the 3-Sigma Control Limits	
		for \bar{X} and R Charts	631
		D Factor for Determining from ō the 3-Sigma Control Limits	
		for \bar{X} and σ Charts	632
		E Factors for Determining from σ' the 3-Sigma Control Limits	
		for \bar{X} , R , and σ Charts	633
		F 3-Sigma Control Limits for Control Charts for Per Cent	-
		Rejected	634
		G Summation of Terms of Poisson's Exponential Binomial	***
		Limit	636
		H Logarithms of Factorials	641
		J Logarithms of Numbers	646
		K Sample Size Code Letters—MIL-STD-105D (ABC Standard) L Moster Table for Normal Inspection (Single Sampling)	040
		L Master Table for Normal Inspection (Single Sampling)— MIL-STD-105D (ABC Standard)	649
		M Master Table for Tightened Inspection (Single Sampling)—	
		MIL-STD-105D (ABC Standard)	650

CONTENTS IN

		TOTAL STREET,
P	Master Table for Tightened Inspection (Double Sampling)— MIL-STD-105D (ABC Standard)	
Q	Master Table for Reduced Inspection (Double 8	653
R	Master Table for Normal Inspection (Multiple Co. 1)	654
	Master Table for Tightened Inspection (Multiple Communication)	655
T	Master Table for Reduced Inspection (Multiple Communication)	657
U	MIL-STD-105D (ABC Standard) Average Outgoing Quality Limit Factors for Normal	659
	Inspection (Single Sampling)—MIL-STD-105D (ABC Standard)	
V	Average Outgoing Quality Limit Factors for Tightened Inspection (Single Sampling)—MIL-STD-105D	661
W	(ABC Standard) Limit Numbers for Reduced Inspection—MIL-STD-105D (ABC Standard)	662
X		663
Y	of the Acceptance Sampling by Variables	664
Z		666 668
	Index	669

LIST OF EXAMPLES

1-1	A and R Charts. Experimental Control Charts for Process Control	8
1-2		14
1-3	Weakness of a Common Acceptance Sampling Scheme	20
2-1		39
3-1	And the late of th	93
3-2	Shift in Quality Level of Steel Castings	95
3-3	Use of & Chart to Prevent Too-Frequent Changes in Process Centering	107
4-1	Use of Control Charts by a Purchaser to Help a Vendor Improve His	
	Process	131
4-2	An Unsound Proposal for Sorting Product into Classes	134
4-3	Milling a Slot in an Aircraft Terminal Block. An Example to Illustrate the	130
	Steps in the Use of \bar{X} and R Charts on a Manufacturing Operation	138
5-1	Setting of Thermostatic Controls. Compensation for the Differences between	
	Operators	158
5-2	Thickness of Pads on Half-Ring Engine Mount. An Example in which	
	Subgroups Were Taken in a Way that Made Evidence of Lack of Control	160
	Have No Practical Value	160
5-3	Deanner Canability Study of Glass Stresses in Glass-to-Wire Scal	104
7-1	Illustration of Calculations Necessary for Control Chart for Fraction	228
		220
7-2	An Illustration of the Selection of Quality Characteristics for Charts for	234
	Fraction Rejected	257
8-1		264
8-2	A Control Chart for Nonconformities per Unit with Variable Subgroup Size	
9-1	A Control Chart for Nonconformities per Cinital Achine Setting When a Trend Is Expected in the Determining the Initial Machine Setting When a Trend Is Expected in the	298
-	Value of a Dimension	
9-2	Value of a Dimension Process Control by np Chart Based on Gage Tolerances That Are Tighter	303
7-4	e Pentine Tolerances	323
	Establishment of Tolerance Limits by Pilot Runs Establishment of Tolerance Limits by Pilot Runs Establishment of Tolerance Limits by Pilot Runs	326
0-1	Establishment of Tolerance Limits by Phot Runs Tolerances at Intermediate Stages in Manufacturing Electrical Cable Tolerances at Intermediate Stages in Manufacturing Electrical Cable Tolerances at Intermediate Stages in Manufacturing Electrical Cable	
0-2	The state of the statistical regions	328
0-3	An Illustration of the Statistical Dimensions, Tolerances, and Fits and Clearances	
	Dimensions, Tolerans	wi