LANDING GEAR & HYDRAULIC COMPONENT REPAIRS

All Maintenance Manual Repairs WESTWIND

- MAIN LANDING GEAR UPPER BODY
- SCISSOR, LOWER LH & UPPER RH / SCISSOR, UPPER LH & LOWER RH
- POWER BRAKE VALVE ASSEMBLY
- THERMAL RELIEF VALVE
- GEAR SELECTOR VALVE
- HYDRAULIC FUSE
- NLG ACTUATOR
- MLG ACTUATOR
- NOSE GEAR STEERING CYLINDER
- SOLENOID VALVE
- CENTERING SPRING
- STEERING VALVE ASSEMBLY
- MAIN LANDING GEAR ROD
- OUTER STRUT
- LANDING GEAR INNER BODY
- FORK/ROD & AXLE ASSEMBLY
- THRUST REVERSER ACTUATOR
- WESTWIND COMPONENT REPAIR & OH list


01/22/13



253505-501 / 253505-502 MAIN LANDING GEAR UPPER BODY

OVERHAUL CONSISTS OF:

- **NDT**
- Repair diameters as necessary
- Replacing bushings as necessary
- **Paint**



OVERHAUL

Repair Dia A

Repair Dia B

Repair Dia C

Repair Dia D

Repair Dia E1

Repair Dia E2

Repair Dia F1

Repair Dia F2

Lower Bearing Bore

(Clip Ring Groove Area)




INSPECTION FEES APPLY

405.350.2100 405.350.7600 F

253511-1 / 253512-1 SCISSOR, LOWER LH & UPPER RH SCISSOR, UPPER LH & LOWER RH

OVERHAUL CONSISTS OF:

- Clean and inspect
- Replace bushings as necessary
- Paint



OPTIONS

OVERHAUL

INSPECTION FEES APPLY

713001-501 / 5713001 / 5713001-501 117W50 / 117W50-1 / 4713074 POWER BRAKE VALVE ASSEMBLY

OVERHAUL CONSISTS OF:

- Inspect and repair housing and components
- Restore bores as necessary
- Repair and / or install new components as necessary
- Assembling with new seals and test to more stringent requirements than OEM



OPTIONS

OVERHAUL

INSPECTION FEES APPLY

713011 / 713011-501 / 713554-501 3713011 / 3713554 / 1713554 / 13713554-501 THERMAL RELIEF VALVE

OVERHAUL CONSISTS OF:

- Inspect and repair housing as necessary
- Repair or replace components as necessary
- Assemble with new seals
- Test / Adjust



OPTIONS OVERHAUL

INSPECTION FEES APPLY

713025 / 4713025 713025-1 / 713025-501 / 713553-501 CEAR SELECTOR VALVE

OVERHAUL CONSISTS OF:

- Clean and inspect
- Replace O-rings
- Place poppets as necessary
- Replace defective parts
- Reseal
- Test



OPTIONS OVERHAUL

INSPECTION FEES APPLY



713047A / G831-4-5 HYDRAULIC FUSE

OVERHAUL CONSISTS OF:

- Clean and inspect
- Modify To "A" Status, if needed
- Replace defective parts
- Reseal
- Test



OPTIONS OVERHAUL


INSPECTION FEES APPLY



713059-505 **NLG ACTUATOR**

OVERHAUL CONSISTS OF:

- Inspect and repair or replace components as necessary
- Restoring piston / shaft assembly to new dimensions if necessary
- Remove and treat corrosion
- Installing all new seals
- Testing to more stringent requirements than the aircraft maintenance manual



OPTIONS OVERHAUL

INSPECTION FEES APPLY


405.350.2100 405.350.7600 F



5713061-503 / 713061-505 / 4713028 4713028-501 MLG ACTUATOR

OVERHAUL CONSISTS OF:

- Inspect and repair or replace components as necessary
- Restoring piston / shaft assembly to new dimensions if necessary
- Remove and treat corrosion
- Installing all new seals
- Testing to more stringent requirements than the aircraft maintenance manual



OPTIONS OVERHAUL

INSPECTION FEES APPLY

713096 Series / 4713096 Series NOSE GEAR STEERING CYLINDER

OVERHAUL CONSISTS OF:

- Disassembling, inspecting & replacing or repairing components as necessary
- Restoring piston / shaft assembly to new dimensions if necessary
- Installing all new seals
- Testing to more stringent requirements than the aircraft maintenance manual



OPTIONS OVERHAUL

INSPECTION FEES APPLY

783164 Series / 783686 Series V20600 Series SOLENOID VALVE

REPAIR CONSISTS OF:

- Inspect and repair components as necessary
- Test



OPTIONS REPAIR

INSPECTION FEES APPLY

EA1699-1/EA1699-501/EA1699-503 EA1699-505/2235.0000.000 CENTERING SPRING

OVERHAUL CONSISTS OF:

- Inspect and repair or replace components as necessary
- Test



OPTIONS OVERHAUL

INSPECTION FEES APPLY

EA1801-2 STEERING VALVE ASSEMBLY

OVERHAUL CONSISTS OF:

- Inspect and repair or replace components as necessary
- Assemble with new seals
- Test



OPTIONS OVERHAUL

INSPECTION FEES APPLY



ED12910-2 MAIN LANDING GEAR ROD

OVERHAUL CONSISTS OF:

- Inspect
- NDT
- Restore ID & OD as necessary
- Restore black oxide coating



OPTIONS OVERHAUL

INSPECTION FEES APPLY




NDT

Paint

C.E. PAGE AIRPORT (KRCE) 1701A N. CIMARRON RD **YUKON OK 73099** 405.350.2100 405.350.7600 F WWW.LEGACY-AVIATION.COM

ES12854-1 / ES12854-501 **OUTER STRUT**



OPTIONS OVERHAUL

Repair Dia A

Repair Dia C

Repair Dia D

Repair Dia E

Repair Dia F

(Drag Brace Link Attach Point – Not Shown)

Repair Dia G

Repair Door Bellcrank Bolt Holes

Replace Trunion Bushings



Diameter G (2 places)

Trunnion Pin **Bushings** (2 places)

INSPECTION FEES APPLY

Diameter A


01/22/13 15

LEGACY

AVIATION SERVICES INC.

C.E. PAGE AIRPORT (KRCE) 1701A N. CIMARRON RD YUKON OK 73099 405.350.2100 405.350.7600 F WWW.LEGACY-AVIATION.COM

ES12858-501 LANDING GEAR INNER BODY



OPTIONS

OVERHAUL

Repair Dia I

Repair Dia E

Repair Dia K

Repair Dia L

Repair Dia.'s A, C

& O-Ring Groove



INSPECTION FEES APPLY



ES12908-503 / -504 910.003.53 / .54 FORK/ROD & AXLE ASSEMBLY



OVERHAUL CONSISTS OF:

- Disassemble
- NDT components
- Repair or replace components as necessary
- Remove & treat minor corrosion
- Reassemble
- Prime & paint per customer requirements

OPTIONS OVERHAUL

Replace Axle Replace Rod

INSPECTION FEES APPLY

F10A5SCH203-1 F10A5SCH203-3 1211164-001 THRUST REVERSER ACTUATOR

OVERHAUL CONSISTS OF:

- Inspect and repair or replace components as necessary
- Modify from -1 to -3 configuration, if necessary
- Assemble with new seals
- Test



OPTIONS

OVERHAUL MODIFY -1 to -3

INSPECTION FEES APPLY



LEGACY

AVIATION SERVICES INC.

C.E. PAGE AIRPORT (KRCE) 1701A N. CIMARRON RD YUKON OK 73099 405.350.2100 405.350.7600 F WWW.LEGACY-AVIATION.COM

Part Number	Description	Capabilities Available
253505-501, -502	Main Landing Gear Upper Body	Overhaul / Repair
253511-1	Lower LH & Upper RH Scissor	Overhaul
253512-1	Upper LH & Lower RH Scissor	Overhaul
713001-501 / 5713001, -501 117W50, -1 4713074	Power Brake Valve Assembly	Overhaul
187W64 / 3400 / 400156 713011, -501 / 3713011, -1, -501 713554-501 / 3713554, -1, -501 1713554 / 13713554-501	Thermal Relief Valve	Overhaul
AV14A3128 Series 713025, -1, -501 / 4713025 713553-501	Gear Selector Valve	Overhaul
713047A / G831-4-5	Hydraulic Fuse	Overhaul / Exchange
713059-505	NLG Actuator	Overhaul
5713061-503 713061-505 4713028, -501	MLG Actuator	Overhaul
713096 Series 4713096 Series	Nose Gear Steering Cylinder	Overhaul
783164 Series / 783686 Series V20600Series	Solenoid Valve	Repair
EA1699-1, -501, -503, -505 2235.0000.000	Nose Gear Centering Spring Assembly	Overhaul
EA1801-2	Steering Valve Assembly	Overhaul
ED12910-2	Main Landing Gear Rod	Overhaul
ES12854-1, -501	Outer Strut	Overhaul / Repair
ES12858-501	Landing Gear Inner Body	Overhaul / Repair
ES12908-503, -504 910.003.53, .54	Fork Rod & Axle Assembly	Overhaul / Repair
F10A5SCH203-1, -3 12111164-001	Thrust Reverser Actuator	Overhaul
572375-1, -2, -3	Cooling Turbine Housing	Repair

CALL FOR A COMPLETE LIST OF WESTWIND CAPABILITIES