

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

| MEMO | RAN | DUM | NO. | HRADM |
|-------------|-----|-----|-----|-------|
| | | | | |

TO

19_PK30404

NAME

Valencia, Vincent Maderazo

FROM

PKIMT Management

Mulwo

SUBJECT

Notice for Suspension

No. of Offense

2nd offense

DATE

December 17, 2020



This refers to the alleged offense(s) you have committed at

9/21/2020

to name:

Valencia, Vincent Maderazo

Violation Offense No.

V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP in Auto Crimping - Advance input of data on wire length

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme:

19 PK30404

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

I-ALERT WRITTEN EXPLANATION

2 1

| | | -ALEKI VVKI | I I EN EXPLANA | AHON | ** | | | |
|---|---|--|--|--|----------------------|--|--|--|
| FAS | | | | Control No: | FAIR- 1A. 2009- 7082 | | | |
| AGENCY Please Specify: PK (MAT | | | Sufferedor M. Muri 110 | K. hiernandez G. Reyes | | | | |
| rease specify. | | | Audited By: | Checked by: Noted By: | | | | |
| Name: Position: ID Number: Batch No.: Car Model/Line: | | Date/ Time: No. of Offense: Superior Name: | outo cimping Ds/n Sept-21/2020 12:30 19 Offerse C-Marasigan | Non-compliance Reference/Document Control Number: | | | | |
| Details of Audit Findings: And following top, accorded conduct advance input on data of their | | | | | | | | |
| Details of Audit Findings: Not following som accounts conduct a dvance input on data of wire length even he did not yet measure actual length of shikelian. | | | | | | | | |
| | (4) 14 () 4 () 4 () 4 () 4 () 4 () 4 () | | RECORDER OF THE PROPERTY OF TH | (Newspace) | | | | |
| WRITTEN EXPLANATION | | | | | | | | |
| alter po si umcent H. Ublencia ay hindi natagal po nese mag print sa advarre input na length na wire dahil matagal po nese mag print lug kandan dahil nawawalan po ng connection ang cais | | | | | | | | |
| COUNTER MEASURE: | | | | | | | | |
| EUSUNOD NA PO aro 5a 50P Para Mainasan ang NG OUTPUT | | | | | | | | |
| at hindi 170 na po uulitin Ong nagawang hemalian- | | | | | | | | |
| REMARKS/ EVALUATION | | | | | | | | |
| i-Alert written only Agency/FALP Written Only(based on handbook) Need day/s suspension(based from handbook & Memo for Major Non-compliance). | | | | | | | | |
| V. Valin Employ | ree | Jr Staff | E-HE NT ELOPO | Supervisor | Anata Manager | | | |
| Date: <u>20 - (</u> | | 00 25 N | Date: 04 26 46 | Date: 11/28/2020 | Date: 01/12/ 2020 | | | |