

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

17 PK16200

NAME

Loreño, Merry-Ann Olivar

FROM

: PKIMT Management

SUBJECT

: Notice for Suspension

No. of Offense

1st offense

DATE

October 21, 2019

This refers to the alleged offense(s) you have committed at

9/19/2019

to name:

ACKNOWLEDGE BY:

No. Offense

Loreño, Merry-Ann Olivar

ure Over Printed name/ Date

ACKNOWLEDGEMENT FORM

COMMENTS/ ASSESMENT

Violation Offense No.

V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme: 1- L MON

17 PK16200

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines

Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 17 PK16200

NAME

Loreño, Merry-Ann Olivar Haren

FROM

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense

1st offense

DATE

18-Oct-19

This refers to the alleged offense(s) you have committed at

19-Sep-19

to name: Loreño, Merry-Ann Olivar

Violation Offense | V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED DY

PKIMT Management

Conforme:__

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

I ALERT WRITTEN EXPLANATION

	FAS		Control No: FALP-1A - 1909 - 1333
	AGENCY Please Specify: PKIMT		JR · ROILC G. Magadia Audited By: Noted By:
.*	Name: Loreño, Marry Ann Position: Associate ID Number: I7-PK/6200 Batch No.: I73 Car Model/Line: Suzuki 401/5116 Audit Findings: Non-compliance Details:	Process: Group/Shift: Date/ Time: No. of Offense: Superior Name: or failure to follow the stand	Appearance A IDS DQ-19-19/11:00Am 1st A. Lamonte Aard operational procedure in impecting the production of the procedure in impecting the production of
	Inspector did not follow the pi	raper may of checking	connector
	W	/RITTEN EXPLANATION	VP
	na connector Kasi po unang tignan ang ins	dahil sa hina nasanay po l ertith bago p	ti tamang pag-iinspect kasi ako ng pa so ang mating part
	Pero pag po one piece l pong gamin ang ta	How naman po mang pag-iitispen	kami nogogona ko et ng sonretar
		Remarks/ Evaluation:	
	sa consonad po na andit n dahil sa hindi ny	ya ay issnehan na a pagsunod sa is	cya ng cospension tandard.
	Issue Re		
	18he 1	0	
	Signature of Employee Date: (7) 11 (7) Date:	Staff Su Date: 09/21/0 Date	Johnson Manager 15-62-19 Date-

MATERIALS.	FROPER WAY OF CHECKING COINNECLOR BOCKMENTING: FALP-WI-QCA-15008	NAME OF TAXABLE PARTY.	May-08-2019
	Prepared by: FALP-CP-QCA-17074	Checked by: Verified by:	Approved by:
FURPOSE To set instruction on how to check the cond to of connector properly	FALP-GL-ESH-18006 Li Mindanao Staff s	B. Ramirez	A, Nachor / T, Maruoka
i er	3		
	ront side of connector based on a lock pastion (unless otherwise	NOTE 1. Sightly touch the retainer using thumb finger	thumb finger
CAUTION: CAUTION: Do not insert your finger inside the connector mating part during inspection! Inspection! and horizonal position.	specified) 1. No foreign matter attached 3. No foreign matter attached 4. No excess burn 4. No excess burn 4. No excess burn 6. No foreign matter attached 6. No foreign matter attached 7. No pail ocked retainer	Trom, left to right, and right to left to be checked if the realiser is already locked or unlocked refer to FAIP-WI-QCA-1501.5 Proper Method on Pressing and Checking of Fetainer lock. NOTE 2: TBO can be detected if encountered half locked/imperfect locked of retainer. NOTE 3: These applies to all connectors except special	e checked if the efer to ressing and ressing and intered half recept special
Presence and condition of packs in rubber seal (applicable for water proof connections).		Strated on different location.	stor lock are
	Check lett side of connection	No deposition of the second of	
ter all torus	Actions the instance of the in	3	3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
			ble PPE
ving info	Delants of disting a varing information regarding safety purposes (Wear Proper PPE Personal Protective Equipment (Refer to FALP-GL-ESH-18006), Be careful not to cause injury during inspection and packing of wire harness	use injury during inspection and packing of wire	
ked item o	Align sequence of checking to current process (sequence no. 2,3,4,5,85); changes on picture item no. 6; additional instruction and note on sequence no. 1,3,4,5,86); Remove checking of deform insulation barrel and bend-up/down terminal (checked item of Initial process) (sequence no. 6); Additional check item (Presence and condition of gomuse and "surnesen") and additional note for prope bending of branch curing checking of connector (sequence no. 6); additional reference	%6); Remove check item for (color/size/type of wir ess) (sequence no. 6); Additional check item I reference	re) 3
er ISO 9001	Update the sequence number of Process, additional comment for sequence No. 1 tem No. 8 First Icea and ICO pirot 300B of males Management Surveys		