

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 18 PK28828

Taño, Kimberly

**FROM** 

: PKIMT Management

SUBJECT

: Notice for Suspension

No. of Offense

: 1st offense

DATE

March 13, 2019

This refers to the alleged offense(s) you have committed at

16-Feb-19

to name:

PKIMT

No. Offense:

Jr. Staff

ACKNOWLEDGI

Staff

1st

Taño, Kimberly

ACKNOWLEDGEMENT FORM

COMMENTS/ ASSESMENT

IDAY SUSPENSION APRIL 09, 2019

Violation Offense No.V

#### OFFENSES AGAINST COMPANY INTEREST

Section No. 14

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

#### Description:

### Non-compliance on implemented countermeasure for customer claim received

You are hereby given 5 days upon reciept of this letter to explain in writing why you should not given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Ac

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines Tel No.: (043) 405 6388-89 / (043) 405 6407-08

#### MEMORANDUM NO. HRADM

TO

: 18 PK28828

Taño, Kimberly

**FROM** 

: PKIMT Management

**SUBJECT** 

: Notice to explain

No. of Offense: 1st offense

DATE

: 12-Mar-19

This refers to the alleged offense(s) you have committed at

16-Feb-19

to name: Taño, Kimberly

Violation Offense No.V

## OFFENSES AGAINST COMPANY INTEREST

Section No. 10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Non-compliance on implemented countermeasure for customer claim received

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY

PKIMT/Management

Conforme:

FURUKAWA - Production Operator

(Please attach your written expalanation upon returning of this letter)

# I ALERT WRITTEN EXPLANATION

FAS DADW	Control No: FALP - IA - 1962 - 094									
FAS MDHII										
PKIMT ADD EVEN	Origh of magain									
	Audited By: Noted By:									
Name: Taño Kimbury	Process: Appearance									
Position: Kurciatu	Group/Shift: ½/ pc									
ID Number: 14- PK 28828	······································									
Batch No.: 244										
43)(41)(41)(41)(41)(41)(41)(41)(41)(41)(41										
Audit Findings: <u>Non- Compliance a Imple</u> Details:	nented Countermeasure for Customer Chain Received									
	lock of connector RCS-BE-JF-GR before									
	PRIMIT ADD EVEN  Taño Kembury On: Magajorh Group/Shift: B/ Ps  The Complete Superior Name: The Magajorh Region No.: 24H No of Offende: 4th No.: 24H No of Offende: 4th No.: 24H No of Offende: 4th No.: 24H No. of Offende: 4th No.: 24H No.: 24H No. of Offende: 4th No.: 24H N									
	·									
WRITTEN	EXPLANATION									
(ACCOMENTED DE COMPANIE MA COMOMENTE GOARD MA COMPANIE DE COMPANIE DE COMPANIE DE COMPANIE DE COMPANIE DE COMP										
	· · · · · · · · · · · · · · · · · · ·									
AT CHECK POINTS IN G BAWAT	HARNETS NA IINSPECT KO.									
Please Kup, P	······································									
1,000										
Remark	s/ Evaluation:									
The second laws and the transfer and the second sec	And the state of t									
MUST ENSURE TO FOLLOW THE COUNTE	R MEASURE GIVEN AT ALL TIME.									
, , , , , , , , , , , , , , , , , , , ,										
the state of the s	tent   /#									
Signature of Employee It Staff	aff Superior Manager									

Ma later

FURUKAWA AUTOMOTIVE SYSTEMS LIMA PHILIPPINES, INC.									Approved by:	Reviewed by:	Prepared by:	
	- V	1000		NAMES OF TAXABLE PARTY.					WARRING I			
			AND DESCRIPTION OF THE PARTY OF	MMARY (	OF RE	CORDS			T. Maruoka	A. Rublo/ G. Magadia	14.0	
Condition of Condition	ermonicalistic property	No: K1808-0485		Line Number	: 6102		Date Pr	epared: 08/06/201		1 A Nobio G, magadia	J.A. Rivas	
	duct infor	mation:					tial Defect Assessr		1.7		<b>-</b>	
Custon	ner:	NISSAN		Car Model:	J02C		SSIBLE TO PASS DURI ERATION	ING NORMAL				
Produc	t No:	24079-5WK0A		Lot No:	59LY21	L-Mc	T POSSIBLE TO PASS ERATION	DURING NORMAL				
Production Date: 20/Jun/18		Contact No.	59KH24		ERATION RKS ON CAUSE:							
		20/3011/10		Serial No:	193	No ri	k found on our pro	ocess. Cannot		7 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		
Date Re	eceived:	3/Aug/18	_	NG Qty:	3	FALP	ice same defect us	ing jigs used on	Damage	d Connector (RSS-BE	-2F-GR)	
3. Belo	w is the su	ımmary of findi	ngs based o	n the initial data	gathered	for the claim	defect:			(1.00 02		
TEM	10.05 B	RECORDS						OLT OF CHECKIN	IG	<del>-</del>	REMA	
1 IRCS Record					No abnormality found on the process.						0	
	Repair Rec	ora e Point <i>(initial and</i>		No repair record found								
	_				No 4M on the affected date							
4	Initial Proc Error Data/ A	ess Records (CCI (Ctual Sample, etc.)	S Data/ Setuat	o/ N/A	N/A							
5 /	Attendance	e Table (Initial on	d Final)	No absent Mi	on the a	ffected dates		<del></del>			0	
6 F	Process Ch	eck (Initial and Fin	al)		PARTS SUPPLY							
				• Af SUB-ASSEMB	Affected connector is stored at a low level on parts rack.  SUB-ASSEMBLY							
ł				• Co	Connector jig on sub-assy is in good condition. No risk found.							
					• ECT checker jig is in good condition.							
İ				• Ch	Checker jig cannot hit the lock portion of the affected connector.							
				APPEARANCE	Closing of checker jig handle cannot damage the connector.							
				• No	marking v	vas done on the	affected connector	after appearance	inspection.			
				• Ho	Failed to consider small harness product for Nissan JO2C     However, as per interview to appearance inspector, she was already conducting come inspection much all its production come in the production come inspection much all its production							
1				hai	rness since	she was also a	ssigned as inspector	for engine harnes	s and she knows that it is	same connector.		
ı				ļ								
7 Si	imulation	· · · · · · · · · · · · · · · · · · ·	-	Simulation	Simulation 1: Closed ECT checker handle with large force.							
				Simulation 2: Closed ECT checker handle with large force 12 times								
ŀ				• RESULT: NO	Simulation 3: Pushing of harness and then closing of checker handle.     RESULT: NO DAMAGE ON THE AFFECTED CONNECTOR							
					Different orientation of connector cannot be inserted inside checker jig.							
				> binereill di	bindent differentiation of connector cannot be inserted inside checker jig.							
			Daily	NO Problem to	O Problem found							
81	Machine Record	ECT	PM	Last PM was or	Last PM was on April 01, 2018							
9	Ketolu		Repair	No Repair was	No Repair was done on affected checker fot the affected month.							
1				Aiready occurr	Already occurred 3 times. Not accepted as FALP responsibility since no risk was found during our process.							
				First Occurrence	ce	Date May-17	Product J02C Engine					
Pa	st Trouble	Check	; I	Installation of Foreign Jul-17 JO2C Engine and								
}				Material Check 2nd Occurrenc		A== 10	JO2C Small					
			3rd Occurrence		Apr-18 May-18	J02C Engine J02C Engine	1					
_				Latest Occurre	nce	Jun-18 J02C Small						
	TV Check		N/A								<u> </u>	
<del></del>		ct Records (Initia	d and Final)	No same internal defect for the past 3 months								
	rting Resul			600/600 sets ar	e GOOD						0	
12 AD	DITIONAL	REQUESTED DA	TA:	N/A								
ontain	ment Act	on / Immediate	Action / T				revent outflow of					
rovida	Ol on the	enecial checking	and made	ng method of RSS	rmeasur	e in order to	revent outflow of	the same defect	<b>t.</b> *			
Put-Ma	rking on t	he connector sa	me'with'en	ine harness			5)				<u> </u>	
riente	d all affect	ted members on	the conten	ts of the provided	d OI. (08/0	04/2018)						
ost cau	ution tag											
eflection	on to Qua	lity System	6. Claim S	tatus (refer to 7	Implem	entation Deta	lis:	M				
Process Fallure Mode and Effect Analysis Feedback Guid			Customer		RODUCT NO:	LOT NUMBI		or.	MARKS	lola-sig		
Quality Control Plan			unacimes)	24	079-5WK0A	59TP78	DATÉ:	N.		Identification Mark on		
Risk and Opportunity Analysis OPEN  FINAL REPORT IS REQUIRED			<u> </u>			3911/8	02/00/2018	Starting lot implementation checking of connector base	on on marking and proper ed on provided OL	Polycard		
FINAL REPORT IS REQUIRED CLOSED			<b>□</b>	<del></del> .						$\blacksquare$		
	- /101		<del></del>			<del></del>					$\neg \!$	