

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines Tel No.: (043) 405 6388-89 / (043) 405 6407-08

		HRADM

TO

20 PK41144

NAME

Roaring, Gizelle Magadia / Summany

FROM

PKIMT Management

SUBJECT

Notice for Suspension

No. of Offense

1st offense

DATE

February 22, 2021

Line/Shift SSAZ

ACKNOWLEDGEMENT FORM COMMENTS/ ASSESMENT

This refers to the alleged offense(s) you have committed at

1/12/2021

to name:

No. Offense:

Roaring, Gizelle Magadia

Violation Offense No.

OFFENSES AGAINST COMPANY INTEREST

Section No.

10 Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the

particular duties and responsibilities inherent to the employee's work

Description:

Non Compliance on proper flow when encounter abnormality

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

PKIMT Management

SSMO 20114 20_PK41144

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

WRITTEN EXPLANATION

Name: Roaring, Lizelle	Date: 02 - 19 - 2021
an alicana an arganes flow to secounter	No.of violation:/
Line	
Reason:	
Ako po si Gizelle Roaring ay nakate clamp). Sinoad Nitayout Pinass ko po siya sa hanger para maayos, Di ko po akalain ng kasama ko. Bukod po dito ay nagta-tape laging butas ang junction. Hindi na po ako sapagkat wala pong sinumang leader ang	encounter ng NG (inverted sa process ko at isinabit na irerepair po siya po ako dahil nakatawag ng jr staff nandoon para mag-ayos
Countermeasure: Pag naka encounter po ako ng NG, fo	Atawaa by aka
ng staff lyr staff para maconfirm nila may Kapag may minor defect / abnormalities dap	NG akong na detect.
	S-ADRUMA
EMPLOYEE	SUPERVISOR
STAFF S	SECTION MANAGER
SIAFF	DECTION MANAGER

		18:43:22	ECT associate get affected harness with claim from ECT hanger
		18:43:26	Barcoded Affected harness with Claim
		18:44:38	ECT machine detected the Crosswire
		18:44:53	ECT associate called Dimension associate (Original ECT inspector of the line since YKA)
Video 1	01/11/2021	18:45:22	Dimension associate seen touching the jig to open pneumatic lock
		18:45:31	Returned harness with Claim to ECT hanger
		18:45:36	Get good harness to pass the serial no. of harness with claim on IRCS
		18:46:40	Rebarcoded good harness on ECT table and set again to jigs for 2nd time ECT check
		18:48:13	Sub assy associate approached Expert then ECT inspection are to get harness with claim and bring to sub assy area
			Dimension associate returned harness with claim to Appearance hanger
Video 3	1,707,711	8:11:47	Appearance gave feedback on 1 portion
	77/ 77/ 7077		Dimension associate get again the harness, attach component from parts box on last station of assembly
		8:13:37	Dimension associate returned harness to Appearance hanger