

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

17 PK16229

NAME

FROM

Alde, Anjanette Almario

SUBJECT

: PKIMT Management

Notice for Suspension

No. of Offense

1st offense

DATE

October 21, 2019

No. Offense: If I day
OCT 27, XIII

OVER Printed name/ Date

This refers to the alleged offense(s) you have committed at

9/19/2019

to name:

Alde, Anjanette Almario

Violation Offense No.

OFFENSES AGAINST COMPANY INTEREST

Section No.

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

### Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIM'T Management

Conforma

17 PK16229

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

#### MEMORANDUM NO. HRADM

TO

: 17 PK16229

NAME

Alde, Anjanette Almario

FROM

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense

: 1st offense

DATE

18-Oct-19

This refers to the alleged offense(s) you have committed at

19-Sep-19

to name: Alde, Anjanette Almario

Violation Offense | N

### OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description

## Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme:

**FURUKAWA - Production Operator** 

(Please attach your written explanation upon returning of this letter)

# I ALERT WRITTEN EXPLANATION

		Control No: FALP-1A - 1909 - 1
AGENCY Please Specify: PKIMT		Audited By: Noted By:
Name: Alde, Anjanette Position: Associate ID Number: 17-PK/16229 Batch No.: 17-3 Car Model/Line: Guzuki HD1/S/16 Audit Findings: Non-compliance or fail	Process: Group/Shift: Date/ Time: No. of Offense: Superior Name:	Appearance A 1 DS 09-19-19 (11:00AM) 1.cf A - Lamonte
Details:  Inspector did not follow the pro		ard operational procedure in impedingly king connector
	, , , , , , , , , , , , , , , , , , , ,	wing Convocion
	EN EXPLANATION	
TOWNORG CHECKING NG COMECTOR		nPUANCE DAHIL SA HINDI NG 10 HON DAHIL SA KAMI
04 Tambakan at nakasano na pagcheck na connector	AYÓN NA RIN P KAHIT KAMI	D Namin And Gonung way
aming superior		
Rem	narks/Evaluations	
The state of the s	**************************************	
sa shrunod po na maard	it sya ay is	snehan na sya ng shispenis
sa shrunod po na maard dahil sa hindi nya	it sya ay is pagenned sa	snehan na sya ng snispens Standard.
sa shrunod po na maard dahil sa hindi nya	it sya ay is pagenned sa	snehan na sya ng snipens Standard.
sa shrunod po na maard	it sya ay is pagenned sa	snehan na sya ng snifens Standard.
sa shrunod po na maard dahil sa hindi nya	it sya ay is pagenned sa	snehan na sya ng snispenis Standard.
sa shrunod po na maard dahil sa hindi nya	it sya ay is pagenned sa	snehan na sya ng snispens Standard.
sa shrunod po na maard dahil sa hindi nya	it sya ay is pagenned sa	snehan na sya ng snispens Standard.

PROPER WAY OF CHECKIN  PURPOSE  Final Assembly P  Scape  On on how to check the condition  of the control of the condition  carrigon:  Carrigon:  all position  proof connector  carrigon:  all position  proof connector  all position  proof connector  all position  proof connector  carrigon:  all position  all position  proof connector  carrigon  all position  all position  proof connector  carrigon  all position  proof connector  connectors  co	OF CHECKING CONNECTOR  DOGUMENT TYPES  DOGUMENT TYPES  EALP-WI-QCA-15008	FALP-CP-QCA-17074	FALP-WI-QCA-15015 FALP-GL-ESH-18006 Stoff	*Check backs de of connector otherwise 1. No danage part fall adges must check 2. No for ign matter attached 3. No excess burn 3. No hall acked refairer 4. No hall acked refairer 4.	insertion part of connector  to cavity (refer to FALP-CP-CCA-17074, Inspection Criteria for Damaged  art of all Common Connectors, for the accessible damage condition).  An Institution Seposed core wire  finiserted wire fine pulling out or 180).  Ind condition of gomusen and taumesen (applicable for water proof  way of bending branch when thecking the insertion part of connector  rion must be 50mm away from neck of connector,  nuch bending of branch.	Dritals of cliango E Personal Protective Equipment (Refer to FALP-GL-ESH-18006), Be careful not to cause Injury during inspection and packing of wire	nges on picture item no. 6; additional instruction and note on sequence no. 1,3,4,5,8,6); Remove check item for (color/size/type of wire) deferon insulation barrel and bend-up/down terminal (checked item of initial process) (sequence no. 6); Additional check item prope bending of branch during checking of connector (sequence no. 6); additional reference	CONTRACTOR
NATERIALS  N/A  To set instruct of connector promotion of connector prometa connector prometa connector prometa connector prometa dispellable for wate alignment lig) alignality bate May-08-2019 Angle of the prometa alignment ligh alignality bate for wate for wate alignality bate for wate for wate alignality bate for wate for	. 18	Alignment Jig	now to check the condition	e Check fronts de of conecte commette lock position (unless specified)  1. Nowwargs part (all edges mu 3. No damage part (all edges mu 3. No foreign muster attached ant during 11.  4. No excess burn  6. No excess burn  7. No excess burn  8. No foreign muster attached ant detring 11.	e Check the  1.No damag on insertion 2. On damag 3. Cond that 3. Cond that A Presence contectors) NOTE. Frop a. Bending p. b. Avoic too	Jitional warning information regarding safety purposes (Wear Proper Pp ness	in sequence of checking to current process (sequence no. 2,3,4,8,5); classady checked item of sub assy cperator using Sub PC, Remove checking sady checked item of sub assy cperator using Sub PC, Remove checking asserte and condition of gomusen and sustainesen) and additional most fo	Update the sequence number of Process, additional comment for sequence
5 4 2 9		N/A	To set instruction of connector of	Check the making part of camertor  1. No terminal behing of the legical authorized and horizontal position.  2. No derminal behing of terminal check).  3. No foreign matter aftender  5. No deformation matter aftender  6. No beneformation pot on means  6. No beneformation pot on means  7. No wrong plating of terminal gold (filt)  7. No wrong plating of terminal gold (filt)  9. Presence of red mark (for male connectors that has alignment ig)  9. Presence and condition of makin ruther seal (applicable for matter)  4.	A Company	107		
MAN NAME OF THE PARTY OF THE PA	FUNDAWA AUTOMOTIVE SYSTEMS UMA PHILIPPINES, INC. CARL PHODEL	B 8	N/A	Check the mating part of competents.  1. No cerminal backing out must check in which of the competent of the competent of the competent of the competents.  2. No demograph matter attaches.  3. No foreign matter attaches.  4. No axeas burn.  5. No deform part of competents.  6. No bend deform/open up as minal (must ober of bend deform) part of competents.  7. No wrong plating of terminal goldfult).  8. Presence of real mark for male connecting.  9. Presence of real mark for male connecting.  4.	Check rightside of connector     Nodemage part (all edges must check)     No foreign matter attached     No excess burn     No deform part of connector	QA-QCA-L3a-1905-015	OA-QCA-L3a-1707-001	A3a-1610-307