MA AUTOMOTIVE SYSTEMS LIMA PHILS. INC. echnology Center, Lipa City, Batangas INCIDENT REPORT FORM ID Number: Complete Name: 18-03730 Almosara Dyna.P Date of Incident: Production 5/Subaru Date Issued: June 19,2020 Part 1: (To be filled-in by the Immediate Superior) July 28,2020 INCIDENT REPORT VIOLATION: UNAUTHORIZED/HIDDEN REPAIR On it was reported that you allegedly conducting cutting of clamp on dimension process due to short dimension which is not allowed. In view of the above, please explain in writing within 48 hours why no disciplinary action should be imposed on you for violating the Company Policy C. Offences Against Work/Business Standard Section Which states Failure to follow business standards, operation procedures, work instruction or work practices which may or may result to damage of company property: Un cuthorized hidden repair excluding The allege offense maybe punishable by written warning to dismissal: FALP (Please explain in writing within 5 days upon receipt of this report. Failure to do so, means you have waived your right to be heard.) DCT 31 2028 KAWASE FREQUENCY OF OFFENSE 1st Offense 2nd Offense ☐ 3<sup>rd</sup> Offense 4th Offense 5th Offense issued by: Noted by: Received by Employee: Date Received: Immediate Superior Manager Signature over Printed Name 08-12-20 Signature over Printed Name Signature over Printed Name Part 2: (To be filled-in by concerned employee) **EXPLANATION** Ako po si Dyna P. Almosara ay na-audit dahil po sa hindi ko pagrunod sa standarol pocedure. Nakitaan po nila ako na nageucut ng clamp dahil po short dimension po ang sequence na yun, Langhinayang po ako sa harneur kaya po nagawa ko ang bagay na yun. Alam ko pang mali at bawal po iyun. Ipagpa umanhin niyo po ang aking nagawang pagkakamali at hindi pagsunod sa standard procedure. Sa surunod po na maka encounter ako ng mga NG va Harnese ay akin na pong gagawan ng red tag at vary mod na rin po akt va standard procedure. Humihingi po ulit ako na paumanhin. Maraming sulamat po... Date prepared: Almosara Dyna P. Date Received: 08/12/20 Employee Name Signature over Printed Name Explanation received by: Signature over Printed Name HR-024-00

EFF: 09/15/18

· 2	Part 3: (To be filled-in Immediate Superior)						
Minor Offens	EVALUATION / INVESTIGATION  Verbal Warning Written Warning Major Offense Suspension Dismissal						
Result of Investig	tion:						
a de la companya de l	-Attempt to replaced damp						
	- Consecutive NG, produced by new employee						
	RECOMMENDATION / CORRECTIVE ACTION						
- Suspension -	Workings Days - Date from						
Dismissal	Effective Date: Offenses Against:						
Remarks:	I days suspension for the attempt of conducting						
Issued by:	Percommonded by:						
	rugena Jerald Ganadillo/Engerie Caileo						
Immediate (Signature over	Analed Hame) (Signature over Printed Name) Human Resources (Signature over Printed Name) President						
Date: 10  15 20	Date: 10/15/20 Date: 1/16/20 D						
Note: For recommon	Mbuu						
Note: For recommendation of the imposition of lesser penalty of verbal / written warning, aside from the signature of the immediate superior & Manager, the approval of Human Resource is needed before implementing the Disciplinary Action.  In case/s of SUSPENSION and/or TERMINATION, the President's signature must affix before implementing the Disciplinary Action.							
	g this notice, I am acknowledging that I have read and understood the information in this IR Form and I have been Informed of the consequences of my action.						
Employee Signature over Printed Name:							
Date Received:							

HR-024-00


EFF: 09/15/18

R.Tabogon	J. Reyes/K. Hernandez	C Manuto	
Davis II		G. Magadia	
Prepared by:	Checked by:	Approved by:	

## I-Alert Daily Line Audit Report

Date & Time	June 19,2020/10:30prp	Illustration	
Shift & Group	NS/A	mestation	Action Taken
Car Maker/ Model	Subaru		ON THE SECOND SE
line No.	7113		
Vame	Almosara, Dyna P.		
D No.	18-03730		
Batch No.	115		
Process	Dimension Process		
AS or Agency: specify	FAS(expert)	Elizabilitati and	
erson Informed	A.Briones	to war	V.,
Audited by	M.Casama/C.Redondo		
leason/Risk:			
<del></del>			The second of th
Audi	t Details		
n-authorized Repair/Hidde	en Renair		
	amp on dimension process due		1454.74E
encountered short dimen	sion from center of junction to		
enter of clamp Y8-17-B	sion from center of junction to		
emarks: Affected Line was	not allowed to use side cutter		

EFF:10/17/19



NAME	DEPARTMENT	POSITION	SIGNATURE
Uma Almolara	PDS- Subaru	Experi (Associate)	disamenan
Cirlie D. Almigera	POC	V2.	<u>Hlanopara</u> Gölk
,			
			•
			*

Note: This attendance form will be used as objective evidence of the completion of the above-named course by the attendees named herein.

Facilitators Signature/Date:

Facilitator:

PRODUCTION DEPARTMENT

Prepared Examined Verified Noted

Minutes of Meeting

Location:

Accords

. . . . . . .

Attendees :

Dyra Albarana Emlie Abangena

Details

Medica struted at around 2:15 pm -

Si Je started the the discussion by asking what was happened with the incident when she was audited by 1-alert, certainy of clamp on Dinkersion, and Mr. Dyniai Almosara thoroughly explained her side on what happened that time the little was a characterist on that affected parties, and even after teaching the right procedure on procedure process. Depart repeated by each and she has no choice but he do it finiting that it will belo her minuse her line explained, she admitted her historia and promised her minuse her line explained a emphasized the impact of the again. See is applained a emphasized the impact of the again.

Meeting ended with the agreement that some incoder will never te-ordered again a will strictly follow Sandard procedure on quotes.

End of Minutes. 2:25