

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 19 PK30772

**NAME** 

Dimaano, Kim Chester Cuasay

FROM

PKIMT Management

SUBJECT

Notice for Suspension

No. of Offense

: 1st offense

DATE

November 17, 2019

This refers to the alleged offense(s) you have committed at

10/30/2019

to name:

ACKNOWLEDGE BY:

MANAGER

PKIMT

No Offense:

Dimaano, Kim Chester Cuasay

ACKNOWLEDGEMENT FORM

COMMENTS/ ASSESMENT

Violation Offense No.

V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not Following SOP - Did not conduct checking of Shikakari when encountered Machine Error during Process

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme

19 PK30772

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines Tel No.: (043) 405 6388-89 / (043) 405 6407-08

### MEMORANDUM NO. HRADM

TO

: 19 PK30772

NAME

Dimaano, Kim Chester Cuasay

**FROM** 

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense

: 1st offense

DATE

16-Nov-19

This refers to the alleged offense(s) you have committed at

30-Oct-19

to name: Dimaano, Kim Chester Cuasay

Violation Offense | V

#### OFFENSES AGAINST COMPANY INTEREST

Section No.

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description

Not Following SOP - Did not conduct checking of Shikakari when encountered Machine Error during Process

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

## I ALERT WRITTEN EXPLANATION

FAS		Contro	DI NO: FALP - /A - 1910 - 2057
AGENCY		Jahana der -	(40)
Please Specify: 3Km7	_	# Asanador	G. Magadia
		<sup>/</sup> Audited B	y: / Noted By:
Name: 9IMAANO, KIM CHESTER		Auto Crimping T	0 244 /
Position: ASSOCIATE	Group/Shif		
ID Number: 19Pk 50172  Batch No.: 2E5	 Date/ Time No. of Offe		19/7.55
Car Model/Line: DAIHATSM DOIL /IN	*****		
Audit Findings:			··············
Details:	Not FOLLOWING	op	
DID NOT CONDUCT CHECKING O	F SHIKAKARI WHEN ENCO	UNTERED MACHINE ER	ROP DYMNG PROCESS.
<u> </u>			
	WRITTEN EXPLANA	TION	
Ako po si kim U	nester Dimagno a	naka encontu	ng tangle
or measuring belt for			
after po na mataencan			
Hindi na po ulit ato n		ng mag stout	of ulitako
hang mass pro1			
	···		
		······	
		/	
to 1, "		14, // \	
for councilia, 11/1/ F.	way Co agricul Is	T Mis / Court	9/
0 1 1	1		<u> </u>
To the second	Kan K		( prof
	, ,		
	Remarks/ Evaluation	n:	
(	, , ,		
for issuance of memo (baser	d pun hand but)		
( post			
a .			
De I	tor:		
Jucamet 1	1. Umric	A.H. 1-1	182
Signature of Employees   J. Vellando	t: Manah	uctibay an	of Few
Signature of Employee Jr Staff Date: 19-11-0	Date: 11 12 16	Date: 11/3	Date: (17)

# I ALERT WRITTEN EXPLANATION

FAS MDHII	Control No: FALP-1A - 1910 - 2057
PKIMT ADD EVEN	Audited By: Noted By:
Name: Dimidano Km Cherjer Process:  Position: a4400jatc Group/Shift:  ID Number: 19 PK 10772 Date/ Time:  Batch No.: 255 No of Offense:  Car Model/Line: Painotty 0011 / Initial Superior Name:  Audit Findings: Not Tollowing Sof	auto Crimping TRD 244  DSIB  Oct 70, 2019 1:53  191  The relargue 2
Details:  Did not conduct checking of Shi Kakari when encountered ma	during process.
WRITTEN EXPLANATION	
Ato po Kim Chester Dimaano ay nav Eurousunod sa sop. Hindi ko po a	ham na kailangang
gunana hang sampling error kan ang wire sa mesaring helt.	
Domoch / Columba	
- To Staff /LV please investigate why member di	dnot land the rule
- for verify the audited item, as per associate it is not needed to	
	er e
ignature of Employee Date: 11-16-19 Date: 11-06-19 Date: 11-06-19 Date: 11-06-19	Dayan  Pervisor  Manager  Date:



### INITIAL PROCESS CONFIRMATION FOR ERROR SAMPLING AND AFTER EQUIPMENT REPAIR

Car Model:				* ' ' ' ' '	hift/ TRD No. :								
Date/Time Error Encountered	Code of	SPECS	Actual Sample		Produce By:		Checked by: (PD Jr.Staff)		Verified by:				
	Error	3F203	Actual Sample	EM J					I Jr. Staff Q.A Person		ersonnel		
		Terminal Name:				PD		Good		Good		Good	
		Actual C/H:		SAMPLE WIRE		ЕМ		No Good		No Good		No Good	
		Actual III.						Signature:		Signature:		Signature:	
		Terminal Name:				PD		Good		Good		Good	
		Actual C/H:		SAMPLE WIRE		ЕМ		No Good		No Good		No Good	
		Actual I/H:					ш	Signature:		Signature:		Signature:	
		Terminal Name:				PD		Good		Good		Good	
		Actual C/H:		SAMPLE WIRE		EM	Name and Address of	No Good		No Good		No Good	
		Actual I/H:						Signature:		Signature:		Signature: _	
		Terminal Name:				-		Good		Good		Good	
		Actual C/H:		SAMPLE WIRE		PD		No Good		No Good		No Good	
		Actual I/H:				ЕМ		Signature:		Signature:		Signature: _	
		Terminal Name:						Good		Good		Good	
		Actual C/H:		SAMPLE WIRE		PD	П	No Good		No Good		No Good	
		Actual I/H:				ЕМ		Signature:		Signature:		Signature:	
		Terminal Name:						Good		Good		Good	
		Actual C/H:		SAMPLE WIRE		PD	🗆	No Good		No Good		No Good	
		Actual I/H:				EM		Signature:		Signature:		Signature: _	
		T						Good		Good		Good	
		Terminal Name: Actual C/H:		SAMPLE WIRE		PD		No Good		No Good		No Good	
		Actual I/H:		•		ЕМ		Signature:		Signature:	_	Signature:	_
						-		Good		Good		Good	
		Terminal Name: Actual C/H:		SAMPLE WIRE		PD		No Good		No Good		No Good	
		Actual I/H:				EM '		Signature:	_	Signature:	_	Signature:	_
								Good		Good		Good	
		Terminal Name: Actual C/H:		SAMPLE WIRE		PD .	$_{,}\square$	No Good		No Good		No Good	
		Actual I/H:		OAM EL MINE		ЕМ			ш		ш		_
						-		Signature: _ Good		Signature:		Signature: _ Good	=
		Terminal Name: Actual C/H:		SAMPLE WIRE		PD		No Good				2000	
		Actual I/H:		SAMPLE WIRE		ЕМ		Lancas and		No Good		No Good	
						-		Signature: _ Good		Signature:		Signature: _	
		Terminal Name:				PD					1000		
		Actual C/H:Actual I/H:		SAMPLE WIRE		ЕМ		No Good		No Good		No Good	
								Signature:		Signature:		Signature: _	=
		Terminal Name:				PD		Good		Good		Good	_
		Actual C/H: Actual I/H:		SAMPLE WIRE		ЕМ		No Good		No Good		No Good	
								Signature: _		Signature:		Signature: _	
		Terminal Name:				PD		Good		Good		Good	
		Actual C/H:		SAMPLE WIRE		ЕМ		No Good		No Good		No Good	
								Signature: _		Signature:		Signature: _	
		Terminal Name:				PD		Good		Good		Good	
		Actual C/H:		SAMPLE WIRE		ЕМ		No Good		No Good		No Good	
								Signature:		Signature:		Signature: _	
		Terminal Name:		2004 - 20 may 22 A		PD		Good	_	Good		Good	
		Actual C/H:		SAMPLE WIRE		ЕМ		No Good		No Good		No Good	
								Signature: _		Signature:		Signature: _	
				Machine Error		_					<u> </u>		
A.	. TCM Error		B. Rear And Front Side Mis- crimping C.		Ov	er-Te	nsion Terminal		D.	Rear An	and the second second second		
E.	Mis- seal Insertion F. Dropped air Pressure G. Others: (Pls. specify)												
NOTE: (Stop the operation if encounter 3 consecutive machine error, Call the attention of Jr.Staff / Staff and Wait for further advise.)													
Sample made by production is ok to verified by Q.A. associate and no need to verify of EQD if error can be fix by production.													
	For	Tangled wire and measurir Wi	ng belt error n rite the actual	o need to attach sample but need measurement on the comment p	I to check th ortion of firs	e len t out	gth a	nd appea Inban.	rance of	actual sh	ikakari.		
Put <b>0</b> if GOOD, <b>X</b> if NO GOOD , / if NOT APPLICABLE.													
TUT O IT GOOD, A IT NO GOOD, I IT NOT APPLICABLE.													