

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 19 PK35467

NAME

Genito, Roselyn Matibag -

FROM

: PKIMT Management

SUBJECT

Notice for Suspension

No. of Offense

2nd offense

DATE

November 10, 2020

ACKNOWLEDGEMENT FORM

COMMENTS/ ASSESMENT

No. Offense: 2/11/
3 dayl Sw pengr

11 / 19-21/70

Line/shift Qf (SMM/K) 42R 5127

ACKNOWLEDGE BY:

MANAGER SIGNATURE OVER Printed name/ Date

This refers to the alleged offense(s) you have committed at

10/10/2020

to name:

Genito, Roselyn Matibag

Violation Offense No.

V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP in inspection process

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

10

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

Date & Time	October 10,2020/01:10
Shift & Group	N/S A
Car Maker/ Model	Suzuki Y2R
Line No.	5127
Name	Genito,Roselyn
ID No.	19PK35467
Batch No.	274
Process	QA
FAS or Agency: specify	PKIMT
Person Informed	J.Prado
Audited by:	M.Calim
Peacon/Pieks	

Reason/Risk:

Audit Details

Not following Visual inspection rule

Associate used wrong master sample VS running product

OK: 3660-59S**21**(2)-1-P NG: 3660-59S**11** (2)-1-P

QCA-097-00



Illustration

OFFENSE: DATE: NOvember 19, 2020

WRITTEN EXPLANATION:

sumusupport po ako sa line IIII Inpanel kupan tambakan rilaumalis po ako va line ang running product namin ay 521. Pagkatapos na po are in the namin na 3127 Floor damil tambak na Mnmag support bumalik namalman mall and dampot ng kasama kong QA, nag change product lang ng S11. Na check ko nameplate per it is nationpare may kaiba na pala- Napansin ko na lang na ibn my nung maglalagay na ng parstape- Multim no sono any inspect kaso norta na kame ny

Countermeasure:

· Liunahin po lagi i'check any nag na myolata-