

DISCIPLINARY ACTION MEMORANDUM

EMPLOYEE NAME: SORIANO, DHENS CLAIRE

EMPLOYEE NUMBER: BF-14239

DEPARTMENT: HONDA TKRA 3123) DAIHMSU 2103 A

DATE: OCTOBER 27, 2019

RECOMMENDATION:

This is in reference with your written explanation regarding your alleged violations of Maxim de Humana Int'l Inc. Employee Code of Conduct and Discipline under Article 8, OFFENSES AGAINST WORK/BUSINESS STANDARDS; section no. 7; Failure to follow business standards, operation procedures, work instructions or work practices which may or not result to damage of company property.

VIOLATION COMMITTED: Associate in NON-COMPLIANCE OR FAILURE TO FOLLOW THE STANDARD OPERATIONAL PROCEDURE IN INSPECTING PRODUCT, Inspector did not compare Actual harness to master sample. Inspector did not follow the proper way of checking connector, last September 19, 2019.

It is clearly stated in Maxim de Humana Int'l Inc., Code of Conduct and Discipline the grounds for this violation. As an employee, you are required to follow all the rules and regulations of our company. Your reason is not enough for you not to be given a disciplinary action.

In view of this, you are hereby given a Goven days Guspension for the said violation of our Employee Code of Conduct.

You are now forewarned that the next similar offense will already lead to a more severe disciplinary action.

PREPARED BY:

Mary Alanis V. Prago

MDHII HR COORDINATOR

NOTED BY:

MDHII BRANCH MANAGER

Employee's Signature Over Printed Name/Date

Received by:

RECOMMENDATION

Dec 1 9-12/16-18

11/24

rdinator bago ang suspension date

Dcc. 19,2019

SIGNATURE OF EMPLOYEE

an ito pagbalik after suspension bago mag Bam/g

DATE OF SUSPENSION:

VEED FOR REFRESHER:

BY:

SHIFT.

DATE RETURNED TO WORK

Signature Over Printed Name/Date



NOTICE TO EXPLAIN

EMPLOYEE NAME: SORIANO. DHENS CLAIRE

EMPLOYEE NUMBER: BF-14239

DEPARTMENT: HONDA TKRA 3123

DATE: OCTOBER 27, 2019

SUBJECT: OFFENSES AGAINST PRODUCTIVITY (200 OFFENSE)

You are hereby ordered to explain in writing five (5) working days from receipt hereof why no disciplinary action should be taken against you for alleged violation of our Code of Discipline under Article 8. OFFENSES AGAINST WORK/BUSINESS STANDARDS; section no. 7; Failure to follow business standards, operation procedures, work instructions or work practices which may or not result to damage of company property.

VIOLATION COMMITED: Associate in NON-COMPLIANCE OR FAILURE TO FOLLOW THE STANDARD OPERATIONAL PROCEDURE IN INSPECTING PRODUCT, Inspector did not compare Actual harness to master sample. Inspector did not follow the proper way of checking connector, last September 19, 2019, which is subject you to 6 to 10 Days Suspension.

Your failure to reply within period stated shall construed as admission of the above charges and/or waiver of your rights to present evidences for and in your behalf thus shall be the basis of the Management's decision.

PREPARED BY:		r K		
		lanis V. P	rago	
	MDHIII	HR COOR	DINATO	R
NOTED BY:	Ms. Cha	dy Dosor	10	
	unun b	CANCU M	IANACE	:D

EMPLOYEE'S EXPLANATION:

nony time po no nay inspect also may conduct po also my point to point then natapatory to very concetor so in aster sample para maketa lespo org pinaghaiba then no audit po also nong hindi trapo binoliat any concetor ny master sample dahil hindi trapo majket ny ayus jong concetor na iniiqueet ko dahil puro po tonidoshi at majiit lang po any payitan nila sa irat ira kaya po hindi trap sya na compone ny malapit pinagangako trapo na mas acyusin tro na ang payihippeot

NOTE: You may use an extra sheet as needed

SORTALD DHEATS CLATTE

Employee's Signature Over Printed Name/Date

Received by: ANOIL A. SOMON & halle

Signature Over Printed Name/Date

I ALERT WRITTEN EXPLANATION

· · · · · · · · · · · · · · · · · · ·	WILLEN EVERY	MATION	
FAS		Control No: =	ALP-11909-13
	·		ALP- 14- 1909 - 13
/ AGENCY			(00)
Please Specify: MDH//	,	M DE OCHMPO	A Ten
	•		6 Magadia
No. and A		Audited By:	Noted By:
Name: Solino, Ditals Claire	Process:	APPEARANCE	•
Position: KLOGNIE	Group/Shift:		
ID Number: 8F- H239	Date/ Time:	09-19-19 / 61:20 PM	
Batch No.:	No. of Offense:	2rd offense	•
Car Model/Line: #PNOA TRRA / 8123	Superior Name:	E. Matrin	
Details:	alunc 10 tollow the standard	operational procedure in	inspecting the pro
	•		
laspeater did not compare tectual harness	to Master Sample:	929424995=044522449544002474044 404 4440440744	>240442442 200 0444224 4 04
Inspector did not follow the pro	per way of docking con	Mcatx.	
************************************	***>>>>> = = = = = = = = = = = = = = = =	·	
M74A D-4474670000346597789977778204044 P#28046644 4467003464			

		\$200 \$4 00 \$4 9\$25040=\$9 \$ 62\$	
	***************************************	***************************************	*************************
Very Time			
Sung Time na now inspect po also nay co	conduct po ako no	point to point then ke	yeg sa competer
and intropect to ay ininababa Kepo	and Convertor of L	and the second	
TOPO IPOPOINTS POINT of may	coconpair if pareha	o po ha sika Lindi	150 600
e sya nahahawakan paraha ng nakaba	& dohr! so delan in	ika at 4 abok - 4 -	
	***************************************	***************************************	Rafit hi (*floon
Jin on ale make and	Allegador brooks black on the party of the second black of the party of the second black of the second bla		
lin po ako moghawak ng pareho ng	1 CONFOOT SA MOY	umpisa po ng portion	ng harness
and ha tompowend owner made contabe at	magyards pund na be	cherd per vinitualina	<i>A</i>
70° 110× (1717)17 110° 110° 110° 110° 110° 110° 110° 11			
quat contactor mas may import pope	also ng mabuti at	sistoradohin na manen	in bol
y need na operation so aking Acress	.74 h-1-1-5-5-4-4-5-4 4 11 11 14 44 5 5 5 5 5 5 5 5 5 5 5 5	Jagaren Jagaren	······································
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	.004444444444899999999944444994444449999999		Prochessa-respondentessa-ra-persoo
de pany i braddo paggan manyara i eddadassy estypt på estypty paggando by datende tod pagganda tod by paggan i	, zásvásza ang (vy ve pre zprážza zeszálásský mentessve speka);	***************************************	[448062 8440620644484H2001 b6+44+464 b.
profiscorreioniaco de priococamo de cristo para interpresenta de como propria establista de establista de como	***************************************		

182 \$52 000 00 7 00 00 00 00 00 00 00 00 00 00	1996P414F494P44949494F4444444444444444444444	***************************************	*********************
	************************************	***************************************	
;te	iterits/PameRinge		
		* ·	
n	11		•
Issue Pen	a/14.		
1300e 1910	· · /	,	-
	• •	•	

Signature of Employee
Date: 9-44-19

Jr Staff Date: 1/au/11 Staff
Date: 9124/14

2 HAZ Supervisor Date: 9-4-/0

Manader Date: 1/21



Master Sample, Registered Ballpen, Daily Checkshiets

Quality Assurance Inspection Board; IRCS; Passtape Supplying Machine

Final Assembly Proces

FALP-GL-FGI-16003, FALP-WI-QCA-15007

Samon Makely Supervisor

8. Karding Guldergo Majaris

Assistant Manager

Section Manager


Department Manager

Feb-23-2019 approved by:

Į

FALP-OP-003, FALP-OP-008, FALP-OP-012,

Final Assembly Assurance/Appearance Inst ection Process FALP-WI-QCA-15005



1. For preparation, conduct 5'S in inspection area and check the condition of inspection board and master sample base on the ME-DSSF1 Daily Check Record for Dimension, Appearance, Assurance Inspection Board and FGI-007 Master Sample Daily Inspection Record.

1.1 Check also the condition of tools and materials using forms of MEI-069F1 Daily Inspection Record of Measuring Tapes and QCA-023 Appearance/ Assurance Daily Checksheet of Tools and Materials.

there is no lacking harness, log in to IRCS using own QR code. shift, if there are lacking sets refer to FALP-GL-QCA-LS-143 Proper Treatment on tacking Hamess and II 1.2 After filling-out all daily inspection records, perform checking of lacking harness left by the previous

1.3 Get the harness from the hanger/polytainer and fill out the product information into the QCA-007 Final Assembly Procuss Inspection Record (If applicable).

daily sample hamess. Refer to FALP-GL-FGI-16003 Control of Master Sample will use Daily Sample provided by QA/PD Ir. Staff/Staff. Daily Sample Card must be attached on the NOTE 1: In case line has no master sample or the master sample was in no good condition, inspector

the actual harness for inspection NOTE 2: Product number of daily sample to be used must always be the same of the product number of



2. Lay out the wire harness into the inspection Board and barcode the

Note 1: Must layout one (1) harness at a time.

Note 2: For those products without na eplate, barcoding are not

actual product number running on insp Note 3: inspector must update the pr

before starting lacking harness to av-Note 4: In case of lacking set, finished

irst the ci



3. Get the ard of the harmass for inspection.

the polycard. icated on every nameplate if it is the same as the

2: Inspector must get the Issued polycard one at a time and only one and for the running product must be present on inspection area.





of hispection. Refer to FALP-OP-008 Quality Assurance Preparation terns Check Sheet of product and performing point to point system and Preventive Action for encountered problem/abnormality during Product and FALP-OP-003 Control of Nonconformities, Corrective for New Product, FALP-OP-012 Monitoring and Measurement of inspection, to inspection Process based on PPG-001 Inspection

WAIT for further instruction. Refer to FALP-WI-QCA-15007 the operation/inspection, CALL the attention of Staff/ir. Staff Note: In case inspector found NG or abnormality, STOP

Characteristics:

A Assurance Inspection (MAZDA)



4.1.3 Push the button for pass tape and attach to the harness.



/Appearance inspection. 4.1.4 Mark the pass tape using register belips n as indication that the harness pass the Assurance

ENG-001-03

Note 3: Check the plastic O1 no: 222K-025-E Note 1. Write also all the required marking [ex. markin 4.1.1 Sign the polycard as indication of person who person the polycard in polycard holder of the polycard in polycard in

Note 2. For harness that will undergo First Good inspi audit claim] in polycard bafore setting to polycard holds:

it. (refer in Good and No good

there is no dirt or marking on polycard holder. Ensure that