Service Support Building (SSB), Administration A

PPIP, Sto. Tomas, Batangas, Philippines Service Support Building (SSB), Tel: No. st (043), 405 6,388-89 / (043) 405, 6407-080. Tomas, Batangas, Philippines Service Support Building (SSB), Administration Aces 388 84 / Phase 406 6407 Sp. Tomas, Batangas, Philippines

MEMORANDUM NO. HRADM

TO

: 18 PK27195

NAME

Evangelio, Dorotea Montalbe

FROM

PKIMT Management

SUBJECT

Notice for Suspension

No. of Offense

1st offense

DATE

November 13, 2020

ACKNOWLEDGEMENT FORM COMMENTS/ ASSESMENT No. Offense: 101 - 2 days Purpersion 12/3-4/2020 Dok return 12/5/70 @ SAM Line/Shift / LUB/TRU 17107 CKNOWLEDGE BY

This refers to the alleged offense(s) you have committed at

11/10/2020

to name:

Evangelio, Dorotea Montalbo

Violation Offense No.

OFFENSES AGAINST COMPANY INTEREST

Section No.

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP in Dimension - Pulling of Branch due to short Dimension

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance

NOTED BY:

PKIMT Management

Conforme: /2

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

Suspersion date moned to

12/4-5/2000

Reason: Mayornor adjustness

Date refund: /2/2/20 8Am

Jonaly Moday

COMPLIANCE AUDIT REPORT (NS - Sherryl O. Duarte)

10-Nov-20

	location Actual Image	Findings/Items for Improvement Associate caught		Action Taken	Category	Operator	Person Informed	Incharge Car Model/ Department	Person Incharged	Status Remarks
\$ Sparu line 7107	The state of the s	pulling branch area of wire harness in	NG	Informed junior staff regarding this matter and advised member to follow Inspection sop	SOP	Dorotea Evangelio - PKIMI	Jhona Alday	Subaru	Sir the	For Monitoring



	OFFENSE: NOT. FAILED IN SOF	DATE: 1/12/76
	WRITTEN EXPLANATION:	
No.	Coop 6m:	
	Also trossi touriten trangelis, trimencim	inspection my line mor Ma andit
	to ano dant an programos to mg	Combine ny haveness, 2 branch as
	Case Jung Kino Combine manyon to mai	not be some one illimite
	Or young Combine min how he and	I have my land on be
	ble young Combine was base to nake to	In Jung Asm Mahm na branch.

Countermeasure: Oalamat to ...

Mext time naka encounter no ganting gitwayon, tatawagin to po

Signature over Printed Name / Line