

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORA	NDUM NO. HRADM	ACISNOWLEDGE MENT FORM COMMENTS, ASSESMENT
ro	: 19_PK30770	No. Offense: 15T / Lay
NAME	Frane, Jessa Marcaida	11/11/19 / day
FROM	: PKIMT Management	
SUBJECT :	: Notice for Suspension	
No. of Offense	: 1st offense	ACKNOWLEDGE BY:
DATE	October 21, 2019	MANAGER WATNETM 10/21/11

This refers to the alleged offense(s) you have committed at

9/19/2019

to name:

Frane, Jessa Marcaida

Violation Offense No.

V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme: /

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines

Tel No.: (043) 405 8388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 19 PK30770

NAME

Frane, Jessa Marcaida

FROM

: PKIMT Management

SUBJECT

Notice to explain

No. of Offense

1st offense

DATE

18-Oct-19

This refers to the alleged offense(s) you have committed at

19-Sep-19

to name: Frane, Jessa Marcaida

Violation Offense 1 5

OFFENSES AGAINST COMPANY INTEREST

Section No.

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY

PKIMT Management

18 8430770

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

I ALERT WRITTEN EXPLANATION

FAS		•	Con	trol No: <u>FALP-18</u> -	1909-1
AGENCY Please Specify:	PKIMT		JR · REVE		agadia ed By:
Position: According to the Position: 19.Ph Batch No.: 20	***************************************	No. of Offense:	Appearance \$ 10.5 69-19-19 261	ce / 08:30Am	ей ву:
Car Model/Line: Suzul Audit Findings:	ki 101 LC120 Non-Compliance or failum	Superior Name to follow thoutag	: A. Lomo ndard yparation	al procedure in imp	
Inspector did not Inspector did no	compare actual har follow the proper r t follow the proper t	vay of check reatment whe	aincy Connecto n encountered	r d abnormalit	Χ

Ako bo ay	ngudit dahil di	EXPLANATIO		may con pari	
rieu po cej	icompart sq m	aster simple		ika ophin n	•
mahilaip din po	o po mailled you	4. In a 144.	eijcliching	estimator, n	-14 / /
	·····	4. In a 144.	eijcliching	<i>j</i> ·	-14 / /
	o po mailylad yw	4. In a 144.	eijcliching	estimator, n	-14 / /
	o po mailylad yw	4. In a 144.	eijcliching	estimator, n	-14/1
	o po mailylad yw	4. In a 144.	eijcliching	estimator, n	-14/1
	o po mailylad yw	4. In a 144.	eijcliching	estimator, n	-14/ <i>1</i>
	o po mailylad yw	4. In a 144.	eijcliching	estimator, n	ala lin
mahilap din po po kaya di k som na din po	o po naivipad yw II will in it is a mil ang makir sample -	n proper a Leala ha and Stevaluation:	ey decliny an po ta y hand count	estimator, n	-14/ <i>1</i>
mahilap din po po kaya di k som na din po	o po naivipad yw II will in it is a mil ang makir sample -	n proper a Leala ha and Stevaluation:	ey decliny an po ta y hand count	estimator, n	-14/1/
	the of Appearman	n proper a Leala ha and Stevaluation:	ey cheding to the	complete, he mbak, p. al	-14/1/

ALL

Final Assembly Assurance/Appearance Inspection Process

Feb-23-2019

WORK INSTRUCTION

FALP-OP-003, FALP-OP-008, Quality Assurance Inspection Board; IRCS; Passtape Supplying Machine

Quality Assurance Inspection Sets Mankoring Form; MB: TO Serve as instruction for Daily inspection Records | Quality Assurance Inspection Master Sample, Registered Ballpen, Daily Checksheets

FAIP-GL-QCA-(S-143, FAIP-GL-FGI-16003, FAIP-WI-QCA-15007 22K-025-E Final Assembly Process

Department Manager Takahide Maruoka Section Manager 8. Rainifert Buillanno Magaul Assistant Manager Supervisor



1. For preparation, conduct 5's in inspection area and check the condition of inspection board and master sample base on the MEI-055F1 Daily Check Record for Dimension, Appearance, Assurance Inspection Board and FGI-007 Master Sample Daily Inspection Recerd. 1.1 Check also the condition of tools and materials using forms of MEI-069F1 Daily inspection Record of Measuring Tapes and QCA-023 Appearance/ Assurance Daily Chacksfreet of Tools and Materials.

shift, if there are lacking sets refer to FALP-GL-QCA-LS-143 Proper Treatment on Lacking Harness and if there is no lacking harness, log in to IRCS using own QR code. 1.2 After filling-out all dally inspection records, perform checking of lacking harness left by the previous

1.3 Get the harness from the hanger/polytainer and fill out the prøduct information into the Q.C.A.007 Final Assembly Process Inspection Record (if applicable).

NOTE 1: In case line has no muster sample or the master sample was in no good condition, inspector will use Dally Sample Grd must be attached on the dally sample harness. Refer to FALP-GL-FG1-16003 Control of Master Sample NOTE 2: Product number of daily sample to be used must always be the same of the product number of the actual harness for Inspection, 4.1 Inspection flow/procedure for product which are required to parcode the polycard in polybox.

4.1.1



pection Board and Sarcode the 2. Lay out the wire harness into the In

Note 1; Must fayout one (1) harness at a time.


eplate, barcoding are not Note 2: For those products without nary

រព (abel card អ្នងនេះស្ Note 3: Inspector must update the prod Note 4: In case of lacking set, finished before starting lacking harness to avoid actual product number running on Ins

st the cu

Vote 2: Inspector must get the issued polycard one at a time and only one ာ်စျိန်ညီard for the running product must be present on inspection area.





4.1.2

4.1.3 Push the button for pass tape and attach to the harness.



4.1.4 Mark the pass tape using register ballpen as indication that the harness pass the Assurance Appearance Inspection,

and Preventive Action for encountered problem/ abnormality during Product and FALP-OP-003 Control of Nonconformities, Corrective Note 1. Write also all the required masking [ex. marking fig castomer hain audit claim] in polycard before setting to polycard holder (fightplicable). 4.1.1 Sign the polycard as indication of person who part set/put the polycard in polycard holder of the polybox Note 2. For harness that will undergo

system 4.1.2 Proceed to Inspection Process based on PPG-001 Insyltems Check Sheet of product and performing point to poin for New Product, FALP-OP-012 Monitoring and Measurem of inspection. Refer to FALP-OP-038 Quality Assurance Preg

the operation/inspection, CALL the attention of Staff/in. Staff WAIT for further Instruction. Refer to FALP-Wi-QCA-15007 is Note: In case Inspector found NG or abnormality, STOP Assembly Process Defect Flow.

A Assurance Inspection (MAZDA) Characteristics:

EFF:04/09/18

there is no dirt or marking on it. (refer in Good and No good polycard holder. Ensure that Note 3: Check the plastic OI nO: ZZZK-025-E

condition beside)



Title:

Control of Minor Defect

_	_	_
-		Page 3 of 6
FALP-GL-QCA-MD-011	February 15, 2019	1/1
Decument Notes	Effective Date:	Revision Non-
Guideline	QA Department	QM-SMG
On the second second		controlled by a

loose comp/ long band tall or a for those lines which are ollowed to use side cutter. Note: Repaining of Other affected portions with the minor repair shall also be checked Loose tiamp/long band tail

Need to use side cutter for trpa ring measurement of product [FALP-CP-012] and Final Assembly Process Deject Flow (FALF-WI-QCA-15007), Fil up Rework Tag (Orange Tag) Attach "red tag" and te er to Monitsring and check/ verify the repaired portion Jr. Staff/Staff certified expert Continue to Inspection Q S Ir. Staff/Staff verify the content of defect and categorize if minor-defect. Assembly Minor Defect Re zord Assurance/ Appearance Inspector found minor de ect. Inspector call the attention of Jr. Staff/ Staff of the (he taping defect Start Inspection 5. PROCESS FLOW CHART 3/0 nspector needs to fill up the Final Assembly Minor Defect Record Staff/ Jr. Staff will put the marking missing marking

CONFIDENTIAL. This document is a scale pre-zerly of FURUXAWA AUTOMOTIVE SYSTEAS, Lina Philis, Inc. NA to be reproduced or photocopied without prez approval of the DCC.

Document Sterrip

DCC-028-00; EFF: 05/02/2017

FURUKAWA AUTOMOTIVE SYSTEMS

LIMA PHILIPPINES, INC.

Control of Minor Defect

Title:

Classification	Guideline	Document No.	FALP-GL-QCA-MD-011	11
Issued by:	QA Department	Effective Date:	February 15, 2019	
Document Controlled by:	QM-SMG	Revision No.:	1/1	Page 4 of 6

6. PROCEDURE DETAILS

- 6.1 Inspection Process found Minor Defect.
 6.2 Inspector stall call the attention of Jr. Staff/Staff if defect was encountered during inspection by the use of ANDON light.
- Jr. Staff/Staff shall confirm/ verify the content of defect and categorize if Minor or Major Defect. 6.3
- Monitoring and Measurement of Product (FALP-OPQ12), and Control of Nonconformities, Corrective and If defect is Linor, after repair was conducted, inspectorshall record the defect at Final Assembly Process Stockect Tag Final Assembly Process) and refer to If defect was verified as Major, attach red tag (CPA.) Preventive Action Procedure (FALP- OP- 003), Minor Defect Record. 6.4
- Only authorized Jr. Staff/Staff shall conduct repails of Minor defect at Inspection table. Certified Expert is also allowed to conduct repair on inspection table but limited on taping repair and missing markings only... 6.5

NOTE: If the Jr. Staff/Staff was assigned) बुआ़ nspector, he/she is not allowed to conduct minor repair on the harness under inspection.

- For taping repair, only additional aping repair is allowed to be done at inspection table. Ir. Staff/ Staff/ Certified Expertare allowed.
 - After toping repair was conducted on harness, Inspector needs to fill-up properly QCA-008 Final Assembly Process yithor Defect Record and shall check/verify the following items thru Inspection Board/ Master sample harness:
- a. Proper arrangement of branches on the affected portion.
 b. Correctings of applied on affected portion.
- Dimer stook of the repaired and related portion where the repair is conducted.

applied With marking is allowed to be done on inspection table. Jr. Staff/ Staff/ Certified Expert are For missing marking, application of marking after checking actual condition of harness/ parts to be

hispector need to fill-up properly QCA-008 final Assembly Process Minor Defect Record and shall also theck/verify the following thru Inspection Board/ Master sample harness after marking was applied off)harriess/ parts:

CONFIDENTIAL. This document is a sole property of FARUKAWA AUTCAKOTIVE SYSTEMS, Lins Pribs, Inc. Not to be reproduced or photocopy, if without prior apprent of the DCC.

DCC-026-00; EFF: 05/02/2017

Document Stamp

