

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMOD	INDUM NO.	TIDADAR
IVERSIVE PER	4 / V # F # / I V # / V # F	H-1 HE ALL HINNE

TO

: 18 PK27619

NAME

FROM

Reves. Jun Sabile

: PKIMT Management

SUBJECT

: Notice for Suspension

No. of Offense

: 1st offense

DATE

October 24, 2019

COMMENTS/ ASSESMENT

No. Offense: BT | Lay

BCT XC, 2019

Line QA - 85124 | B

KNOWLEDGE BY:

AGER BRAINLEZ

Signature Over Printed name/ Date

ACKNOWLEDGEMENT FORM

This refers to the alleged offense(s) you have committed at

9/18/2019

to name:

PKIMT

Reyes, Jun Sabile

Violation Offense No.

*

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme: 18 PK27619

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines

Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 18 PK27619

NAME

Reyes, Jun Sabile

FROM

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense

1st offense

DATE

18-Oct-19

This refers to the alleged offense(s) you have committed at

18-Sep-19

to name: Reyes, Jun Sabile

Violation Offense | V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme:

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

LALERT WRITTEN EXPLANATION

	I MEETI VOITI	I LIV LAIV	AIION	
FAS		(4)	Control No:	FALF. 19- 10tg. 1383
AGENCY Please Specify	z KNNUJ		Ylbut Urbarto Audited By:	G Magadia Noted By:
Position: 49 ID Number: 18 Batch No.: 26 Car Model/Line: 31 Audit Findings: Details:	Non-connphones or yell 31 51 3 50 0 51 5 700 462 700		*	the product.
(1) Inspector did	not follow on troper	Logy be check	THE CONNECTOR	
Albuit this ins a proper way side back ci insertion sorry of our common time that its And I Jun connector and As a Quartify that should a	ident, I'm seally son of checking of can decling of can decling of can decline in the seal of the seal	heater, from right might the it hast to eat point to the project that the project the project that the project that the project that the project th	1 know that morting part then the lass inc because a atic why the atic why of a whath is a 20P of it at all be one of	there is then front t is the the some there a checking had checking thmes the mapany
	Rema	rks/ Evaluation:		
	Issue Panalt	, T		

Signature of Employee
Date: 1/4/1/1

J. Ringman Jr Staff Date: 77

Date: 9/14/4

Supervisor Date: 10-0-19

Mahager Date: 0-3-19

FURDICAWA AUTOMOTIVE SVETENC				NOOCON	DOCUMENT TYPE:	WORK INSTRUCTION	WORK INSTRUCTION PAGE NO. 1 OF
LIMA PHILIPPINES. MC.	PROPER	VAY OF CHECKING CONNECTOR	CTOR	DOCUL	DOCUMENT NO.:	REVISION NO.:	EFFECTIVITY DATE:
				FALP-WI	FALP-WI-QCA-15008	3	May-08-2019
CAR MODEL	MATERIALS	DEVICES / EQLIPMENT USED - FINE	REFERENCE	ラボールの出版を選択が出来	のは、日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日	APPROVAL	· · · · · · · · · · · · · · · · · · ·
19	N/N	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Prepared by:	Checked by:	Verified by:	Approved by:
7		Alignment jig	FALP-CP-OCA-17074				
FORMS	PURPOSE	3doos Section 1	FALP-WI-QCA-15015				
d Z	To set instruction on how to check the condition	m Final Accomply Dennes	FALP-GL-ESH-18006	L. Mindanao	S. Morfe	B. Ramirez	A. Nachor / T. Maruoka
	of connector properly			Staff	Supervisor	Asst. Manager	Sec. Manager / Dept. Manager

Checked by:		5. Morfe	Supervisor
Prepared by:		L. Mindanao	Staff
	FALP-CP-QCA-17074 FALP-WI-OCA-15015	FALP-GL-ESH-18006	

Y		7	100000000000000000000000000000000000000
NA PARTIES			
À	1	¥.	4
			6

NOTE 1: Slightly touch the retainer using thumb finger from left to right, and right to left to be checked if the FALP-WI-QCA-15015 Proper Method on Pressing and retainer is already locked or unlocked refer to

NOTE 2: TBO can be detected if encountered half

situated on different location.




Checking of Retainer lock

1. No damage part (all edges must check)

2. No fore gn matter attached
3. No excess burn
4. No ball locked retainer

locked/imperfect locked of retainer.





NO GOOD condition on proper way of checking connector.

WARNING 1. Stop the Production or Process 1) In case of Abnormalities, Please

2. Call the attention of Jr. Staff / staff

insertion part of connector

3. Wait for further advise

2) Wear proper PPE. (Refer to FALP-GL-ESH-18006 Personal

(3) Be careful not to cause injury during inspection of





H

connector lock position (unless otherwise specified) of connector based on Check front side

No wrong part
 No damage part (all edges must check
 No foreign matter attached
 No excess burn

CAUTION:
Do not insert your finger inside the connector mating part during inspection!

• Check the mating part of connector

1. No terminal backing out (must check in vo.

2. No damage part (all edges must check).

3. No foreign matter attached

8. Presence of red mark (for male connectors that has alignment jig) 9. Presence and condition of pack in rubber seal (applicable for water proof connectors).

7. No wrong plating of terminal (gold/tin)

5. No deform part of connecto



9

M

4



Check the insertion part of connector

ction Criteria for Damaged

1. No damaged cayity (refer to FALP-CP-QCA-17074 Inspired

1. To damage part (all edges must check · Check left side of connector

3. To excess bun
4. To deform part of connector To foreign matter attached

No damage part (all edges must check)
 No foreign matter attact ed
 No excess burr
 No deform part of connector

· Check right side of connector

able damage condition).

4. Presence and condition of gomusen and tsumesen 2. No damaged insulation/expesed core wire. 3. Condition of inserted wire (no pulling out or TBQ).

NOTE: Proper way of bending branch when checking the a. Bending portion must be <u>60mm</u> away from neck of con Avoid too much bending of aranch connectors). NOTE: Proper way of b

Protective Equipment (PPE) for the applicable PPE

First Issue per ISO 9001:2008 Quality Management System Oct-21-2016 Jul-25-2015 A3a-1507-027

