

--Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

···		PKIMT	ACKNOWLEDGEMENT FORM
MFM	ORANDUM NO.`HRADM	X	COMMENTS/ ASSESMENT
JVI 15/1/1	ORANDOM NO. HRADM	No. Offense:	<i>.</i>
ТО	: 17_PK19408	tor	\$ 0000 m
	_		MARCH 4 ~ 8, 2019 MARCH 4 ~ 8, 2019 MARCH 9, 2019
	Lescano, Gemmalyn Cabiscuelas Holum		4~ B, 2019
	•	-	march 9 2016 /
FROM	: PKIMT Management	Line (CL) RCJK	1 1/13
31 H3 H3 CM	AT At the Confidence of the second confidence	Jr. Staff	·
SUBJECT :	: Notice for Suspension	Staff	Ω
No. of Offense	: 1st offense	ACKNOWLEDGE	mut 100
40. Of Official	. 150 01101150		CH Haya
DATE	15-Feb-19	MANAGER	Signature, av P. e. 1 dia o'Oate
		<u> </u>	Signature (1997 Province Gard Date
This refers to the	alleged offense(s) you have committed at 4-Feb-19	to name:	Lescano, Gemmalyn Cabiscuelas
ims reters to the	The state of the s	to name.	Ecocatio, ocininary ii cabiscucius
			-
Violation-Offens			
	OFFENSES AGAINST COMPANY	Y INTEREST	•
Section No. 14			·
Omission or co	mmission of an act in connection with or against the poli		
	the particular duties and responsibilities inhere	ent to the emp	loyee's work
Description:			
Description			
	Not Follow SOP in Lay - out	process	
You are hereby g	iven 5 days upon reciept of this letter to explain in writing w	hy you should	not given a disciplinary action for
<u>offense. Failure t</u>		ie process and	the company has no recourse but to
implement the pe	o comply would mean you voluntarily waive your right to du		
	o comply would mean you voluntarily waive your right to du nalty provided for based in our company rules and regulation	ns	
	o comply would mean you voluntarily waive your right to du malty provided for based in our company rules and regulation	ns	
This is for your g	nalty_provided for based in our company rules and regulation	ns	
This is for your g	o comply would mean you voluntarily waive your right to durable provided for based in our company rules and regulation uidance and strict compliance.	ns	
This is for your g	nalty_provided for based in our company rules and regulation	ns	
	nalty_provided for based in our company rules and regulation	ns	
This is for your g	nalty_provided for based in our company rules and regulation	ns.	
	nalty_provided for based in our company rules and regulation	ns.	
	uidance and strict compliance.	ns.	·
NOTED BY: All Mayon; PKIMT Manage	nalty provided for based in our company rules and regulation uidance and strict compliance.	ns.	
NOTED BY:	nalty provided for based in our company rules and regulation uidance and strict compliance.	ns.	

FURUKAWA - Production Operator
(Please attach your written explanation upon returning of this letter)

 $\langle \cdot \rangle \bigg)_{i_0}$

17_PK19408

 Γ



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

: 17 PK19408

FROM

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense: 1st offense

DATE

: 11-Feb-19

This refers to the alleged offense(s) you have committed at

4-Feb-19

to name: Lescano, Gemmalyn Cabiscuelas

Violation Offense No.V

OFFENSES AGAINST COMPANY INTEREST

Section No. 10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not Follow SOP in Lay - out process

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme: ____ 17_PK19408

FURUKAWA - Production Operator

(Please attach your written expalanation upon returning of this letter)

Date:February 04,2019

Line:Suzuki Line 5113-B

Agency; PKIMT

Ma`am

Safety first po!

This is to inform that Ms.Gemmalyn Lescano(almost 8 months on process) is our top contributor of crosswire at layout process. She has a total of 7 crosswires for the month of December, 8 crosswires for the month of January and currently has 2 consecutive crosswire for the first week of February . Upon observation she was not consistent in referring to assy drawing and not following her sequence inspite of frequent instruction and re-orientation. In this situation, we need to consider the quality of the line and we decided to transfer her to other process without insertion.

Prepared by:

Rona Vivar

PD4 Staff

Plan isme 1 h. hh 2/1/19

WRITTEN EXPLANATION

Name: Lacano, Semnalyo Violation: Not following Sp Line 5/13	Date: 24/19 No.of violation:
Reason: ako po ay nag kanoon ng wrong kadahilanan po na di aho gum ng rayity. At di ko pagtingin	insert sa sub 14. s namit ng pagbibila n sa sub dimwing
Countermeasure:	
magbibility ng po alo ng	line at cayity mg
bowat connector na pag in	insertan ko po.
Titingin na din po ako s	sa subdam wing
	•
GE MAR OF GIND EMPLOYEE	Prumi T. Imum SUPERVISOR
JR.STAFF	SECTION MANAGER
STAFF	

DATE	OCCURRENCE PROCESS	RESPONSIBLE PERSON	PRODUCT NAME	LOT NO	SERIAL NO	Defect Category	Defect Category No.	DEFECT DETAILS / DESCRIPTION
3	LAYOUT	GEMMA B	36602-53RF0	59WD10	00010		9	WRONG INSERT ON JSN-32F-GR GR/ L1C1 NG: L2C1 CIVUS 0.35
5	LAYOUT	GEMMA B	36602-53R80	59WD08	00015		00009	WRONG INSERT ON JSN-32FA-SB SB/ L1C11 NG: L1C10 CIVUS 0.35
5	LAYOUT	GEMMA B	36602-53RJ1	59WD81	00004		00009	ON JMX5-20FA-K R/ L2C9 NG: L2C10 LG/ L2C10 NG: L2C9
7	LAYOUT	GEMMA B	36602-53RF0	59WD13	00071		00009	WRONG INSERT ON JSN-32F-GR VI/ L1C3 NG: L1C6
7	LAYOUT	GEMMA B	36602-53RF0	59WD13	00063		00009	WRONG INSERT ON JSN-32F-GR Y/ L1C11 NG: L1C1 CIVUS 0.35
7	LAYOUT	GEMMA B	366023-53R70	59WD05	00015		00009	WRONG INSERT ON JMX5-20FA-L R/L2C9 NG: L2C10
9	LAYOUT	GEMMA B	36602-57R20	59WZ71	00072		60000	WRONG INSERT ON CONN. JMX5-20FA-L VI/ L1C9 NG: L2C10 CIVUS 0.35
29	LAYOUT	GEMMA B	36602-53RJ1	59AY33	00052		00009	WRONG INSERT ON JMX5-20FA-L LG/L2C10 NG: L2C9
		•						

19	18	14	10	ъ	4	1	DATE
483	453	361	199	83	48	21	REWORKIN G ISSUE NUMBER
5113	5113	5113	5113	5113	5113	5113	LINE NO. /
SHIFT B	SHIFT B	SHIFT 8	SHIFT B	SHIFT B	SHIFT B	SHIFT B	GROUP NAME/ SHIFT NO
LAYOUT	ECT	LAYOUT	LAYOUT	ECT	LAYOUT	LAYOUT	PROCESS DETECTED
LAYOUT	LAYOUT	LAYOUT	LAYOUT	LAYOUT	LAYOUT	LAYOUT	OCCURRENCE PROCESS
GEMMA B	GEMMA B	GEMMALYN B	GEMMA B	GEMMA B	GEMMA B	GEMMA B	RESPONSIBLE PERSON
	1				0.00.007070		
							Defect Category
				00009	00009	9	Defect Category Defect Category No.