

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 19 PK31042

NAME

De Guzman, John Carlo Gutierrez

FROM

: PKIMT Management

SUBJECT

: Notice for Suspension

No. of Offense

1st offense

DATE

October 23, 2019

iday Suspers

64 74, 1049

Line QA - HMM /A

ACKNOWLEDGE BY:

MANAGER Signature Over Printed name/ Date

ACKNOWLEDGEMENT FORM

COMMENTS/ ASSESMENT

This refers to the alleged offense(s) you have committed at

9/23/2019

to name:

No. Offense:

De Guzman, John Carlo Gutierrez

Violation Offense No.

V

OFFENSES AGAINST COMPANY INTEREST

Section No.

10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Fallure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Management

Conforme:_

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines

Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 19 PK31042

NAME

De Guzman, John Carlo Gutierrez

FROM

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense

: 1st offense

DATE

18-Oct-19

This refers to the alleged offense(s) you have committed at

23-Sep-19

to name: De Guzman, John Carlo Gutierrez

Violation Offense | \

OFFENSES AGAINST COMPANY INTEREST

Section No.

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description

Not following SOP in inspecting the product

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

10

NOTED BY

PKIMT Management

Conforme:_

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)

I ALERT WRITTEN EXPLANATION

	FAS	ato.		Control No:	FMP-1A-1909-1452
	AGENCY				(10)
		ecify: PKIMT		M. DE OCHMPO	G. Magadia
		P		Audited By:	Noted By:
	Name:	DEGUZMAN, JHON CARLO	Process:		/ Noted by:
	Position:	ASSOCIATE	Group/Shift:	OA	,
	ID Number:	19. PK 31042	Date/ Time:	# 1 ns	
	Batch No.:		No. of Offense:	9-23-19 / 1:10 Pm)
	Car Model/Line:	256 TKKA / 3130	Superior Name:	A - RABANO	
	Audit Findir				dure in inspecting the pondu
÷	Details:				our macangmores
	Inspector di	d not follow the proper Wo	gy of checking connec	ctor.	

				***************************************	***************************************

		A STATE OF WRITING	EN EXPLANATION		
					SHIP WHO SHIP SHOULD SH
	. I ques	s i did the proper way o	of checking the co	nnectors - l'us compo	ared the
19	1 1	s I did the proper way o	F checking the co		
9	actual harness	s I did the proper way o to master sample and that there is another property	is also did the property of the control of the property of the change of	point to point system	
,	actual harness didn't know	to master sample and that there is another w	i also did the parties of the ching the	point to point systeme connectors.	em. But i
	actual harness didn't know My w	to master sample and that there is another will law of checking these conv	i also did the p energing of oneching the ector is I check	point to point systeme connectors. First the mating p	em. But i
,	actual harness didn't know	to master sample and that there is another will any of checking these connections there is a master sample there	i also did the p energing of oneching the ector is I check	point to point systeme connectors.	em. But i
,	actual harness didn't know My w	to master sample and that there is another will law of checking these conv	i also did the p energing of oneching the ector is I check	point to point systeme connectors. First the mating p	em. But i
	actual harness didn't know My w	to master sample and that there is another will any of checking these connections there is a master sample there	i also did the p energing of oneching the ector is I check	point to point systeme connectors. First the mating p	em. But i
	actual harness didn't know My w	to master sample and that there is another will any of checking these connections there is a master sample there	i also did the p energing of oneching the ector is I check	point to point systeme connectors. First the mating p	em. But i
	actual harness didn't know My w	to master sample and that there is another will any of checking these connections there is a master sample there	i also did the p energing of oneching the ector is I check	point to point systeme connectors. First the mating p	em. But i
	actual harness didn't know My w	to master sample and that there is another will any of checking these connections there is a master sample there	i also did the p energing of oneching the ector is I check	point to point systeme connectors. First the mating p	em. But i
	actual harness didn't know My w	to master sample and that there is another will any of checking these connections there is a master sample there	i also did the p energing of oneching the ector is I check	point to point systeme connectors. First the mating p	em. But i
	actual harness didn't know My w connector with start check	to master sample and that there is another will any of checking these connections there is a master sample there	i also did the person of checking the color is a check and down of the color of the	point to point systeme connectors. First the mating play master—sample	em. But i
20	actual harness didn't know My w convector with start check	to master sample and that there is another will any of checking these connector the master sample ther all sides of the connector	i also did the participant of checking the checking the checking the check of down to the check of the check	point to point systeme connectors: Eirs! the mating play industry sample	em. But I
20	actual harness didn't know My w connector with start check	to master sample and thul there is another wo lay of checking these comm the master sample ther all sides of the connector	i also did the person of checking the ector is a check of dropped down is	point to point systeme connectors. First the mating play master—sample	em. But 1
20	actual harness didn't know My w connector with start check	to master sample and that there is another will any of checking these connector the master sample ther all sides of the connector	i also did the person of checking the ector is a check of dropped down is	point to point systeme connectors. First the mating play master—sample	em. But 1
	actual harness didn't know My w connector with start check	to master sample and thout there is another wo may of checking these connector the master sample ther all sides of the connector	i also did the penetring of the children is I check to I dropped down is	point to point systeme connectors. First the mating play master—sample	em. But 1
	actual harness didn't know My w convertor with start check	to master sample and thout there is another wo may of checking these connector the master sample ther all sides of the connector	i also did the person of checking the ector is a check of dropped down is	point to point systeme connectors. First the mating play master—sample	em. But 1
	actual harness didn't know My w convertor with start check	to master sample and thout there is another wo may of checking these connector the master sample ther all sides of the connector	i also did the penetring of the children is I check to I dropped down is	point to point systeme connectors. First the mating play master—sample	em. But 1
	actual harness didn't know My w convertor with start check	to master sample and thul there is another wo lay of checking these comm the master sample ther all sides of the connector	i also did the penetring of the children is I check to I dropped down is	point to point systeme connectors. First the mating play master—sample	em. But 1
	actual harness didn't know My w convertor with start check	to master sample and thout there is another wo may of checking these connector the master sample ther all sides of the connector	i also did the penetring of the children is I check to I dropped down is	point to point systeme connectors. First the mating play master—sample	em. But 1

Signature of Employee Date: 10/02/10

ARABAND Jr Staff Date:しつしょり

White Multar Staff Date: 10-02-19

PIL. m. DPANA

Supervisor Date: 10-2-19

Manager Date:

FURUKAWA AJ DANOTIVE SYSTEMS	TIVE SYSTEMS			NUDOG	DOCUMENT TYPE:	WORK INSTRUCTION	PAGENO: 1 OF
TIMA PHILIPPINE, INC.		PROPER WAY OF CHECKING CONNECTOR		DOGUN	DOCUMENT NO.:	SON NCISIVAR	EFFECTIVITY DATE:
				FALP-WI-	FALP-WI-QCA-15008	3	Mav-08-2019
CAR MOCEL MA	MATERIALS STREET STREET	DEVICES / EQUIPMENT USED	REFERENCE			APPROVAL	100mm 100m
NA I	-> 14			Prepared by:	Checked by:	Verified by:	Approved by:
	44 /	Alignment Jig	CALD OD OD A 4707				
FORMS	Ogana Bugana	SCOPE STATE	FALP-WI-QCA-15015				
M/A	To set instruction on how to check the condition	o check the condition	FALP-GL-ESH-18006	L Mindanao	S. Morfe	B. Ramirez	A, Nachor / T. Maruoka
	of connector properly	SCOOL AND THE WASHINGTON		Staff	Supervisor	Asst. Manager	Sec. Manager / Dept. Manager
						-	
			THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO I		APPROXIMATION OF THE PROPERTY OF THE PERSON		THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN



connector lock position (unless otherw specified)

1. No termina backing out must steck in v 2. No damage part (all edges muss check) 3. No foreign marter attached . Check the mating part of consector

red mark (for male



 No damage part (all edges must check)
 No foreign matter attached Check backside of connector.



NOTE 1: Slightly touch the retainer using thumb finger from left to right, and right to left to be checked if the retainer is already locked or unlocked refer to FALP-AVI-QCA-15015 Proper Method on Pressing and Checking of Retainer lock.

NOTE 3: These applies to all connectors except special connectors where in retainer and connector lock are situated on different location. NOTE 2: TBO can be detected if encountered half locked/imperfect locked of retainer,



NO GOOD condition on proper way of checking

1 WARNING

Check the insertion part of connector
 L. No damaged cauty (refer to FALP-CP-QCA-27074 Inspect on Criteria for Damaged
 on Insertion Part of all Common Connectors, for the accentable damage condition),
 No damaged insulation/exposed core wire.

Ne damage, part (all edges must · Check left side of connector

· Check right side of cornector

1. No damage part (all edges n

2. No foreign matter attached

4. No deform part of connect

m

4

4 No deform part of connector No foreign matter attached

Condition of inserted wire mo pulling out or TBO).

 Stop the Production or Process
 Call the attention of Jr. Staff / staff 1) In case of Abnormalities, Please

3. Wait for further advise

(2) Wear proper PPE. (Refer to FALP-GL-ESH-18006 Personal Protective Equipmen: (PPE) for the applicable PPE

NOTE: Proper way of bending branch when checking the insertion part of connector a dending portion noist be 68mm away from neck of connector, by Ayold too much bending or branch.

be <u>68mm</u> away from neck of com 1g of branch.

(3) Be careful not to cause injury during inspection of

BRACKER	Toursday No.	STATE OF STREET		
	OF THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE	THE STORY WATER	· · · · · · · · · · · · · · · · · · ·	Pekalis pri change
QA-QCA-13a-2905-015	3	May-C8-2019	Additional warning information regarding salety purposes (Wear Proper PPE Personal	dictional warning information regarding safety purposes [Wear Proper PPE Person and Protective Equipment (Refer to FALP-GL-ESH-18006), Be careful not to cause injury during inspection and packing of wir
QA-QCA-I3a-1727-001	2	Jul-24-2017	Align sequence of checking to current process [sequence ro. 2.3,4,8.5]; changes on private item no. 6; additional instruction and note on sequence no. 1,3,4,5,8.6]; Remove alreading of derion notations barrel and bend-up/down terminal (checked from of initial process) (sequengered and condition of germusen and teamesent) and additional note for proper by notating of breather during checking of connector (sequence no. 6); additional reference	Align sequence of checking to current; process [sequence ro. 2.3,4,8.5]; changes on pitture item no. 6; additional instruction and note on sequence no. 1,3,4,5,86]; Remove check item for (color/size/type of aircardy checked item of unitial process) (sequence no. 6); Additional check item of some condition of genuses and stansesen) and acaditional check for prope binding of branch during checking of connector (sequence no. 6); additional reference
A3a-1610-007	1	Cct-22016	Cct-220.5 Upcarte the sequence number of Process, additional comment for sequence No. 1 tem No. 8	No.8
A3a-1507-022	0	Jui-25-2015	Jui-25-2015 First issue per ISO 9001:2008 Quality Management System	
		The same of the sa		

