

Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines
Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

TO

: 18_PK25298

Gadil, Riela De Boria

FROM

: PKIMT Management

SUBJECT

: Notice for Suspension

No. of Offense

: 1st offense

DATE

March 11, 2019

This refers to the alleged offense(s) you have committed at

23-Feb-19

to name:

ACKNOWLEDGE BY

PKIMT

No. Offense:

Gadil, Riela De Borja

KATHERINE O. CABRERA

Signature Over Printed name/ Date

ACKNOWLEDGEMENT FORM

COMMENTS/ ASSESMENT

MARICH Et, 2019

Line Serreya VOI 1717 -A Jr. Staff - CONSULTY TUDYTE #.

Violation Offense No.V

OFFENSES AGAINST COMPANY INTEREST

Section No. 14

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

Description:

Not following SOP / General Rule

You are hereby given 5 days upon reciept of this letter to explain in writing why you should not given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

This is for your guidance and strict compliance.

NOTED BY:

PKIMT Managament

Conforme:

18 PK25298

FURUKAWA - Production Operator

(Please attach your written explanation upon returning of this letter)



Service Support Building (SSB), Administration Area, Lot 14, Phase 1-A, FPIP, Sto. Tomas, Batangas, Philippines Tel No.: (043) 405 6388-89 / (043) 405 6407-08

MEMORANDUM NO. HRADM

ГО

: 18_PK25298

Gadil, Riela De Boria

ROM

: PKIMT Management

SUBJECT

: Notice to explain

No. of Offense : 1st offense

DATE

: 10-Mar-19

This refers to the alleged offense(s) you have committed at

23-Feb-19

to name: Gadil, Riela De Borja

iolation Offense No.V

OFFENSES AGAINST COMPANY INTEREST

ection No. 10

Omission or commission of an act in connection with or against the policies & procedures, SOPs, set work guidelines & to the particular duties and responsibilities inherent to the employee's work

escription:

Not following SOP / General Rule

You are hereby given 5 days upon receipt of this letter to explain in writing why you should not be given a disciplinary action for such offense. Failure to comply would mean you voluntarily waive your right to due process and the company has no recourse but to implement the penalty provided for based in our company rules and regulations.

his is for your guidance and strict compliance.

OTED BY:

18_PK25298

FURUKAWA - Production Operator


(Please attach your written expalanation upon returning of this letter)

I ALERT WRITTEN EXPLANATION

FAS		Control No: FALP-1A . 1002 - 121
✓ AGENCY Please Specify: PKIMT		Audited By: Noted By:
Name: GAON RIELA	Process:	
ONDIL INTELA	Group/Shift:	ASS7
ASSOCIATE	Date/ Time:	A-NS
18.5.T.D.43.77.1R	No. of Offense:	FEB. 23,2019/11:07 PM
C 11/1:	Superior Name:	1ST
		J. MATIBAG
Audit Findings: NOT FOLIO WI Details:	NG GOP GENER	AL RUIBS
> Associate caught in act do air Norking. during attachment of 91-GOGLD-W-D. Product: 36620-79RBOC12-2-P	during her pho	ccc, by not using clamp to
WRITTEN	N EXPLANATION	
modlip po und portion na 'y	g clarp CI- P jig ko p on tinatanya as na aladaliar I back ong d ang clarp	-6060-W-D, daril po D tet apepan kase to na lang po yung D po ato pay garun imosion sa okin, kase Cy jbinabalik ko po sa
Please sue	J.R	
Remar	ks/ Evaluation:	
Encountait , othe Do ATRICULTY ON DIMESUM ASSOCIATE WHO DIMESUM ASSOCIATE WHO DIMESUM FOR THE CONSTRUCTORY ON Defect, acsociate whe construction for the construction of Employee Justific Justi		The price of air

Date/Time	Feb, 23,2019 /11:07pm
Line/ Process	5117/ Assembly
Shift/ Group	A/NS
Person Informed	J.Matibag
	Details

Not using clamp jig during attachment of clamp CL-60610-W in assembly process.



MEI-085F1 Assy Board Daily Inspection Record

To serve as a guide for assembly process in making a

wire harness

Final Assembly Process

FALP-OP-020

Section Manager

Division Manager

A

ballpen, Assembly Board

PAGE NO.: 1 OF

Checked by:

Verified by:

Approved by: Nov-06-2018



Conduct checking of assy board and fill up MEI-085F1 Assy Board Daily Inspection Record.



2. Check and set the product label based on the running product.

- Assigned Layout associate will put "Start of Change Product" together with the name plate of the product
- 2. Assigned Layout associate will put "Attention!!! Last 5 sets to change new product" to inform those involved in the operation that they will be changing product. These two tags will be attached to the harness until the last inspection.





3. WIRE LAYOUT
The layout associate must know and follow the instruction indicated on assembly drawing for the correct layout and position of wires and connectors.

Note:

setting the parts.

4. Set parts on one set supply box or overhead parts box. Associate must check the running product before





Note: Put the harness on the hanger for inspection.

1. Applicable to those lines with hanger. For those lines which maintains one piece flow, pass to next process.

- Call the attention of countries machine or process. med personnel and report any abnormality in
- Always turn off the machine/equipment when not in use and when encountered abnormality.
- Wear proper PPE. (Refer to FALP-GL-ESH-18006 Personal Protective Equipment (PPE) for the applicable PPE.

BENT/PULLED JOINTED PORTION

				ENG-001-03
1		Aug-01-2013	0	A3d-102
	and change picture of instruction no. 2		,	100
		Nov-18-2C15	1	#50-TTCT-PCM
	The state of the s			1511 004
-1		Mar-19-2018		LO-LUG-FOG-TOOD-OOR
			,	DD_DBD_13-1000 000
	Sphill align step of			
	Taning Application and a store			
1	The second state of present and the second s	Jul-31-2018	u	LD-LUD-F2G1-F07-007
			,	BD_BBD 135 1907 003
	and the state of t			
4	Nov-06-2018 Change picture under step 1, 2, 3 and 5 - Add warning for safety purposes	Nov-06-2018	4	. C. I.C. P. P. TOTO-COO
4	Control of the Contro			PD-PRD-13-1910-006
1			The second secon	

The associate must know how to read the assy board correctly. Avoid making harness with expose wire
 Workload of layout and assy associate must be based on FALP-GL-ENG-15008 Standard Operation Table Guidelines.

The taping associate must follow instructions from operation instruction and indications on taping and installation of components.

TAPING OF WIRES AND INSTALLATION OF PARTS

3. Wires or branch should not over pulled or over bent during attach

nt of components and taping application

