GBZ80(7) Miscellaneous Information Manual

NAME

gbz80 — CPU opcode reference

DESCRIPTION

This is the list of opcodes supported by rgbasm(1), including a short description, the number of bytes needed to encode them and the number of CPU cycles at 1MHz (or 2MHz in GBC dual speed mode) needed to complete them.

Note: All arithmetic/logic operations that use register **A** as destination can omit the destination as it is assumed it's register **A**. The following two lines have the same effect:

OR A,B

LEGEND

List of abbreviations used in this document.

```
Any of the 8-bit registers (A, B, C, D, E, H, L).

**T16**

Any of the general-purpose 16-bit registers (BC, DE, HL).

**8**

8-bit integer constant.
```

n16

16-bit integer constant.

GBZ80(7)

```
8-bit offset (-128 to 127).

3-bit unsigned integer constant (0 to 7).

CC

Condition codes:

Z:

Execute if Z is set.

NZ:

Execute if Z is not set.

C:

Execute if C is set.

NC:

Execute if C is not set.
```

vec

One of the RST vectors (0x00, 0x08, 0x10, 0x18, 0x20, 0x28, 0x30 and 0x38).

INSTRUCTION OVERVIEW

8-bit Arithmetic and Logic Instructions

ADC A,r8 ADC A,n8 ADC A,n8 ADD A,r8 ADD A,n8 ADD A,n8 AND A,r8

AND A,[HL]

AND A,n8

CP A,r8

CP A,[HL]

CP A,n8

DEC r8

DEC [HL]

INC r8

INC [HL]

OR A,r8

OR A,[HL]

OR A,n8

SBC A,r8

SBC A,[HL]

SBC A,n8

SUB A,r8

SUB A,[HL]

SUB A,n8

XOR A,r8

XOR A,[HL]

XOR A,n8

16-bit Arithmetic Instructions

ADD HL,r16

DEC r16

INC r16

Bit Operations Instructions

BIT u3,r8

BIT u3.[HL]

RES u3,r8

RES u3,[HL]

SET u3.r8

SET u3,[HL]

SWAP r8

SWAP [HL]

Bit Shift Instructions

RL r8

RL [HL]

RLA

RLC r8

RLC [HL]

RLCA

RR r8

RR [HL]

<u>RRA</u>

RRC r8

RRC [HL]

RRCA

SLA r8

SLA [HL]

SRA r8

SRA [HL]

SRL r8

SRL [HL]

Load Instructions

LD r8,r8

LD r8,n8

LD r16,n16

LD [HL],r8

LD [HL],n8

LD r8,[HL]

LD [r16],A

LD [n16],A

LD [\$FF00+n8],A

LD [\$FF00+C],A

LD A,[r16]

LD A,[n16]

LD A,[\$FF00+n8]

LD A.[\$FF00+C]

LD [HL+],A

LD [HL-],A

LD A,[HL+]

LD A,[HL-]

Jumps and Subroutines

CALL n16

CALL cc,n16

JP HL

JP n16

JP cc.n16

JR e8

JR cc.e8

RET cc

RET

RETI

RST vec

Stack Operations Instructions

ADD HL,SP

ADD SP,e8

DEC SP

INC SP

LD SP,n16

LD [n16],SP

LD HL,SP+e8

LD SP,HL

POP AF

POP r16

PUSH AF

PUSH r16

Miscelaneous Instructions

CCF

CPL

DAA DI EI

HALT

NOP

SCF

STOP

INSTRUCTION REFERENCE

ADC A,r8

Add the value in r8 plus the carry flag to **A**.

Cycles: 1

Bytes: 1

Flags:

- **Z**: Set if result is 0.
- N: 0
- **H**: Set if overflow from bit 3.
- C: Set if overflow from bit 7.

ADC A,[HL]

Add the value pointed by **HL** plus the carry flag to **A**.

Cycles: 2

Bytes: 1

Flags: See ADC A,r8

ADC A,n8

Add the value n8 plus the carry flag to **A**.

Cycles: 2

Bytes: 2

Flags: See ADC A,r8

ADD A,r8

Add the value in r8 to **A**.

Cycles: 1 Bytes: 1

Flags:

- **Z**: Set if result is 0.
- N: 0
- H: Set if overflow from bit 3.
- **C**: Set if overflow from bit 7.

ADD A, [HL]

Add the value pointed by **HL** to **A**.

Cycles: 2 Bytes: 1

Flags: See ADD A,r8

ADD A,n8

Add the value n8 to **A**.

Cycles: 2 Bytes: 2

Flags: See ADD A,r8

ADD HL,r16

Add the value in *r16* to **HL**.

Cycles: 2
Bytes: 1
Flags:

• N: 0

• **H**: Set if overflow from bit 11.

• C: Set if overflow from bit 15.

ADD HL,SP

Add the value in **SP** to **HL**.

Cycles: 2 Bytes: 1

Flags: See ADD HL,r16

ADD SP,e8

Add the signed value *e8* to **SP**.

Cycles: 4 Bytes: 2

Flags:

• **Z**: 0

• N: 0

• H: Set if overflow from bit 3.

• **C**: Set if overflow from bit 7.

AND A,r8

Bitwise AND between the value in r8 and **A**.

Cycles: 1

Bytes: 1

Flags:

- **Z**: Set if result is 0.
- N: 0
- H: 1
- **C**: 0

AND A, [HL]

Bitwise AND between the value pointed by **HL** and **A**.

Cycles: 2 Bytes: 1

Flags: See AND A,r8

AND A,n8

Bitwise AND between the value in n8 and A.

Cycles: 2 Bytes: 2

Flags: See AND A,r8

BIT u3,r8

Test bit u3 in register r8, set the zero flag if bit not set.

Cycles: 2 Bytes: 2

Flags:

• **Z**: Set if the selected bit is 0.

• N: 0 • H: 1

BIT u3,[HL]

Test bit u3 in the byte pointed by HL, set the zero flag if bit not set.

Cycles: 3

Bytes: 2

Flags: See BIT u3,r8

CALL n16

Call address *n16*.

Cycles: 6
Bytes: 3

Flags: None affected.

CALL cc,n16

Call address *n16* if condition *cc* is met.

Cycles: 6/3

Bytes: 3

Flags: None affected.

CCF

Complement Carry Flag.

Cycles: 1

Bytes: 1

Flags:

- N: 0
- **H**: 0
- **C**: Complemented.

CP A,r8

Subtract the value in r8 from A and set flags accordingly, but don't store the result.

Cycles: 1

Bytes: 1

Flags:

- **Z**: Set if result is 0.
- N: 1
- H: Set if no borrow from bit 4.

• C: Set if no borrow (set if r8 > A).

CP A, [HL]

Subtract the value pointed by **HL** from **A** and set flags accordingly, but don't store the result.

Cycles: 2 Bytes: 1

Flags: See <u>CP A,r8</u>

CP A,n8

Subtract the value *n8* from **A** and set flags accordingly, but don't store the result.

Cycles: 2 Bytes: 2

Flags: See <u>CP A,r8</u>

CPL

Complement accumulator $(A = \sim A)$.

Cycles: 1 Bytes: 1

Flags:

• N: 1 • H: 1

DAA

Decimal adjust register A to get a correct BCD representation after an arithmetic instruction.

Cycles: 1

Bytes: 1

Flags:

• **Z**: Set if result is 0.

- H: 0
- C: Set or reset depending on the operation.

DEC r8

Decrement value in register r8 by 1.

Cycles: 1

Bytes: 1

Flags:

- **Z**: Set if result is 0.
- N: 1
- H: Set if no borrow from bit 4.

DEC [HL]

Decrement the value pointed by **HL** by 1.

Cycles: 3

Bytes: 1

Flags: See <u>DEC r8</u>

DEC r16

Decrement value in register r16 by 1.

Cycles: 2

Bytes: 1

Flags: None affected.

DEC SP

Decrement value in register **SP** by 1.

Cycles: 2

Bytes: 1

Flags: None affected.

DI

Disable Interrupts.

Cycles: 1 Bytes: 1

Flags: None affected.

EI

Enable Interrupts.

Cycles: 1 Bytes: 1

Flags: None affected.

HALT

Enter CPU low power mode.

Cycles: -

Bytes: 1

Flags: None affected.

INC r8

Increment value in register r8 by 1.

Cycles: 1 Bytes: 1

Flags:

• **Z**: Set if result is 0.

- N: 0
- H: Set if overflow from bit 3.

INC [HL]

Increment the value pointed by **HL** by 1.

Cycles: 3 Bytes: 1

Flags: See <u>INC r8</u>

INC r16

Increment value in register r16 by 1.

Cycles: 2 Bytes: 1

Flags: None affected.

INC SP

Increment value in register **SP** by 1.

Cycles: 2

Bytes: 1

Flags: None affected.

JP n16

Absolute jump to address *n16*.

Cycles: 4

Bytes: 3

Flags: None affected.

JP cc,n16

Absolute jump to address n16 if condition cc is met.

Cycles: 4/3

Bytes: 3

Flags: None affected.

JP HL

Jump to address in HL, that is, load PC with value in register HL.

Cycles: 1 Bytes: 1

Flags: None affected.

JR e8

Relative jump by adding e8 to the current address.

Cycles: 3 Bytes: 2

Flags: None affected.

JR cc,e8

Relative jump by adding e8 to the current address if condition cc is met.

Cycles: 3/2

Bytes: 2

Flags: None affected.

LD r8,r8

Store value in register on the right into register on the left.

Cycles: 1

Bytes: 1

Flags: None affected.

LD r8,n8

Load value *n8* into register *r8*.

Cycles: 2 Bytes: 2

Flags: None affected.

LD r16,n16

Load value *n16* into register *r16*.

Cycles: 3
Bytes: 3

Flags: None affected.

LD [HL],r8

Store value in register r8 into byte pointed by register **HL**.

Cycles: 2 Bytes: 1

Flags: None affected.

LD [HL],n8

Store value *n8* into byte pointed by register **HL**.

Cycles: 3 Bytes: 2

Flags: None affected.

LD r8,[HL]

Load value into register r8 from byte pointed by register HL.

Cycles: 2 Bytes: 1

Flags: None affected.

LD [r16],A

Store value in register $\bf A$ into address pointed by register r16.

Cycles: 2 Bytes: 1

Flags: None affected.

LD [n16],A

Store value in register A into address n16.

Cycles: 4
Bytes: 3

Flags: None affected.

LD [\$FF00+n8],A

Store value in register A into high RAM or I/O registers.

The following synonym forces this encoding: LDH [\$FF00+n8],A

Cycles: 3
Bytes: 2

Flags: None affected.

LD [\$FF00+C],A

Store value in register A into high RAM or I/O registers.

Cycles: 2

Bytes: 1

Flags: None affected.

LD A,[r16]

Load value in register $\bf A$ from address pointed by register r16.

Cycles: 2 Bytes: 1

Flags: None affected.

LD A,[n16]

Load value in register **A** from address n16.

Cycles: 4
Bytes: 3

Flags: None affected.

LD A,[\$FF00+n8]

Load value in register A from high RAM or I/O registers.

The following synonym forces this encoding: LDH A,[\$FF00+n8]

Cycles: 3 Bytes: 2

Flags: None affected.

LD A,[\$FF00+C]

Load value in register ${\bf A}$ from high RAM or I/O registers.

Cycles: 2 Bytes: 1

Flags: None affected.

LD [HL+],**A**

Store value in register A into byte pointed by HL and post-increment HL.

Cycles: 2

Bytes: 1

Flags: None affected.

LD [HL-],A

Store value in register A into byte pointed by HL and post-decrement HL.

Cycles: 2

Bytes: 1

Flags: None affected.

LD A,[HL+]

Load value into register A from byte pointed by HL and post-increment HL.

Cycles: 2

Bytes: 1

Flags: None affected.

LD A,[HL-]

Load value into register A from byte pointed by HL and post-decrement HL.

Cycles: 2

Bytes: 1

Flags: None affected.

LD SP,n16

Load value *n16* into register **SP**.

Cycles: 3

Bytes: 3

Flags: None affected.

LD [n16],**SP**

Store **SP** into addresses n16 (LSB) and n16 + 1 (MSB).

Cycles: 5
Bytes: 3

Flags: None affected.

LD HL,SP+e8

Add the signed value e8 to SP and store the result in HL.

Cycles: 3

Bytes: 2

Flags:

- **Z**: 0
- N: 0
- **H**: Set if overflow from bit 3.
- C: Set if overflow from bit 7.

LD SP,HL

Load register HL into register SP.

Cycles: 2

Bytes: 1

Flags: None affected.

NOP

No operation.

Cycles: 1 Bytes: 1

Flags: None affected.

OR A,r8

Bitwise OR between the value in r8 and A.

Cycles: 1
Bytes: 1
Flags:

• **Z**: Set if result is 0.

• **N**: 0

• **H**: 0

• **C**: 0

OR A, [HL]

Bitwise OR between the value pointed by **HL** and **A**.

Cycles: 2

Bytes: 1

Flags: See OR A,r8

OR A,n8

Bitwise OR between the value in n8 and A.

Cycles: 2

Bytes: 2

Flags: See OR A,r8

POP AF

Pop register **AF** from the stack.

Cycles: 3

Bytes: 1

Flags: None affected.

POP r16

Pop register r16 from the stack.

Cycles: 3 Bytes: 1

Flags: None affected.

PUSH AF

Push register **AF** into the stack.

Cycles: 4 Bytes: 1

Flags: None affected.

PUSH r16

Push register *r16* into the stack.

Cycles: 4

Bytes: 1

Flags: None affected.

RES u3,r8

Set bit u3 in register r8 to 0.

Cycles: 2

Bytes: 2

Flags: None affected.

RES u3,[HL]

Set bit *u3* in the byte pointed by **HL** to 0.

Cycles: 4

Bytes: 2

Flags: None affected.

RET

Return from subroutine.

Cycles: 4

Bytes: 1

Flags: None affected.

RET cc

Return from subroutine if condition *cc* is met.

Cycles: 5/2

Bytes: 1

Flags: None affected.

RETI

Return from subroutine and enable interrupts.

Cycles: 4

Bytes: 1

Flags: None affected.

<u>RL r8</u>

Rotate register r8 left through carry.

C <- [7 <- 0] <- C

Cycles: 2

Bytes: 2

Flags:

• **Z**: Set if result is 0.

• **N**: 0

• **H**: 0

• C: Set according to result.

RL [HL]

Rotate value pointed by HL left through carry.

C <- [7 <- 0] <- C

Cycles: 4

Bytes: 2

Flags: See RL r8

RLA

Rotate register A left through carry.

C < -[7 < -0] < -C

Cycles: 1

Bytes: 1

Flags:

• **Z**: 0

• N: 0

• **H**: 0

• C: Set according to result.

RLC r8

Rotate register *r8* left.

C <- [7 <- 0] <- [7]

Cycles: 2

Bytes: 2

Flags:

- **Z**: Set if result is 0.
- N: 0
- **H**: 0
- C: Set according to result.

RLC [HL]

Rotate value pointed by HL left.

C <- [7 <- 0] <- [7]

Cycles: 4

Bytes: 2

Flags: See RLC r8

RLCA

Rotate register A left.

C < [7 < 0] < [7]

Cycles: 1

Bytes: 1

Flags:

- **Z**: 0
- N: 0
- **H**: 0
- C: Set according to result.

<u>RR r8</u>

Rotate register *r8* right through carry.

GBZ80(7)

C -> [7 -> 0] -> C Cycles: 2

Bytes: 2

Flags:

- **Z**: Set if result is 0.
- N: 0
- **H**: 0
- C: Set according to result.

RR [HL]

Rotate value pointed by HL right through carry.

 $C \rightarrow [7 \rightarrow 0] \rightarrow C$

Cycles: 4

Bytes: 2

Flags: See RR r8

RRA

Rotate register A right through carry.

 $C \rightarrow [7 \rightarrow 0] \rightarrow C$

Cycles: 1

Bytes: 1

Flags:

- **Z**: 0
- N: 0
- **H**: 0
- C: Set according to result.

RRC r8

Rotate register r8 right.

- $[0] \rightarrow [7 \rightarrow 0] \rightarrow C$
- Cycles: 2
- Bytes: 2
- Flags:
 - **Z**: Set if result is 0.
 - N: 0
 - **H**: 0
 - C: Set according to result.

RRC [HL]

Rotate value pointed by HL right.

$$[0] \rightarrow [7 \rightarrow 0] \rightarrow C$$

- Cycles: 4
- Bytes: 2
- Flags: See RRC r8

RRCA

Rotate register A right.

 $[0] \rightarrow [7 \rightarrow 0] \rightarrow C$

Cycles: 1

Bytes: 1

Flags:

- **Z**: 0
- N: 0
- **H**: 0
- C: Set according to result.

RST vec

Call restart vector vec.

Cycles: 4

Bytes: 1

Flags: None affected.

SBC A,r8

Subtract the value in r8 and the carry flag from **A**.

Cycles: 1

Bytes: 1

Flags:

- **Z**: Set if result is 0.
- N: 1
- H: Set if no borrow from bit 4.
- C: Set if no borrow (set if r8 > A).

SBC A,[HL]

Subtract the value pointed by HL and the carry flag from A.

Cycles: 2

Bytes: 1

Flags: See <u>SBC A,r8</u>

SBC A,n8

Subtract the value n8 and the carry flag from **A**.

Cycles: 2

Bytes: 2

Flags: See SBC A,r8

SCF

Set Carry Flag.

Cycles: 1
Bytes: 1

Flags:

• N: 0

• **H**: 0 • **C**: 1

SET u3,r8

Set bit u3 in register r8 to 1.

Cycles: 2 Bytes: 2

Flags: None affected.

SET u3,[HL]

Set bit u3 in the byte pointed by **HL** to 1.

Cycles: 4
Bytes: 2

Flags: None affected.

SLA r8

Shift left arithmetic register r8.

C < -[7 < -0] < -0

Cycles: 2

Bytes: 2

Flags:

- **Z**: Set if result is 0.
- N: 0
- **H**: 0

• C: Set according to result.

SLA [HL]

Shift left arithmetic value pointed by HL.

C < -[7 < -0] < -0

Cycles: 4

Bytes: 2

Flags: See <u>SLA r8</u>

SRA r8

Shift right arithmetic register *r8*.

 $[7] \rightarrow [7 \rightarrow 0] \rightarrow C$

Cycles: 2

Bytes: 2

Flags:

- **Z**: Set if result is 0.
- N: 0
- **H**: 0
- C: Set according to result.

SRA [HL]

Shift right arithmetic value pointed by HL.

 $[7] \rightarrow [7 \rightarrow 0] \rightarrow C$

Cycles: 4

Bytes: 2

Flags: See <u>SRA r8</u>

SRL r8

Shift right logic register r8.

 $0 \rightarrow [7 \rightarrow 0] \rightarrow C$

Cycles: 2

Bytes: 2

Flags:

- **Z**: Set if result is 0.
- N: 0
- **H**: 0
- C: Set according to result.

SRL [HL]

Shift right logic value pointed by HL.

 $0 \rightarrow [7 \rightarrow 0] \rightarrow C$

Cycles: 4

Bytes: 2

Flags: See <u>SRA r8</u>

STOP

Enter CPU very low power mode. Also used to switch between doube speed and normal CPU modes in GBC.

Cycles: -

Bytes: 2

Flags: None affected.

SUB A,r8

Subtract the value in r8 from **A**.

Cycles: 1

Bytes: 1

Flags:

- **Z**: Set if result is 0.
- N: 1
- H: Set if no borrow from bit 4.
- C: Set if no borrow (set if r8 > A).

SUB A, [HL]

Subtract the value pointed by HL from A.

Cycles: 2 Bytes: 1

Flags: See SUB A,r8

SUB A,n8

Subtract the value *n8* from **A**.

Cycles: 2 Bytes: 2

Flags: See SUB A,r8

SWAP r8

Swap upper 4 bits in register r8 and the lower ones.

Cycles: 2 Bytes: 2

Flags:

- **Z**: Set if result is 0.
- N: 0
- H: 0
- **C**: 0

SWAP [HL]

Swap upper 4 bits in the byte pointed by **HL** and the lower ones.

Cycles: 4

Bytes: 2

Flags: See **SWAP r8**

XOR A,r8

Bitwise XOR between the value in r8 and **A**.

Cycles: 1
Bytes: 1
Flags:

• **Z**: Set if result is 0.

• N: 0 • H: 0

• **C**: 0

XOR A,[HL]

Bitwise XOR between the value pointed by HL and A.

Cycles: 2

Bytes: 1

Flags: See XOR A,r8

XOR A,n8

Bitwise XOR between the value in *n8* and **A**.

Cycles: 2

Bytes: 2

Flags: See XOR A,r8

SEE ALSO

rgbasm(1), rgbds(7)

HISTORY

rgbds was originally written by Carsten Sørensen as part of the ASMotor package, and was later packaged in RGBDS by Justin Lloyd. It is now maintained by a number of contributors at https://github.com/rednex/rgbds.

April 17, 2017 RGBDS Manual