## SERVICE REPORT PREVENTIVE MAINTENANCE PRECISION AIR HANDLING UNIT (PAHU)

FORM	NO.

Tipe Form PM03

									Tipe Form Fillus	
Lokasi : LT3		Model Unit :			Team Engineer List :			Date: 2024-07-29 09:53:39		
Code unit : 2 No. Seri : 2				Start PM:						
Non	nor Unit :	Periode :	de :					Close PM	:	
CHI	ECKLIST TEAM BRIEFII	NG								
INTI	ENSIVE SAFETY BRIEFING	GTEAM?OK?	NOT OK							
Λ	Filter Section									
A	Filler Section	Spec. Range /								
	Item Checked	Cond. Std.	Actual	Checked	Item (	Checked	Spec	. Range	Actual Checked	
	4. OhaaldDawlaaa filtana		Di	rty	5. Clean condensate pan 6. Clean trap in condensate drain 7. Check/Test filter-		,		Clean	
	1. Check/Replace filters	Clean or Dirty					Clean or Dirty			
	2. Grille area	Ol. an Na	C	)k			Clean or Dirty		Clean	
	unrestricted	Ok or No								
	3. Wipe section clean	Clean or Dirty	Clo	ean				1	Ok	
	•	,				clog switch		or No		
	4. Coil clean	Clean or Dirty	Clo	ean	operation					
В	<b>Blower Section</b>									
	Item Checked	Spec. Range /	Blov	ver 1	Blower 2		Blo	wer 3	- Keterangan	
		Cond. Std.	Before	After	Before	After	Before	After	rtotorungun	
	1. Mounting bolts tight	Ok or No	OK	OK	OK	OK	OK	OK	OK	
	2. Fan-guard bolts tight	Ok or No	OK	OK	OK	OK	OK	OK	OK	
	3. Impeller spins freely	Ok or No	OK	OK	OK	OK	OK	OK	OK	
	4. Check/Test air sail switch	Ok or No	OK	OK	OK	OK	OK	OK	OK	
	5. Motor amp draw	FLA L1 = A	L1	L1	L1	L1	L1	L1	11	
	Compare to	FLA L2 = A	L2	L2	L2	L2	L2	L2	11	
	nameplateamps	FLA L3 = A	L3	L3	L3	L3	L3	L3	11	
	6. Check belt tension	OLN.	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
	and	Ok or No								
	condition									
	7. Check sheave/pulley	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
С	Reheat									
	Item Checked	Spec. Range /			Heater 2		Heater 3		Keterangan	
		Cond. Std.	Before	After	Before	After	Before	After	1101010119011	
	1. Reheat amp draw	FLA = A	1	1	1	1	11	1	1	
	2. Check Heater Resistance	18-22 ohm	1	1	1	1	11	1	1	
	3. Inspect elements	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
	4. Check	22.22	1	1	1	1	1	1	1	
	TemperatureHeater	max 90 ?C								
	5. Check wire	OLN.	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
	connections	Ok or No								
D	Steam Generating Hum	nidifier								
	Item Checked	Spec. Range	Ok or No  1 4. Check condition of hose  Ok 5. Clean strainer		ed	Spec. Range	Actual Checked			
	1. Humidifier amp draw	A			4. Check condition of steam hose			Ok or No	Clean	
	2. Check drain valve/drain lines/trap for damage/clogs/leaks	Ok or No			5. Clean s	strainer		Ok or No	Clean	
	3. Check water fill valve and all supply lines/connection for leaks	Ok or No			tank)			Ok or No	Clean	
					7. Check	operation of	f	Ok or No	Ok	

E Electrical Panel

Item Checked	Spec. Range / Cond. Std.		Keterangan			
	Cond. Std.	Before	- Cite	cked After		
1. Check fuses	Ok or No	Ok		Ok		Ok
2. Check contactors for pitting (Replace if pitted)	Ok or No	Ok		Ok		Ok
3. Check/Re-torque wire connections	Ok or No	Ok		Ok		Ok
E Electrical Panel						
Item Checked	Spec. Range / Cond. Std.			tual cked		Keterangan
		Before		After	After	
4. Voltage Line to Neutral Ground	220 + 10%	L1/L2/L3 =		L1/L2/L3 =	V	1
5. Voltage Line to Line	380 + 10%	L1L2/L2L3/L1L3 =	V	L1L2/L2L3/L1L3 =	V	1
6. Frequency	50 + 10%	F =		F =		1
F Controls	30 + 10%	F =	ПZ	F =	ПZ	-
Item Checked	Spec. Range / Cond. Std.	Actual Checked	lt	tem Checked	Spec. Range	Actual Checked
1. Check/Verify control operation	Ok or No	Ok	3. Check/T device	est water-detection	Ok or No	Ok
2. Check/Test changeoverdevice	Ok or No	Ok	4. Check/Test CAN connection between indoor and outdoor units		Ok or No	Ok
G Chiled Water						
Item Checked	Spec. Range	Actual Checked	Item Checked		Spec. Range	Actual Checked
1. Check Water Temperature / Pressure In	?C Psi	1	5. Check Valve in & Out Chilled Water (No Corrosion, No Leaks)		Ok or No	Ok
2. Check Temperature / Pressure Out	?C	1	6. Clean outside valve & Pipe		Clean	Clean
3. Clean Pressure gauge & Temperature Gauge	Clean or Dirty	Clean	7. Clean Strainer		Dirty Clean or	Clean
4. Check motorize valve	Ok or No	Ol-	O Charle Dina Insulation		Dirty Ok or No	Ok
H General Function	OK OF INO	Ok 8. Check Pipe Insulation		ripe insulation	OK OF NO	OK
Item Checked	Spec. Range	Actual Checked	It	Item Checked		Actual Checked
1. Cooling Test	Ok or No	&Ok	4. Dehumi	dification Test	Range Ok or No	Ok
2. Heating Test	Ok or No	Ok	5. Alarm T	est	Ok or No	Ok;
3. Humidification Test	Ok or No	Ok				
Room Condition Item Checked	Spec. Range	Actual Checked	Item Checked		Spec. Range	Actual Checked
1. Temperature	1 C	1	2. Humidit	y	1%	1
Femuan : 1		NOT				
Rekomendasi :1						

	JOB COMPLETED	? Yes		RUNNING HOURS :1						
	APPROVAL SIGNING									
Г	Approved by		Verified B	Ву	Service By					
ISS,			Superviso	or,	Team Leader/Staf,					
	() No. HP.	N	(_) o. HP.		No HP	()				

Keterangan : Lembar 1 untuk Teknisi; Lembar 2 untuk User; Lembar 3 Arsip Kantor

