SERVICE REPORT PREVENTIVE MAINTENANCE

FORM NO.

		PREC	ISION A		NDITIO	NING (P	PAC)			
		P	T. HM SA LANT			,	110)		Tipe Form PM04	
Lok	asi : LT3	Model Unit:			Team Engi	neer List : to	es	Date : 2024-	1	
							2024- 08-03			
Coc	le unit : 12	No. Seri }: 12			1			Start PM : 06:10		
Nor	nor Unit : 83	Periode :				Close PM: 08:10				
CH	ECKLIST TEAM BRIE	FING			-					
INT	TENSIVE SAFETY BRIEF					?	OK	?	NOT OK	
	AM Filter Section									
Λ	Item Checked	Spec. Range / Cond. Std.	Actual	Checked	Item (Checked	Spec. Range	Ac	tual Checked	
	1. Check/Replace filters	Clean or Dirty	Clean	,	5. Clean co		Clean or Dirty	Clean		
	2. Grille area unrestricted	restricted OK / Not OK c			6. Clean trap in Clean or Condensate drain Dirty		Clean			
	3. Wipe section clean	Clean or Dirty			7. Check/Test filter-Ok or No		Ok			
D	4. Coil clean Blower Section	Clean or Dirty	Clean		clog switcl	n operation				
ь		Spec. Range /	Blov	wer 1	Blo	Blower 2		wer 3		
	Item Checked	Cond. Std.	Before	After	Before	After	Before	After	Keterangan	
	1. Mounting bolts tight	Ok or No	OK	OK	OK	OK	OK	OK	OK OK	
	2. Fan-guard bolts tight 3. Impeller spins freely	Ok or No Ok or No	OK OK	OK OK	OK OK	OK OK	OK OK	OK OK	OK OK	
l	4. Check/Test air sail		OK	OK	OK	OK	OK	OK	OK	
	switch	Ok or No								
	5. Motor amp draw	FLA L1 =···· A	L1	L1	L1	L1	L1	L1	1	
	Compare to nameplate amps	FLA L2 =···· A	L2	L2	L2	L2	L2	L2	1	
		FLA L3 =···· A	L3	L3	L3	L3	L3	L3	1	
	6. Check belt tension and condition	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
C	7. Check sheave/pulley	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
	Reheat	Spec. Range /	Hea	iter 1	Heater 2		Heater 3			
	Item Checked	Cond. Std.	Before	After	Before	After	Before	After	Keterangan	
	1. Reheat amp draw	FLA =····· A	1	1	1	1	1	1	1	
	2. Check Heater Resistance	18-22 ohm	1	1	1	1	1	1	1	
	3. Inspect elements	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
	4. Check wire connections	Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
D	Steam Generating Hum	idifier								
	Item Checked	Spec. Range	1 Ok		Item Checked 4. Check condition of steam hose 5. Clean strainer			Spec. Range	Actual Checked	
	1. Humidifier amp draw	Α						Ok or No	Clean	
	2. Check drain valve/drain lines/trap fordamage/clogs/leaks	Ok or No						Ok or No	Clean	
	3. Check water fill valve and all supply lines/connection for leaks	Ok or No	Clean		6. Check humidifier bottle (Boiler tank)			Ok or No	Clean	
L					7. Check operation of humidifier			Ok or No	Ok	
E	Electrical Panel	Cman D-			Actual	Checked				
	Item Checked	Spec. Range / Cond. Std.		Before	Actual	Спескей	After		Keterangan	
	1. Check fuses	Ok or No	Ok			Ok			Ok	

2. Check contactors for

pitting (Replace if pitted)

Ok

Ok or No

Ok

Ok

3.		Ok	Ok	Ok
Che	ck/Rok or No			
tore	ue			
wir	ę			
con	nections			

E Electrical P									
T		Spec. Range /	Actual						T Z 4
Item (Checked	Cond. Std.			Che	cked	Keterangan		
				Before			After		
	Voltage Line to						1		
Neutral 220 + 10		220 + 10%	L1/L2/L3 = 1	l	$V \qquad L1/L2/L3 = 1$			V	
5. Voltage L	ina ta I ina	380 + 10%	L1L2/L2L3/	л п з –1		L1L2/L2L3/I	11.3 –1		1
3. Voltage L	ine to Line	380 + 10%	V	LILS —		V	alls —-		1
6. Frequency	y	50 + 10%	F=1		Hz	F=1		Hz	1
F Controls									
Item (Checked	Spec. Range / Cond. Std.	Actual Checked		Item Checked			Spec. Range	Actual Checked
1. Check/Ve	erify control	Ok or No	Ok		3. Check/Test water-			Ok or No	Ok
operation		OR OF IVO	Ole		detectiond		nnoction		Ok
2. Check/Te changeover		Ok or No	Ok		4. Check/Test CAN connection between indoor and outdoor units			Ok or No	OK
G Refrigeration	on Piping								
Item (Checked	Spec. Range	Actua	al Checked	1	Item Check	ed	Spec. Range	Actual Checked
1. Check ref	rigerant lines		Ok						Clean
(clamps secu	re/no	Ok or No	3. C			or restricti			
rubbing/no						re drop acı	OSS	Ok or No	
2. Check for	moisture	Ok or No	Ok		filterdrier				
(sight glass)	~ .	OR OF IVO							
H Compresso	r Section	G B	C	1	Comp. 2 Con		2		
Item (Checked	Spec. Range / Cond. Std.	Before	omp. 1 After	Before	After	Before	np. 3 After	Keterangan
1. Ampere d	raw	OA··· A	1	1	1	1	1	1	1
2. Check oil		55 - 90 PsiG	1	1	1	1	1	1	1
3. Check for	oil leaks	200 - 300 PsiG	1	1	1	1	1	1	1
4. Check			Ok	Ok	Ok	Ok	Ok	Ok	Ok
compressori (springs/bus		Ok or No							
5. Cap tubes rubbing)		Ok or No	Ok	Ok	Ok	Ok	Ok	Ok	Ok
6. Check/Re	-torque		Ok	Ok					
				OK	Ok	Ok	Ok	Ok	Ok
wireconnect	ions (inside	Ok or No		OK	Ok	Ok	Ok	Ok	Ok
compressor	box)	Ok or No		OK .	Ok	Ok	Ok	Ok	Ok
compressor 7. Compress	box)	Hz	1	1	Ok 1	Ok 1	Ok 1	Ok 1	Ok
7. Compress operation	box) or		1	1	Ok 1	Ok 1	Ok	Ok 1	Ok
7. Compress operation (vibration/n 8. Check cra	or oise) ank-case	Hz dB	1 Ok	l Ok	Ok 1 Ok	Ok I Ok	1	1	Ok 1 Ok
compressor 7. Compress operation (vibration/n 8. Check cra heater fuses/	or oise) ank-case operation	Hz	1 Ok	l Ok	l Ok	1 Ok	1 Ok	1 Ok	1 Ok
7. Compress operation (vibration/n 8. Check cra	box) or oise) ank-case operation	Hz dB	1	1	1	1	1 Ok	1 Ok	1
compressor 7. Compress operation (vibration/n 8. Check cra heater fuses/ 9. Check for	box) or oise) ank-case operation	Hz dB	1 Ok	l Ok	l Ok	1 Ok	1 Ok	1 Ok	1 Ok
compressor 7. Compress operation (vibration/n 8. Check cra heater fuses/ 9. Check for refrigerantle 10. Suction pressure Cir 11. Discharg	box) or oise) ank-case operation eaks cuit	Hz dB Ok or No Ok or No 55 - 90 PsiG	1 Ok	l Ok	l Ok	1 Ok	l Ok	1 Ok	1 Ok
compressor 7. Compress operation (vibration/n 8. Check cra heater fuses/ 9. Check for refrigerantl 10. Suction pressure Cir 11. Discharg Pressure Cir	box) or oise) ank-case operation eaks cuit	Hz dB Ok or No Ok or No 55 - 90 PsiG 200 - 300 PsiG	Ok Ok	l Ok	l Ok	I Ok Ok	I Ok Ok	1 Ok	1 Ok
compressor 7. Compress operation (vibration/n 8. Check cra heater fuses/ 9. Check for refrigerantl 10. Suction pressureCir 11. Discharg PressureCir 12. Superhea	box) or oise) ank-case operation eaks cuit ge cuit at Circuit	Hz dB Ok or No Ok or No 55 - 90 PsiG 200 - 300 PsiG ?C	Ok Ok	l Ok	l Ok	I Ok Ok	Ok Ok 1	1 Ok Ok 1 1 1	1 Ok Ok 1 1 1
compressor 7. Compress operation (vibration/n 8. Check cra heater fuses/ 9. Check for refrigerantl 10. Suction pressure Cir 11. Discharg Pressure Cir	box) or oise) ank-case operation eaks cuit ge cuit at Circuit essure	Hz dB Ok or No Ok or No 55 - 90 PsiG 200 - 300 PsiG ?C	1 Ok Ok 1 1	1 Ok Ok 1 1 1 Ok	Ok Ok I I Ok	Ok Ok I II Ok	Ok Ok I I Ok	Ok Ok 1 1 1 Ok	Ok Ok 1 1 1 Ok
compressor 7. Compress operation (vibration/n 8. Check cra heater fuses/ 9. Check for refrigerantl 10. Suction pressure Cir 11. Discharg Pressure Cir 12. Superhea 13. Low-pressor	box) or oise) ank-case operation eaks cuit te cuit at Circuit ssure at Circuit	Hz dB Ok or No Ok or No 55 - 90 PsiG 200 - 300 PsiG ?C	1 Ok Ok 1 1	1 Ok Ok 1 1 1 1	Ok Ok I	1 Ok Ok 1 11	Ok Ok I I Ok	Ok Ok 1 1 1 Ok	1 Ok Ok 1 1 1
compressor 7. Compress operation (vibration/n 8. Check cra heater fuses/ 9. Check for refrigerantl 10. Suction pressure Cir 11. Discharg Pressure Cir 12. Superhea 13. Low-presswitchcut ou 14. Low presin Circuit	box) or oise) ank-case operation eaks cuit te cuit at Circuit ssure at Circuit	Hz dB Ok or No Ok or No 55 - 90 PsiG 200 - 300 PsiG ?C Ok or No	Ok Ok I I Ok	1 Ok Ok 1 1 1 Ok	Ok Ok I I Ok	Ok Ok I II Ok	Ok Ok I I Ok Ok Ok	Ok Ok I I Ok Ok Ok	Ok Ok 1 1 1 Ok

Ι	Condensor Section				<u></u>			
	Item		Spec. Range	Before	After		Keterangan	
	Checked							
	1. Coil clean of debris (Clean coil ifrequired)		Clean or Dirty	Clean	Clean			
	2. Fans free of debris		Clean or Dirty	Clean	ean Clean			
	3. Fans securely mounted		1	1	1			
	4. Motor bearings in good condition		1	1	1			
	5. Check all refrigerant lines for		Ol N-	Ok	Ok			
	vibration		Ok or No					
	isolation. Support as necessary							
	6. Check for refrigerant le		Ok or No	Ok	Ok			
	7. Check surge-protection (ifinstalled) status-indicat	or lights	Ok or No	Ok	Ok)k		
	8. Check/Re-torque wire connections		Ok or No	Ok	Ok	Ok		
	9. Check contactors for pi ifpitted)	tting (replace	Ok or No	Ok	Ok			
	10. Verify operation sequence/set points		1	1	1			
	11. Charge verification:		1	1	1			
	a. Outdoor Ambient Temperature		1	1	1			
	b. Subcooling		1	1	1			
	c. Indoor-unit Return-air Temperature		1	1	1			
	d. Sight-glass level (if Lee-Temp orpumped refrigerant)		1	1	1			
	12. Motor amp draw		FLA = 1 A			2/L3 = .mp		
J	General Function							
	Item Checked	Spec. Range	Actual Checked	Item Checked		Spec. Range	Actual Checked	
	1. Cooling Test	Ok or No	Ok	4. Dehumidification Test		Ok or No	Ok	
	2. Heating Test Ok or No		Ok	5. Alarm Test		Ok or No	Ok	
	3. Humidification Test	Ok or No	Ok					
K	Room Condition							
	Item Checked	Spec. Range	Actual Checked	Item Checked		Spec. Range	Actual Checked	
	1. Temperature	1 C	1	2. Humidity		1 %	1	
			NOT	NOTES				
Ten	nuan :							
Rek	comendasi :							
			RESU	ME				
	JOB COMPLETED ? YES ? NO, please check on NOTES ?							
	•		4 222 0					
		APPRO SIGNI	ING					
	Approved by		Verified B	Service By				
		•						
l	ISS,		Supervisor	,		Tea	m Leader/Staf,	

Keterangan : Lembar 1 untuk Teknisi; Lembar 2 untuk User; Lembar 3 Arsip Kantor