

PT. DIKARI TATA UDARA INDONESIA

AIR CONDITIONING DIVISION

Sales, Design, Service, Installation, Prepentive Maintenance

Tipe Form PM0A

	SERVICE	REPORT TROUE	BLESHO	OT / CORRECTI	VE				
Customer UP / No. Kontak Alamat	: DKR : asd : asd		Engineer List :asd		Tangga	Survey :2024-11-26			
TASK LIST									
Checked	Service Cho	ecked	Checked		Service	Checked			
7	Intensive Safety Briefing			5. Mencatat data equipment					
\	2. Memastikan tools teknisi memadai			6. Mencatat laporan/keluhan teknis user					
	3. Memastikan APD & Permit-JSA lengka			7. Melakukan survey dengan aman, menyeluruh, dan terukur					
	4. Dokumen penunjang memadai (jika di			8. Melakukan analisa, tindakan, dan rekomendasi					
TINDAK I	ANJUT DARI LAPORAN/PEKERJA	AN		ECT LEVEL		DEFECT TYPE			
PASCA PM TEMUAN DH/SRQ COMPLAIN Lainnya:		High ☑ N Low	ledium	Minor ✓ Tidak standar Area sulit dijangkau / Hard Access					
CATATAN EQUIPMENT					Sumber kontaminasi produk Mengurangi kualitas Tidak Dibutuhkan				
Jenis Equipment : AC Split Name Plate : ada						Γidak Safety			
Brand & Model : LGG Thn Pembuatan : 2001						Lainnya : _			
Serial No. : 12233 Thn Install :2002									
Trouble Desc. : so									
Action : sd									
Rekomendasi Tel	nisi Lapangan : sd								
No	Deskripsi	LIST KEBUTUHAN P Model/Part Number		RIAL & JASA	l/oto	rangan			
1	·		Qty	Keterangan Test12					
1	Test12	Test12	1		1 e	St12			

	Foto Equipment								
No	Gambar	Info	Keterangan						
1									
	PAlisarran	1	Before						
2		sd	Before						
	TREATOR .								
	Foto Parameter								
No	Gambar	Info	Keterangan						
1		6	After						

2	FEBRUARY CONTRACTOR OF THE PROPERTY OF THE PRO	sd	Before