

## PT. DIKARI TATA UDARA INDONESIA

AIR CONDITIONING DIVISION

Sales, Design, Service, Installation, Prepentive Maintenance

Tipe Form PM0A

SERVICE REPORT TROUBLESHOOT / CORRECTIVE									
UP / No. Kontak	: DKR : asd : asd		Engineer List :asd		Tanggal Survey :2001-02-22				
	TASK LIST								
Checked	Service Che	ecked	Checked		Service Checked				
$\checkmark$	Intensive Safety Briefing			5. Mencatat data equipment					
	2. Memastikan tools teknisi memadai			6. Mencatat laporan/keluhan tekn	nis user				
	3. Memastikan APD & Permit-JSA lengkap			7. Melakukan survey dengan aman, menyeluruh, dan terukur					
	4. Dokumen penunjang memadai (jika di			8. Melakukan analisa, tindakan, d					
TINDAK L	ANJUT DARI LAPORAN/PEKERJA	AN		ECT LEVEL	DEFECT TYPE				
_			High		Minor				
✓ PASC	A PM TEMUAN DH/SRQ		Medi	ım	Tidak standar				
COMPLAIN	I Lainnya :		<b>√</b> ι	ow	Area sulit dijangkau / Hard Access				
	CA	FATAN EQUIPMENT			Sumber kontaminasi produk Mengurangi kualitas Tidak Dibutuhkan				
Jenis Equipment :	AC Split Name Plate :	ada			Tidak Safety				
Brand & Model : LGG Thn Pembuatan : 2001					Lainnya : _				
Serial No. : 12233 Thin Ferribuatan : 2007									
Oction 140 12200	THI HISTO	.2002							
Trouble Desc. : ds									
Action : ds									
Rekomendasi Tek	nisi Lapangan : ds								
Na	De alvinai	LIST KEBUTUHAN F		RIAL & JASA	Katana nan				
No	Deskripsi	Model/Part Number	Qty		Keterangan				

	Foto Equipment							
No	Gambar	Info	Keterangan					
1		asd	Before					
	Foto Parameter							
No	Gambar	Info	Keterangan					
1	Title and the second se	ds	Before					