

VISUAL SOP PROOF – PACKAGE INSPECTION

Purpose

Confirm that one outbound package is checked and sealed before dispatch.

Procedure

1. Compare the package label with work order LOT A-104.
2. Scan the package QR code and confirm package ID PKG-4821.
3. Inspect the top and all four sides for dents, tears, or water damage.
4. Apply the blue security seal across the center seam.
5. Press Complete after all inspection steps are finished.

Recording guidance

Keep the label, QR code, package top, all four sides, seal, and completion control visible to the camera. If a required surface is outside the frame, the result must be sent for human review.