



螺母输送机

Nut Feeder

螺母输送机一般与焊接设备配套使用，为了提高生产效率和杜绝此类的安全隐患，用能快速准确的螺母输送机来代替人手方式装配则是一个很好的解决方案。只需将螺母输送机的接线简单的接入焊接控制器，工人只需进行一次操作即国产先进螺母输送机可完成把螺母送进定位销，然后焊接的工序。既快捷又安全，已经得到众多车厂的广泛使用。

This nut feeder system is used for nut supply to the welding equipment. In order to improve productivity and prevent security risks, it can conveyor the nuts quickly and accurately, which is a good solution for manual operate. Just wire nuts conveyor to the welding controllers, its working is fast and safe, which has been widely used in many of the automobile industry



电源输入 Power supply	AC220V, 50Hz / 60Hz Max 250 - 400VA
螺母类型 Nut shapes	四角，圆形，六角，T，菱形螺母 Square, round, Hexagon, T, dome, with cover, with rib, collar etc.
气源压力 Air pressure	0.25 - 0.4MPa
尺寸 Sizes	M4 - M12, 7/16
圆盘尺寸 Bowl size	φ260mm, φ350mm
漏斗容量 Hopper capacity	9L (M6螺母约1万个Approx. 10,000 pcs for M6 nut)
工作能力 Supply capacity	40 - 60pcs/min
传送管长度 Supply chute length	2m
角度 Angle	0° - 90°
设备重量 Weight	100kg