Annexes

Table 1. SIPOC diagram of sampling.

S	OC diagram o I	Р	0	С
Quality coordinator	AQL	Determine the acceptable quality level (AQL). Note: AQL is determined by:	AQL	Receiving Operator
		management, quality department and supplier agreements.		
Quality coordinator		Choose inspection level (Level I, II, II or special)		
	Inspection Level	Note: At the start of sampling, the inspection level is II, unless another level is indicated	Inspection Levels	Receiving Operator
Quality coordinator Supplier	Products to be received	Determine lot size	Products received	Receiving Operator
Quality coordinator	Products to be sampled	Go to the code table and find the inspection letter according to the level selected	Inspection letter	Receiving Operator
Quality coordinator	Products to be sampled	Set type of inspection (Normal, Severe or Reduced)	Type of inspection	Receiving Operator
Quality coordinator	Products to be sampled	Determine sample size and acceptance number according to the type of inspection	Quantity of products to be sampled	Receiving Operator
Operario de recepción	Products to be sampled	Select batch sample	Products sampled	Receiving Operator
Quality coordinator	Products to be evaluated Technical standards of the product	Evaluate the criteria according to the technical standards of the product.	Evaluated products	Receiving Operator

	Quality control procedure for vegetables and legumes	Note: Perform quality control procedure		
Quality coordinator	Products evaluated Technical quality standards	Accept or reject lot according to number o defective products	Accepted or rejected f products	Receiving Operator
Receiving Operator	Accepted and rejected products	Keep a batch acceptance and rejection record	Product acceptance/rejection record	Storage of merchandise

Table 2. SOP Summary.

Type	Description			
	Reception of vegetables and legumes			
	Acceptance sampling of bulk vegetables and legumes			
Procedure	Acceptance sampling of vegetables and legumes in pieces			
	Quality control of vegetables and legumes			
	Control and calibration of scales			
	Reception of vegetables and legumes			
	Acceptance sampling of bulk vegetables and legumes			
Instructions	Acceptance sampling of vegetables and legumes in units			
	Sorting of sampled products			
	Product handling			
	Transport GMP's			
	Product reception logbook			
	Sampling			
	Quality control			
Records	Batch acceptance and rejection			
Records	Follow-up of quality failures by the supplier			
	Goods issue and return of goods			
	Scale calibration and control			
	Quality control analysis			
	Of labels and sampled lots			
Schedule	Calibration of digital scales			
Scriedule	Calibration of industrial scales			
Poporto	Non-compliance with transport GMPs			
Reports	Quality failures			

Tabla 3. Socialization cost analysis.

Description of	Time (h)	Cost per	Number	Number of	Total cost
activity		meeting	of	participants	
•		J	meetings		
Presentation of the proposal	2	\$34,18	6	2	\$410,20
Meeting with management	3	\$76,60	4	1	\$306,40
Proposal approval / denial	1	\$25,53	1	1	\$25,53
Quality analyst training	2	\$10,55	6	3	\$189,84
Operator training	2	\$7,17	10	12	\$860,40
		Total			\$1382,17