


Your location
Kerteh, Terengganu
Add destination
Leave now
Options
Send directions to your phone
via E8
1 hr 34 min
Fastest route now due to traffic conditions
141 km
This route has tolls.
Details
Search near your destination
Gas
Hotels
Rest stops
More
Kuala Krai
Balah
Dabong
Permaisuri
Chalok
Sungai Tong
Marang
Kuala Berang
Kampong Limau kasturi
Kampung Paloh 3
Kampong Buai
Kampong Batu
Taman Negara
Bunga
Kampong Batu Kura
Kampung Pagi
Kuala Tahan
Paka
Kerteh
Kemasik
Chukai
1 hr 34 min
141 km

Sent: Friday, 13 May, 2022 1:56 AM
To: nazri.nasier@aimsglobal.com.my
Cc: {KPSB_Pilotage} <{KPSB_Pilotage}@petronas.com>; {KPSB_VTS} <{KPSB_VTS}@petronas.com>; HANIFA KAMAL <hanifa.kamal@aimsglobal.com.my>; Syamsuddin Muhamad (MARINE/KPSB) <syamsuddin.muhamad@petronas.com>
Subject: AFA1 CURRENT SUPPLY ISSUES

Salam Nazri

Would like to inform you that during the SBM operation of Dee4 Cedar, AFA1 encounter difficulty which was determined as no current supply to capstan lead to AFA1 not able to do the hose handling operation. Few attempts made to recover the current supply before AFA2 was called to replace her. Appreciate your assistance to rectify the issues and share with KPSB the findings/root cause. Do have the way forward to avoid any recurrence.

Thanks,
Asyraf


Kerteh, Terengganu
Your location
Add destination
Leave now
Options
Send directions to your phone
via E8
1 hr 30 min
Fastest route now due to traffic conditions
140 km
This route has tolls.
Details
Gas
Hotels
Rest stops
More
1 hr 30 min
140 km
1 hr 36 min
128 km
Kuala Krai
Permaisuri
Balah
Chalok
Dabong
Kampong Limau kasturi
Kampung Paloh 3
Kampong Buai
Kuala Berang
Kampong Batu
Bukit Besi
Kuala Dungun
Taman Negara
Paka
Bunga
Kampong Batu Kura
Kerteh
Kemasik
Kampung Pagi
Kuala Tahan