Date: 6/9/2022 Project: Estimate 5

Job# RS5032

Customer Name: PAUL SUSAN FREESE AND PRICCO

Sales Person: Nicole Acosta

Address: 17863 N. 99TH DR

SC, AZ 85373

## **Location: Garage- RV**

PERMITS:	
CITY PERMIT	1.00
CITY PERMIT BATHROOM	1.00
CITY PERMIT KITCHEN	1.00

**Sub Total:** 796.95

## Location: Kitchen- 1

MASONRY:	
BLOCK FENCE >> 6 FT BLOCK FENCE UNFINISHED  Item Added (Change Order 1, 6/9/2022)	1.00
BLOCK FENCE >> 6 FT FENCE STUCCO LACE FINISH  Item Added (Change Order 1, 6/9/2022)	0.00
BLOCK FENCE >> PILASTER BLOCK COLUMN AT GATE  Item Added (Change Order 1, 6/9/2022)	1.00
MANMADE STONE OR BRICK VENEER >> MANUFACTURED BRICK MATERIAL ONLY Item Added (Change Order 1, 6/9/2022)	50.00
MANMADE STONE OR BRICK VENEER >> MANUFACTURED STONE MATERIAL ONLY Item Added (Change Order 1, 6/9/2022)	50.00
MANMADE STONE OR BRICK VENEER >> LABOR ONLY Item Added (Change Order 1, 6/9/2022)	1.00
BLOCK WORK >> 4 X 8 SOLID BLOCK Item Added (Change Order 1, 6/9/2022)	1.00
BLOCK WORK >> BLOCK REPAIR Item Added (Change Order 1, 6/9/2022)	1.00
BLOCK WORK >> 8 X 16 BLOCK Item Added (Change Order 1, 6/9/2022)	1.00
BLOCK WORK >> BLOCK WALL 6' HIGH  Item Added (Change Order 1, 6/9/2022)	30.00
BRICK WORK >> BRICK COLUMN PER HEIGHT  Item Added (Change Order 1, 6/9/2022)	1.00
BRICK WORK >> BRICK REPAIR TOOTH IN  Item Added (Change Order 1, 6/9/2022)	1.00
BRICK WORK >> FACE BRICK Item Added (Change Order 1, 6/9/2022)	100.00
COLUMN >> 16 X 16 BLOCK COLUMN UP TO 4FT HIGH  Item Added (Change Order 1, 6/9/2022)	1.00
COLUMN >> 16 X 16 BLOCK COLUMN UP TO 8FT HIGH  Item Added (Change Order 1, 6/9/2022)	1.00
COLUMN >> 24 X 24 BLOCK COLUMN UP TO 8FT HIGH  Item Added (Change Order 1, 6/9/2022)	1.00

MANMADE STONE OR BRICK VENEER >> MANUFACTURED BRICK MATERIAL ONLY  Item Added (Change Order 1, 6/9/2022)	50.00
MANMADE STONE OR BRICK VENEER >> MANUFACTURED STONE MATERIAL ONLY Item Added (Change Order 1, 6/9/2022)	50.00

Sub Total: 14,961.00

## Location: Kitchen- 2

MASONRY:		
BRICK WORK >> BRICK COLUMN PER HEIGHT  Item Added (Change Order 1, 6/9/2022)	1.00	
BRICK WORK >> BRICK REPAIR TOOTH IN Item Added (Change Order 1, 6/9/2022)	1.00	
PAINTING / STAINING:		
ADDED NOTES: >> Caulk Around All Baseboards and Windows as Needed. (Where gaps exist)  Item Added (Change Order 1, 6/9/2022)	1.00	
ADDED NOTES: >> Fill All Holes And Cracks In The Walls, Texture Where Needed To Blend As Best As Possible But Patches May Be Visible After Painting.  Item Added (Change Order 1, 6/9/2022)	1.00	
ADDED NOTES: >> Remove All Loose And Peeling Paint and Prime All Bare Surfaces.  Item Added (Change Order 1, 6/9/2022)	1.00	
EXTERIOR PAINTING >> Paint Exterior Wall >> -Caulk around windows, doors and trim to seal out moisture and drafts. (Where gaps exist)  Item Added (Change Order 1, 6/9/2022)	1.00	
EXTERIOR PAINTING >> Paint Exterior Wall >> -Caulk around windows, doors and trim to seal out moisture and drafts. (Where gaps exist)  Item Added (Change Order 1, 6/9/2022)	1.00	

Sub Total: 1,670.92