Composite SOW by Section



11-8-21

Customer Name: SUSAN PRICE PATTERSON 2

Job Number: RS5024

Estimate Name: KITCHEN & DESK

Section: PROJECT	PREPARATION				
Location			Total Cost	Item Status	
Kitchen- 1	SITE PREPARATION >> DUST CONTROL >>		\$388.50		Need to order 18 SF of shower pan tile to repl
	Sub Total:		\$388.50		
Section: DEMOLITI	ON				
Location			Total Cost	Item Status	
Kitchen- 1	KITCHEN CABINETS OR COUNTER >>TEAR OUT		\$600.00		Save open book case at desk area and put int
Kitchen- 1	ELECTRICAL >> REMOVE LIGHT FIXTURE >>		\$18.50		
Kitchen- 1	ELECTRICAL >>ALARM SYSTEM PANEL		\$25.00		
	Sub Total:		\$643.50		
Section: INTERIOR	MISC FRAMING				
Location			Total Cost	Item Status	
Closet- Master	Closet Shelving Labor and Material		\$250.00	Item Added	
				(Closet Shelving,	
				11/30/2021)	
Sub To			\$250.00		
Section: ELECTRIC	CAL				
Location			Total Cost	Item Status	
Kitchen- 1	OUTLETS >> GFCI OUTLET >>		\$222.83		
Kitchen- 1	OUTLETS >> WALL OUTLET >>		\$1,070.58		
Kitchen- 1	OUTLETS >> WALL OUTLET >>		\$535.29		
Kitchen- 1	APPLIANCES >>SINGLE OVEN 220		\$675.00		
Kitchen- 1	APPLIANCES >> COOKTOP CIRCUIT >>		\$555.00		

Kitchen- 1	LIGHTING >> LED >> RECESSED LED LIGHT >>		\$547.95		
Kitchen- 1	LIGHTING >> LED >> LED STRIP LIGHT >>		\$442.45		
Kitchen- 1	OUTLETS >> WALL OUTLET >>		\$178.43		
Kitchen- 1	EVALUATION >> SMALL SITE EVALUATION >>				
		Sub Total:	\$4,458.78		
Section: WALL &	CEILING DRYWALL				
Location			Total Cost	Item Status	
Kitchen- 1	PATCH WORK >> SMALL DRYWALL PATCH >>		\$468.00		
		Sub Total:	\$468.00		
Section: CABINET	TRY				
Location			Total Cost	Item Status	
Kitchen- 1	CUSTOM CABINETS		\$33,825.00		Save towel clothes pin and marble thing. Hard
		Sub Total:	\$33,825.00		
Section: COUNTE	R TOP				
Location			Total Cost	Item Status	
Kitchen- 1	SLAB FABRICATION >>COUNTER TOPS		\$12,600.00		Has slabs reserved at AZ Tile. White Ice Grar
		Sub Total:	\$12,600.00		
Section: CLEAN U	JP				
Location			Total Cost	Item Status	
Kitchen- 1	30 YD DUMPSTER >>		\$897.25		
Kitchen- 1	BROOM CLEAN SITE >>		\$122.10		
Kitchen- 1	NOTE: Place OSB sheeting under dumpster to protect driveway >>		\$129.50		
		Sub Total:	\$1,148.85		
Section: PAINTING	G / STAINING				
Location			Total Cost	Item Status	
Kitchen- 1	INTERIOR PAINTING >>AT 2 DRYWALL PATCHES		\$240.00		Paint touch up -
		Sub Total:	\$240.00		
Section: PLUMBIN	NG				
Location			Total Cost	Item Status	
r					

Kitchen- 1	KITCHEN PLUMBING >> SINK: >> LABOR ONLY INSTALL SINK TO EXISTING LOCATION, NEW P TRAP AND ANGLE STOPS INCLUDED >>		\$410.05		
Kitchen- 1	KITCHEN PLUMBING >> FAUCET >> LABOR ONLY FAUCET IN COUNTER TOP >>		\$87.75		HO providing new faucet and soap dish. Ray t
		Sub Total:	\$497.80		
Section: SUN CIT	Ύ				
Location			Total Cost	Item Status	
Kitchen- 1	MISC		\$430.89		Repair floor in sun room as well.
Kitchen- 1	DISCOUNT		\$-1.32	' '	HO getting new appliances. Trash appliances
		Sub Total:	\$429.57		
		Grand Total:	\$54,950.00		