Composite SOW by Location



Customer Name: PAUL SUSAN FREESE AND PRICCO

Job Number: RS5032 (06/15/2022)

Estimate Name: Estimate 5

Locatio	n:Garag	e- RV
---------	---------	-------

SL	Section Name	Item Name	Short Note	Item Status	Checklist Note
26000.00	PERMITS	CITY PERMIT >>			
26000.00	PERMITS	CITY PERMIT BATHROOM >>			
26000.00	PERMITS	CITY PERMIT KITCHEN >>			

Location:Kitchen- 1

SL	Section Name	Item Name	Short Note	Item Status Checklist Note
19000.00	MASONRY	BLOCK FENCE >> 6 FT BLOCK FENCE UNFINISHED >>		Item Added (Change Order 1, 6/9/2022)
19000.00	MASONRY	BLOCK FENCE >> 6 FT FENCE STUCCO LACE FINISH >>		Item Added (Change Order 1, 6/9/2022)
19000.00	MASONRY	BLOCK FENCE >> PILASTER BLOCK COLUMN AT GATE >>		Item Added (Change Order 1, 6/9/2022)
19000.00	MASONRY	MANMADE STONE OR BRICK VENEER >> MANUFACTURED BRICK MATERIAL ONLY >>		ltem Added (Change Order 1, 6/9/2022)
19000.00	MASONRY	MANMADE STONE OR BRICK VENEER >> MANUFACTURED STONE MATERIAL ONLY >>		Item Added (Change Order 1, 6/9/2022)
19000.00	MASONRY	MANMADE STONE OR BRICK VENEER >> LABOR ONLY >>		Item Added (Change Order 1, 6/9/2022)
19000.00	MASONRY	BLOCK WORK >> 4 X 8 SOLID BLOCK >>		Item Added (Change Order 1, 6/9/2022)

19000.00 MASONRY	MANMADE STONE OR BRICK VENEER >> MANUFACTURED STONE MATERIAL ONLY >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	MANMADE STONE OR BRICK VENEER >> MANUFACTURED BRICK MATERIAL ONLY >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	COLUMN >> 24 X 24 BLOCK COLUMN UP TO 8FT HIGH >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	COLUMN >> 16 X 16 BLOCK COLUMN UP TO 8FT HIGH >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	COLUMN >> 16 X 16 BLOCK COLUMN UP TO 4FT HIGH >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	BRICK WORK >> FACE BRICK >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	BRICK WORK >> BRICK REPAIR TOOTH IN >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	BRICK WORK >> BRICK COLUMN PER HEIGHT >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	BLOCK WORK >> BLOCK WALL 6' HIGH >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	BLOCK WORK >> 8 X 16 BLOCK >>	Item Added (Change Order 1, 6/9/2022)
19000.00 MASONRY	BLOCK WORK >> BLOCK REPAIR >>	Item Added (Change Order 1, 6/9/2022)

Location:Kitchen- 2

SL	Section Name	Item Name	Short Note	Item Status Checklist Note
19000.00	MASONRY	BRICK WORK >> BRICK COLUMN PER HEIGHT >>		Item Added (Change Order 1, 6/9/2022)
19000.00	MASONRY	BRICK WORK >> BRICK REPAIR TOOTH IN >>		Item Added (Change Order 1, 6/9/2022)

45000.00	PAINTING / STAINING	ADDED NOTES: >> Caulk Around All Baseboards and Windows as Needed. (Where gaps exist) >>	Item Added (Change Order 1, 6/9/2022)
45000.00	PAINTING / STAINING	ADDED NOTES: >> Fill All Holes And Cracks In The Walls, Texture Where Needed To Blend As Best As Possible But Patches May Be Visible After Painting. >>	Item Added (Change Order 1, 6/9/2022)
45000.00	PAINTING / STAINING	ADDED NOTES: >> Remove All Loose And Peeling Paint and Prime All Bare Surfaces. >>	Item Added (Change Order 1, 6/9/2022)
45000.00	PAINTING / STAINING	EXTERIOR PAINTING >> Paint Exterior Wall >> -Caulk around windows, doors and trim to seal out moisture and drafts. (Where gaps exist) >>	Item Added (Change Order 1, 6/9/2022)
45000.00	PAINTING / STAINING	EXTERIOR PAINTING >> Paint Exterior Wall >> -Caulk around windows, doors and trim to seal out moisture and drafts. (Where gaps exist) >>	Item Added (Change Order 1, 6/9/2022)