

Date: 2018-12-10

Report Number: 60.790.18.058.01

Model No.: 165-00645





Page 1 of 6 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-12-10

Report Number: 60.790.18.058.01





Page 2 of 6 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-12-10

Report Number: 60.790.18.058.01








Date: 2018-12-10

Report Number: 60.790.18.058.01






Page 4 of 6 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong



Date: 2018-12-10

Report Number: 60.790.18.058.01








Date: 2018-12-10

Report Number: 60.790.18.058.01

Model No.: 165-00645



(According to the Schematics, the antenna type is cooper rod antenna)

Page 6 of 5 TÜV SÜD Hong Kong Ltd. 3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong