
5150MHz~5250MHz, 5725MHz~5850MHz


802.11a

5180MHz




Date: 6 AUG 2018 14:23:20

5200MHz




Date: 6 AUG 2018 14:29:52




Date: 6.AUG 2018 14:35:20

5745MHz




Date: 6 AUG 2018 14:57:43



Date: 6.AUG 2018 15:03:05


5825MHz



Date: 6 AUG 2018 15:07:31


802.11n-HT20

5180MHz




Date: 6.AUG 2018 15:13:12

5200MHz




Date: 6 AUG 2018 15:18:56



Date: 6.AUG 2018 15:24:04

5745MHz




Date: 6 AUG 2018 15:29:06



Date: 6.AUG 2018 15:35:18

5825MHz



Date: 6 AUG 2018 15:40:26


802.11n-HT40

5190MHz




Date: 6.AUG 2018 15:46:33

5230MHz




Date: 6 AUG 2018 15:52:14



Date: 6.AUG 2018 15:57:55


5795MHz



Date: 6 AUG 2018 16:03:00


802.11ac-HT20

5180MHz




Date: 6.AUG 2018 16:09:50

5200MHz




Date: 6 AUG 2018 16:16:46




Date: 6.AUG 2018 16:22:54

5745MHz




Date: 6 AUG 2018 16:28:04



Date: 6.AUG .2018 16:32:42


5825MHz



Date: 6 AUG 2018 16:37:15


802.11ac-HT40

5190MHz




Date: 6 AUG 2018 16:46:37

5230MHz




Date: 6 AUG 2018 16:51:55



Date: 6.AUG 2018 16:57:20


5795MHz



Date: 6 AUG 2018 17:02:45


802.11ac-HT80

5210MHz



Date: 6.AUG 2018 17:08:28

5775MHz



Date: 6 AUG 2018 17:19:00