Correspondence by Project

Project Number:

949271167

Correspondence Number	Memo
2AA30FFR-01-1	1) Please provide a certification contract. Response: The Certification Contract has been uploaded. 2) The TCB submittal attestation has an incorrect FCC ID listed. Please provide a corrected letter. Response: The TCB submittal attestation has been revised and uploaded. 3) Please provide test setup photos. Response: The test setup photos have been uploaded. 4) The operational description describes an operation that is not permitted by the rules. Please provide a description that complies with the rules. Response: The Operational Description has been revised and uploaded. 5) The user manual provides guidance on using shielded cables, however the devices has no cables. Please provide a corrected user manual. Response: The revised owners manual has been uploaded. 6) The modification letter does not list the resistor that was changed. Please provide a corrected letter. Response: The modification letter has been revised.

1 of 1 9/25/2013 6:10 PM