

October 11 2013

TUV SUD BABT TCB Octagon House, Segensworth Road, Fareham, Hampshire, PO15 5RL

Dear Sir or Madam,

We, Octane Fitness, 7601 Northland Drive, Suite 100, Brooklyn Park, MN 55428, are requesting Limited Modular Approval (LMA) on the BTLE/ANT+ Radio Module Model 108581-001 and hereby declare that the BTLE/ANT+ Radio Module Model 108581-001 will only be integrated into Octane Fitness products. Therefore, Octane Fitness will retain full control of final installation.

Octane Fitness is the integrator of this module and the following regulatory notices will be included in the end product manuals.

Industry Canada Notices

"This device complies with Industry Canada licence-exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause interference, and (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes : (1) l'appareil ne doit pas produire de brouillage, et (2) l'utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement."

FCC Notices

"This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation."

"Note: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- —Reorient or relocate the receiving antenna.
- —Increase the separation between the equipment and receiver.
- —Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- —Consult the dealer or an experienced radio/TV technician for help."



"Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment"

Host device labelling requirement notice:-

"To meet the FCC and Industry Canada host device labelling requirements, any host equipment incorporating your module must include the FCC ID/IC number on the host label as follows:

"Contains transmitter module IC: 11442A-108581A" where 11442A-108581A is the module's IC certification number.

"Contains transmitter module FCC ID: 2AA4O-108581A" where 2AA4O-108581A is the module's FCC ID number.

Sincerely

Company Officer:

Aaron Ellingson

Telephone Number:

763-230-3064

Email:

aellingson@octanefitness.com