



Report No. : FR531929

Appendix A. Test Photos

Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A4

Report Version


: Rev. 01






Report No. : FR531929

Radiated below 1GHz Test



Radiated below 1GHz Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A4

Report Version


: Rev. 01






Report No. : FR531929

Radiated above 1GHz Test



Radiated above 1GHz Test




SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A4

Report Version : Rev. 01



FCC Test Report No.: FR531929



SPORTON INTERNATIONAL INC. Page No. : A4 of A4 TEL: 886-3-3273456 Report Version : Rev. 01

FAX: 886-3-3270973