





**Appendix A. Test Photos** 





**Conducted Test** 



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A5

Report Version


: Rev. 01


Report No. : FR531903





Report No. : FR531903





SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A5

Report Version : Rev. 01



**Radiated below 1GHz Test** 

**Report No. : FR531903** 




SPORTON INTERNATIONAL INC. Page No. : A3 of A5 TEL: 886-3-3273456 Report Version : Rev. 01


FAX: 886-3-3270973





**Report No. : FR531903** 





SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A4 of A5

Report Version : Rev. 01



Radiated above 1GHz Test

**Report No. : FR531903** 

SPORTON INTERNATIONAL INC. Page No. : A5 of A5 TEL: 886-3-3273456 Report Version : Rev. 01

FAX: 886-3-3270973