


## **Appendix A. Test Photos**

## **Conducted Test**



**Conducted Test** 



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A4

Report Version

: Rev. 01


Report No. : FR540106






Report No. : FR540106

## **Radiated below 1GHz Test**



**Radiated below 1GHz Test** 



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A4


Report Version : Rev. 01






Report No. : FR540106

## **Radiated above 1GHz Test**



**Radiated above 1GHz Test** 



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A4

Report Version

: Rev. 01



Radiated above 1GHz Test

**Report No. : FR540106** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A4 TEL: 886-3-3273456 Report Version : Rev. 01

FAX: 886-3-3270973