



Appendix A. Test Photos

Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A4

Report No. : FR493012


Report Version : Rev. 01






Report No. : FR493012





Radiated below 1GHz Test



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A4
Report Version : Rev. 01






Report No. : FR493012

Radiated above 1GHz Test



Radiated above 1GHz Test




SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A4

Report Version : Rev. 01



FCC Test Report **Report No. : FR493012**



SPORTON INTERNATIONAL INC. TEL: 886-3-3273456

FAX: 886-3-3270973

Page No. : A4 of A4 : Rev. 01

Report Version