



**Appendix A. Test Photos** 

## **Conducted Test**



**Conducted Test** 



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A4

Report No. : FR493015


Report Version : Rev. 01






**Report No. : FR493015** 





**Radiated below 1GHz Test** 



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A4


Report Version : Rev. 01






Report No. : FR493015

## **Radiated above 1GHz Test**



**Radiated above 1GHz Test** 



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A4

Report Version

: Rev. 01



FCC Test Report No.: FR493015



SPORTON INTERNATIONAL INC.
TEL: 886-3-3273456

FAX: 886-3-3270973

Page No. : A4 of A4
Report Version : Rev. 01