



Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 **Report No. : FR920112**



FCC Test Report No.: FR920112



Under table view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973




FCC Test Report

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Report No.: FR920112




FCC Test Report

Report No. : FR920112

For radiated emissions 30MHz~1GHz



Front view



Rear view

-----THE END------