


Report No.: FR891729AW

Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973



FCC Test Report No.: FR891729AW



Under table view


TEL: 886-3-327-3456 FAX: 886-3-327-0973



FCC Test Report

Report No.: FR891729AW

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973




FCC Test Report

Report No. : FR891729AW

For radiated emissions 30MHz~1GHz



Front view



Rear view

——THE END——